

J & L Hazardous Waste Manifests

Page Intentionally Left Blank

PLEASE TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11507

REFERENCE 80
Page 3

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
OR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, N.O.S.	ORM-E	NA9189				X	3333	X				1	Rel	F006
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>John M. Bryant</i>	Waste Waste Officer	6/28/01	6/28/01
TRANSPORTER	STATE	NUMBER	RECEIPT OF SHIPMENT
DWT No. 129	IN	21904K	<i>John M. Bryant</i>
			DATE RECEIVED
			6/28/01

Jones & Laughlin Steel Corporation / an LTV company

PLEASE TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11508

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
OR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, N.O.S.	ORM-E	NA9189				X	3770	X				1	Rel	F006
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 4

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA W. T.
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	09+H	NA9189				X	3333	X				1	ROL	
Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert G. Leslie	TITLE Waste Management Supervisor	DATE TO BE SHIPPED MONTH 02 YEAR 82	EXPECTED ARRIVAL DATE MONTH 02 YEAR 82
Transporter HWT ID No. 126	STATE IN	NUMBER 126	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT Robert G. Leslie
		DATE RECEIVED MONTH 02 YEAR 82	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

115

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WAS TYP	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	09+H	NA9189				X	3710	X				1	ROL	T	FOC
Central Waste Treatment Plant Sludge	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 11567

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J & L STEEL CORP.	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2031	IND005462601
INDUSTRIAL DISPOSAL CORP.	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2464	IND041250501
TRANSPORTER NO. 1 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
GARY LAND DEVELOPMENT P.O. BOX 6056 GARY, IN 46406 219-944-7858 IND 077005916			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189				X	5770	X				1 ROLL		FOOL
2. CENTRAL WASTE TREATMENT PLANT	(12)													
3. SLUDGE														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George P. ...</i>	TITLE Waste Waste Oper	DATE TO BE SHIPPED MONTH 7 DAY 13 YEAR 2	EXPECTED ARRIVAL DATE MONTH 7 DAY 13 YEAR 2
TRANSPORTER HWT ID No. 129	STATE IN	NUMBER 2210 AR	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John ...</i>
		DATE RECEIVED MONTH 7 DAY 13 YEAR 2	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 11561

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J & L STEEL CORP.	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2031	IND005462601
INDUSTRIAL DISPOSAL CORP.	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2464	IND041250501
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
GARY LAND DEVELOPMENT P.O. BOX 6056 GARY, IN 46406 219-944-7858 IND 077005916			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189				X	3333	X				1 ROLL		FOOL
2. CENTRAL WASTE TREATMENT PLANT	(12)													
4. SLUDGE														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>...</i>	TITLE ...	DATE TO BE SHIPPED ...	EXPECTED ARRIVAL DATE ...
-------------------------------------	--------------	---------------------------	------------------------------

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306-111

REFERENCE 80
Page 6

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J & L STEEL CORP	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2531	IND0005-21
TRANSPORTER NO. 1 INDUSTRIAL DISPOSAL CORP.	P.O. BOX 59 EAST CHICAGO, IN 46312	219-391-2106	IND 0442500
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY GARY LAND DEVELOPMENT	P.O. BOX 6056 GARY IN 46406	219-944-7258	IND 0770055

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WA T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189					X 3333	X			1	R/L T	FL	
2. CENTRAL WASTE TREATMENT PLANT (SLUDGE)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James M. Bryant</i>	TITLE Waste Water Oper	DATE TO BE SHIPPED MONTH 7 DAY 4 YEAR 82	EXPECTED ARRIVAL DATE MONTH 7 DAY 4
TRANSPORTER HWT ID No. 174 IN 46407	STATE IN	NUMBER 46407	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James M. Bryant</i>
			DATE RECEIVED MONTH 7 DAY 4

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306-111

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J & L STEEL CORP	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2531	IND0005-4626
TRANSPORTER NO. 1 INDUSTRIAL DISPOSAL CORP.	P.O. BOX 59 EAST CHICAGO, IN 46312	219-391-2106	IND 0442500
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY GARY LAND DEVELOPMENT	P.O. BOX 6056 GARY IN 46406	219-944-7258	IND 077-55

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WA T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189					X 3770	X			1	R/L T	FL	
2. CENTRAL WASTE TREATMENT PLANT (SLUDGE)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11578

REFERENCE 80
Page 7

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	JLL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3332	X				1 RoL	T	F006
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Leonard Pinner</i>	TITLE <i>Waste Mgr. Control</i>	DATE TO BE SHIPPED MONTH 7 DAY 6 YEAR 87	EXPECTED ARRIVAL DATE MONTH 7 DAY 8 YEAR 87
Transporter ID No. 13456789	STATE IN	NUMBER 123456789	DATE RECEIVED MONTH 7 DAY 6 YEAR 87

Jones & Laughlin Steel Corporation / and its company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11577

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	JLL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3772	X				1 RoL	T	F006
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 8

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND000060
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X		X					T
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert A. Lash...	TITLE ...	DATE TO BE SHIPPED MONTH DAY YEAR 7 8 88	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7 8 88
Transporter HWT ID No. 138 TM 972712	STATE IN	NUMBER 972712	RECEIPT OF SHIPMENT DATE RECEIVED MONTH DAY YEAR 7 8 88

Jones & Laughlin Steel Corporation / an L.P.C. of Indiana

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306-11

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L STEEL CORP	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2531	IND000060
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189				X	3,333	X				1	Roll
2. (CENTRAL WASTE TREATMENT PLANT)	(12)												
3. SLUDGE													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE ...	TITLE ...	DATE TO BE SHIPPED MONTH DAY YEAR 7 8 88	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7 8 88
------------------------------	--------------	--	---

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 9

3	PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3,770	3			1	ROL	P006
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>Shirley M. ...</i>	WASTE WATER OPERATOR	6-12-82	6-12-82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	MONTH	DAY
<i>Handwritten Signature</i>	6	12	82

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1148

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

3	PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3,770	3			1	ROL	P006
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 10

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, N.O.S.	09H-E	NA9189				X	2270	X				1 ROL	T	P006
Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>George P. ...</i>	<i>Unit ...</i>	MONTH DAY YEAR	MONTH DAY YEAR
Transporter	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
HWT	124	121	<i>Michael ...</i>
ID No.	124	121	DATE RECEIVED
			MONTH DAY YEAR
			6 19 92

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11484

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, N.O.S.	09H-E	NA9189				X	2233	X				1 ROL	T	P006
Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306
PHONE NO. 11481

EPA I.D. NO. 11481

3 PART A		EPA I.D. NO. 11481	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X		X					T	F006
(Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James R. Wright</i>	TITLE <i>Manager</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>6 14 82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>6 14 82</i>
TRANSPORTER SIGNATURE <i>Richard R. Smith</i>	TRANSPORTER TITLE <i>Manager</i>	DATE RECEIVED MONTH DAY YEAR <i>6 14 82</i>	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11481

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
JSL Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3270					1	R	F006
(Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
-----------------------	-------	--------------------------------------	---

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 12

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd. East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	E W/ T	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189					3333				1	Rel	T	FO
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John R. Wright</i>	TITLE Waste Value Over	DATE TO BE SHIPPED MONTH 6 DAY 15 YEAR 1982	EXPECTED ARRIVAL DATE MONTH 6 DAY 15 YEAR 1982
Transporter HWT ID No. 129 IN 29042	STATE IN	NUMBER 29042	DATE RECEIVED MONTH 6 DAY 15 YEAR 1982

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd. East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	E W/ T	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste solid n.o.s.	ORM-E	NA9189												
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen. - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 11504
REFERENCE 801151

Page 13

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JAL Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	B.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3333	X			1	RoL	F00
Central Waste Treatment Plant Sludge	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James D. Bryant</i>	TITLE <i>Waste Mgmt. Officer</i>	DATE TO BE SHIPPED MONTH 6 DAY 24 YEAR 82	EXPECTED ARRIVAL DATE MONTH 6 DAY 24 YEAR 82
Transporter HWI ID No. 11111111111111111111	STATE IN	NUMBER 11111111111111111111	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
		DATE RECEIVED MONTH 6 DAY 24 YEAR 82	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen. - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 11504

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JAL Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3770	X			1	RoL	F006
Central Waste Treatment Plant Sludge	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 14

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	W T	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, h.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3333	X				1	Rel	T	1
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James H. Bryant</i>	TITLE Waste Manager	DATE TO BE SHIPPED MONTH DAY YEAR 6/26/82	EXPECTED ARRIVAL DAY MONTH DAY 6/26/82
TRANSPORTER HWT ID No. 124	STATE IN	NUMBER 240012	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowach</i>
			DATE RECEIVED MONTH DAY 6/26/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

111

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	W T	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, h.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770	X				1	Rel	T	1
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7308

REFERENCE 80
Page 15

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
TREATMENT, STORAGE OR DISPOSAL FACILITY	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
Gary Land Development	P.O. Box 6056	Gary, IN 46406	219-544-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WAS TYP
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		373.3	X				1	ROL	FO
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
George Pinner	Waste Water Operator	MONTH DAY YEAR	MONTH DAY YEAR
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
Michael J. Pinner	MONTH DAY YEAR		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0889

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
TREATMENT, STORAGE OR DISPOSAL FACILITY	NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
Gary Land Development	P.O. Box 6056	Gary, IN 46406	219-544-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WAS TYP
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3770	X				1	ROL	FO
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: I certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED MONTH DAY YEAR EXPECTED ARRIVAL DATE MONTH DAY YEAR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 16

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425051
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	3,770	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH DAY YEAR 2 21 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2 21 82
TRANSPORTER SIGNATURE <i>[Signature]</i>	TITLE Hazardous Waste Operator	DATE RECEIVED MONTH DAY YEAR 2 21 82	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

08896

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	3,333	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Water Operator	DATE TO BE SHIPPED MONTH DAY YEAR 2 21 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2 21 82
---	-------------------------------	---	--

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 17

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	031-E	NA9189				X	3770	X				1	RoL	T	PO06
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE R. Roberts	TITLE Waste transporter	DATE TO BE SHIPPED MONTH 2 DAY 23 YEAR 82	EXPECTED ARRIVAL DATE MONTH 2 DAY 23 YEAR 82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT John R. Smith	DATE RECEIVED MONTH 2 DAY 23 YEAR 82		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1115

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	031-E	NA9189				X	3,333	X				1	RoL	T	PO06
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	--------------------	-----------------------

lease TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 18

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,776					1 Ro	T	P006
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	20 82	2 20 82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	STATE	NUMBER	DATE RECEIVED
<i>[Signature]</i>	IN	126	2 20 82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08956

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333					1 Ro	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

1147

REFERENCE 80

Page 19

PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3770	X				1	ROU	F006
Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James R. Wright</i>	TITLE Waste Waste Operator	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No. 184	STATE IN	NUMBER 22932	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION ON RECEIPT OF SHIPMENT <i>Richard R. Bush</i>
			DATE RECEIVED MONTH DAY YEAR 6 10 82

Jones & Laughlin Steel Corporation / and TV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

1147

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3333	X				1	ROU	F006
Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE

TITLE

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 20

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO.	TYPE	EPA HAZ CODE	W
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				ROL		
2. Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE J. W. ...	TITLE ...	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
TRANSPORTER HWT ID No. 1241	STATE IN	NUMBER ...	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT ...
		DATE RECEIVED MONTH DAY YEAR	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

114

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO.	TYPE	EPA HAZ CODE	EF WA TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				ROL		
2. Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	YEAR	MONTH	DAY	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	------	-------	-----	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 21

3 PART A

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044280587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-344-7858	IND077005916
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>			

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	333.3	X				1	ROL		PO
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: George Purney TITLE: Waste Water Operator DATE TO BE SHIPPED: MONTH 5 DAY 3 YEAR 82 EXPECTED ARRIVAL DATE: MONTH 5 DAY 3 YEAR 82

TRANSPORTER: STATE IN NUMBER 13417W-28930 TRANSPORTER NO. 1 SIGNATURE AND CAPTION OF RECEIPT OF SHIPMENT: Michael J. Purney DATE RECEIVED: MONTH 5 DAY 3 YEAR 82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0889

3 PART A

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044280587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-344-7858	IND077005916
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>			

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	ROL		PO
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: George Purney TITLE: Waste Water Operator DATE TO BE SHIPPED: MONTH 5 DAY 3 YEAR 82 EXPECTED ARRIVAL DATE: MONTH 5 DAY 3 YEAR 82

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 22

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425051
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	091-E	NA9189				X	3,770	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER Operator	DATE TO BE SHIPPED MONTH DAY YEAR 2 21 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2 21 82
TRANSPORTER HWT ID NO. 12417126721	STATE NUMBER IN 01	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT ON SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 2 21 82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08896

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	091-E	NA9189				X	3,333	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
---	-------	--------------------------------------	---

Please TYPE or PRINT clearly, using
point pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7396

0889

REFERENCE 80
Page 23

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	JAL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7856	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3720	X				1	REL	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>[Signature]</i>	<i>Unit Water Separator</i>	2 6 82	2 6 82
Transporter HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
124	IN	2399A	<i>[Signature]</i>

Jones & Laughlin Steel Corporation / an LTV company

PE or PRINT clearly, using
point pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7396

08900

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	JAL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7856	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	REL	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 24

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS					
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	374	X					1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)																
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George Pinner</i>	TITLE <i>VP Operations</i>	DATE TO BE SHIPPED MONTH <i>2</i> DAY <i>9</i> YEAR <i>82</i>	EXPECTED ARRIVAL DATE MONTH <i>2</i> DAY <i>9</i> YEAR <i>82</i>
TRANSPORTER HWT ID No. <i>129</i>	STATE <i>IN</i>	NUMBER <i>2404R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John R...</i>
			DATE RECEIVED MONTH <i>2</i> DAY <i>9</i> YEAR <i>82</i>

Jones & Laughlin Steel Corporation / and its company

Please TYPE or PRINT clearly, using a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

089

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442507
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS					
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X					1	Rel	T	00
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 25

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312 2	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	Ro/T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *Gen'l Mgr* DATE TO BE SHIPPED: *6/25/82* EXPECTED ARRIVAL DATE: *7/25/82*

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: *6/25/82*

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11159

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3865	X				1	Ro/T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *[Blank]* DATE TO BE SHIPPED: *[Blank]* EXPECTED ARRIVAL DATE: *[Blank]*

Please TYPE or PRINT clearly, using a ballpoint pen. PRESS HARD.

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 26

NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
GENERATOR JAL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2511	IND05462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7558	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE.

This Form is No.

Out Of A Total Of

The First Manifest Document No. is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-C	NA9135					X 3770	X				1	Ro/	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Water Oper	DATE TO BE SHIPPED MONTH DAY YEAR 2/27/82	RECEIVED BY <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 2/27/82
Transporter HWT ID No. 129	STATE IN	NUMBER 24042	TRANSPORTER NO. SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 2/27/82

Please TYPE or PRINT clearly, using
allpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 27

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425056
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George P. ...</i>	TITLE Waste Water Operator	DATE TO BE SHIPPED MONTH 3 DAY 3 YEAR 82	EXPECTED ARRIVAL DATE MONTH 3 DAY 3 YEAR 82
Transporter HWT ID No. 12414	STATE IN	NUMBER 2892A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Thomas ...</i>
			DATE RECEIVED MONTH 3 DAY 3 YEAR 82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1116

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 28

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.c.s.s.	ORM-E	NA9189				X	3,333	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 3 DAY 1 YEAR 82	EXPECTED ARRIVAL DATE MONTH 3 DAY 1 YEAR 82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 3 DAY 1 YEAR 82		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1116

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.c.s.s.	ORM-E	NA9189				X	3,370	X				1	ROL	T	06
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 29

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425057
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EF WA TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid, h.o.s.	ORM-E	NA9189			X		3333	X			1	Ro	T	FC
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>Waste Manager</i>	3/7/22	3/7/22
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
<i>[Signature]</i>	3/7/22		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

088

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EF WA TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid, h.o.s.	ORM-E	NA9189			X		2770	X			1	Ro	T	FC
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 30

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	Roll		P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John E. Pomeroy</i>	TITLE Waste Operator	DATE TO BE SHIPPED MONTH 3 DAY 5 YEAR 82	EXPECTED ARRIVAL DATE MONTH 3 DAY 5 YEAR 82
Transporter HWT ID No. 124 IN 9793 R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>	DATE RECEIVED MONTH 3 DAY 5 YEAR 82	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1116

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	Roll		P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306

REFERENCE 80

Page 31

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3233	X			1	Ro	T	F006
Central Waste Treatment Plant Sludge	(12)													
3.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Central Waste Corp	DATE TO BE SHIPPED MONTH DAY YEAR 3/12/82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3/12/82
Transporter HWT ID No. 129	STATE IN	NUMBER 29022	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH DAY YEAR 3/12/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 111

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EP WAS TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X			1	Ro	T	F00
Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 32

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X		X					T	P006
2. (Central Waste Treatment Plant Sludge)	(12)						3333					1 Ro		
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No. 129 2K 2904 R	STATE NUMBER IN 129 2K 2904 R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT V. R. O. P. K. 3/10/82	DATE RECEIVED MONTH DAY YEAR 3/10/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08815

3 PART A		DOCUMENT NO. 7306 - 08815	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1 Ro	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
-----------------------	-------	--------------------------------------	---

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 33

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYP	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, h.c.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	333	X				1	ROL	T	FOO
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John J. Penney</i>	TITLE <i>Plant Manager</i>	DATE TO BE SHIPPED MONTH <i>3</i> DAY <i>16</i> YEAR <i>82</i>	EXPECTED ARRIVAL DATE MONTH <i>3</i> DAY <i>16</i> YEAR <i>82</i>
Transporter HWT ID No. <i>124</i> <i>12</i> <i>28935</i>	STATE <i>IN</i>	NUMBER <i>124</i> <i>12</i> <i>28935</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Brack</i>
DATE RECEIVED MONTH <i>3</i> DAY <i>16</i> YEAR <i>82</i>			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

112

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 6056 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYP	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, h.c.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770	X				1	ROL	T	FOO
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11211
REFERENCE 80211

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. PORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	Net	T	P006
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James R. Wampler</i>	TITLE 1741	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No. <i>BZ</i>	STATE <i>IN</i>	NUMBER <i>2905A</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. R...</i>
DATE RECEIVED MONTH DAY YEAR			<i>5 14 82</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11211

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3775	X				1	Net	T	P006
(Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 35

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd. East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				x	3333	x				1 Rol	T	FOG
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Richard P. Roach</i>	TITLE Manager	DATE TO BE SHIPPED MONTH DAY YEAR 7 20 77	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7 20 77
TRANSPORTER HWT ID No. 124	STATE IN	NUMBER 2993A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard P. Roach</i>
			DATE RECEIVED MONTH DAY YEAR 7 20 77

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1124

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				x	3770	x				1 Rol	T	FOG
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1121

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3533	X				1	ROL	T	P006
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O Leslie	TITLE Master Mateo	DATE TO BE SHIPPED MONTH 3 DAY 18 YEAR 82	EXPECTED ARRIVAL DATE MONTH 3 DAY 18 YEAR 82
Transporter ID No. 124774	STATE IN	NUMBER 2075	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT Michael Beach
		DATE RECEIVED MONTH 3 DAY 18 YEAR 82	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1121

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	ROL	T	P006
(Central Waste Treatment Plant Sludge)	(12)														
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O Leslie	TITLE Master Mateo	DATE TO BE SHIPPED MONTH 3 DAY 18 YEAR 82	EXPECTED ARRIVAL DATE MONTH 3 DAY 18 YEAR 82
Transporter ID No. 124774	STATE IN	NUMBER 2075	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT Michael Beach
		DATE RECEIVED MONTH 3 DAY 18 YEAR 82	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 37

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Rd. East Chicago, IN 46312 P.O. Box 59	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				x	3338	x				1	Rob	T	P006
2. Central Waste Treatment Plant Sludge	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Walter Winkler</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 3 DAY 27 YEAR 82	EXPECTED ARRIVAL DATE MONTH 3 DAY 27 YEAR 82
TRANSPORTER LWT ID No. 124 1/14 2 8 9 5 8	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Beach</i>	DATE RECEIVED MONTH 3 DAY 27 YEAR 82	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1125

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312 P.O. Box 59	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				x	3,770	x				1	Rob	T	P006
2. Central Waste Treatment Plant Sludge	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7286
EPA I.D. NO. 1125

3 PART A

Page 38

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, Ind 46312 P.O. Box 59	219-391-2531	TND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	East Chicago, IN 46312	219-397-2664	TND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, TN 46406	219-944-7858	TND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189					3333					1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE managing director	DATE TO BE SHIPPED MONTH 7 DAY 23 YEAR 82	EXPECTED ARRIVAL DATE MONTH 3 DAY 23 YEAR 88
Transporter HWT ID No. 12972	STATE IN	NUMBER 290412	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John K. ...</i>

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306
EPA I.D. NO. 1125

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312 P.O. Box 59	219-391-2531	TND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	East Chicago, IN 46312	219-397-2664	TND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, TN 46406	219-944-7858	TND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. n.o.s. Hazardous waste, solid	ORM-E	NA9189					3770					1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 39

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR TST Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2511	IND005462601
TRANSPORTER NO. 1 (IF ANY) Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250597
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid, N.O.S.	ORM-E	NA9189				X	2339	X					1	Rel	TT	F006
2. (Central waste Treatment Plant Sludge)	(12)															
3.																
4.																

al Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment:
o. Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Greg. W. ...</i>	TITLE WASTE WATER OPA,	DATE TO BE SHIPPED MONTH DAY YEAR 3 30 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3 30 82
Transporter HWT ID No. 124 111 29934	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. ...</i>	DATE RECEIVED MONTH DAY YEAR 3 30 82

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 40

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd. East Chicago, IN 46312	219-391-2531	TND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, N.O.S. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770					1	ROL	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE	DATE TO BE SHIPPED			EXPECTED ARRIVAL DATE			
			MONTH	DAY	YEAR	MONTH	DAY	YEAR	
<i>Shirley P. ...</i>		<i>West Water Center</i>	4	1	82	4	1	82	
TRANSPORTER		STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT			DATE RECEIVED		
D No. 124		IN	2893R	<i>Richard ...</i>			4 1 82		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11256

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	TND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, N.O.S. Central Waste Treatment Plant Sludge	ORM-E (12)	NA9189				X	3337					1	ROL	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

PLEASE TYPE OR PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

REFERENCE 8011

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WA TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	0911	NA9189					3770					1	Rel		
2. (Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Chief Waste Officer	DATE TO BE SHIPPED MONTH DAY YEAR 4/3/82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 4/3/82
TRANSPORTER HWT ID No. 129 IN 21904R	STATE IN	NUMBER 21904R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>

Jones & Laughlin Steel Corporation / an LTV company

PLEASE TYPE OR PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306

112

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WA TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	0911	NA9189					3333					1	Rel		
2. (Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 42

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Cary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3770	X				1	Roll	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

SIGNATURE <i>[Signature]</i>	TITLE General Manager	DATE TO BE SHIPPED MONTH DAY YEAR 11/7/92	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11/7/92
STATE IN	NUMBER 290412	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 11/11/92

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1133

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Cary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3333	X				1	Roll	T	P006
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1133
EPA I.D. NO. Page 43

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1 Rail	T	FO
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>James R. Wright</i>	<i>Waste Water Operator</i>	4 10 82	
TRANSPORTER HWHT	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
ID No. 124	IN	2994	<i>Richard Roach</i>

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1133

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1 Rail	T	FO06
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 44

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X					1	ROL	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James W. Welfer</i>	TITLE W. Welfer, Operator	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No. 154	STATE IN	NUMBER 2893X	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Krack</i>
DATE RECEIVED MONTH DAY YEAR		DATE RECEIVED MONTH DAY YEAR	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11338

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X					1	ROL	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11341
REFERENCE 80

3 PART A

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3374	X				1 Rol	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
Robert O Leslie	Master/Operator	4/17/82	4/17/82
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
IND No. 124	IN	2899	4/17/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1134

3 PART A

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3770	X				1 Rol	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
		MONTH / DAY / YEAR	MONTH / DAY / YEAR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11342

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE.

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, R.O.S.	ORM-E	NA9189				X	3353	X				1	RCL	T	FG06
2. (Central Waste Treatment plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Vice President	DATE TO BE SHIPPED MONTH DAY YEAR 4/20/82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 4/20/82
Transporter HWT ID No. 129	STATE IN	NUMBER 2901R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH DAY YEAR 4/20/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11343

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE.

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, R.O.S.	ORM-E	NA9189				X	3770	X				1	RCL	T	FG06
Central Waste Treatment plant Sludge	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 111
Page 47

3 PART A

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189			X		3333	X				1	Roll	T	F
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John R. ...</i>	TITLE Waste Manager	DATE TO BE SHIPPED 4/24/82	EXPECTED ARRIVAL DATE 4/24/82
TRANSPORTER HWT ID No. 129 IN 2190412	STATE IN	NUMBER 2190412	DATE RECEIVED 4/24/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 113

3 PART A

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406		944-7858 219-688-5326	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189			X		3770	X				1	Roll	T	F
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 48

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-344-7858	IND0770059

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	W
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid H.O.S.	094-E	NA9189					3770					1	Box	T	
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James A. Wright</i>	TITLE <i>W. W. Wright</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>6 8 82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>6 9</i>
TRANSPORTER HWT ID No. <i>124</i>	STATE <i>IN</i>	NUMBER <i>27938</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>B. J. ...</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-344-7858	IND0770059

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	W
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid H.O.S.	094-E	NA9189					2275					1	Box	T	
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 11473
REFERENCE 80

3 PART A

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
IWT Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

Page 49

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste solid n.o.s.	ORM-E	NA9189				X							T	F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>Waste Operator</i>	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
TRANSPORTER NO. 1 STATE NUMBER D No. <i>121702781A</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR	

HAZARDOUS WASTE MANIFEST

3 PART A

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
IWT Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

DOCUMENT NO. 7306 11474

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste solid n.o.s.	ORM-E	NA9189					3333					1 Pallet		F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 50

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1 Ro	T	F006
2. Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Water Oper	6/12/22	6/18/22
Transporter HWT ID No. 1/19	STATE	NUMBER	DATE RECEIVED
3	IN	2404R	6/12/22

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11500

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,770	X				1 Ro	T	F006
2. Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

1/1/19

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306
Page 51

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE	
Hazardous waste, solid, h.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3333	X				1	Ro	T
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James D. Bryant</i>	TITLE Waste Water Ops.	DATE TO BE SHIPPED MONTH 6 DAY 21 YEAR 12	EXPECTED ARRIVAL MONTH 6 DAY 21
TRANSPORTER HWT ID No. 126	STATE IN NUMBER 2891	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Robert Cook</i>	DATE RECEIVED MONTH 6 DAY 21

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 1

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE	
Hazardous waste, solid, h.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770	X				1	Ro	T
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL
-----------------------	-------	--------------------	------------------

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7386

REFERENCE 80
Page 52

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	TND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Cary, TN 46406	219-944-7858	TND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE		EPA HAZ CODE	W
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid n.o.s.	ORM-E	NA9189				x	3710					1	REL	T	
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>J. L. Perkins</i>	TITLE Waste Value Manager	DATE TO BE SHIPPED MONTH DAY YEAR 11/16/82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11/16/82
Transporter HWT ID No. 129	STATE IN	NUMBER 290412	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION <i>John R. Roush</i>
			DATE RECEIVED MONTH DAY YEAR 11/16/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	TND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Cary, TN 46406	219-944-7858	TND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE		EPA HAZ CODE	W
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				x	3333					1	REL	T	
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

11454

3 PART A

REFERENCE 80

Page 53

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312			219-391-2531	
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3276	X				1	Rel	T	P006
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George Perry</i>	TITLE <i>Asst. Mgr. Operations</i>	DATE TO BE SHIPPED MONTH <input type="checkbox"/> DAY <input type="checkbox"/> YEAR <input type="checkbox"/>	EXPECTED ARRIVAL DATE MONTH <input type="checkbox"/> DAY <input type="checkbox"/> YEAR <input type="checkbox"/>
TRANSPORTER HWI ID No. <i>184 IN 2793R</i>	TRANSPORTER NO. 1 SIGNATURE AND VERIFICATION OF RECEIPT OF SHIPMENT <i>Richard Howard</i>	DATE RECEIVED MONTH <input type="checkbox"/> DAY <input type="checkbox"/> YEAR <input type="checkbox"/>	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11455

3 PART A

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312			219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	Rel	T	P006
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 54

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J. Steel Corp. TRANSPORTER NO. 1	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	TND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste solid D.O.S.	ORM-E	NA9189				X	3710	X				1	ROL	T	P006
Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE James R. Wright	TITLE Waste Management	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No. 124	STATE IN	NUMBER 2899A	DATE RECEIVED MONTH DAY YEAR

Jones & Laughlin Steel Corporation / an TV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1145

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J. Steel Corp. TRANSPORTER NO. 1	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	TND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste solid D.O.S.	ORM-E	NA9189				X	3733	X				1	ROL	T	P006
Central waste treatment plant sludge)	(12)														
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 8011450

3 PART A

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR JEL Steel Corp.	3001 Dickey Rd East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid D.O.S.	0911	NA9189				x	3770					1	201	T	P006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *James W. Wright* TITLE: *WASTE WATER OPER* DATE TO BE SHIPPED: *6/2/82* EXPECTED ARRIVAL DATE: *6/2/82*

TRANSPORTER SIGNATURE: *J. Marking* DATE RECEIVED: *6/2/82*

Jones & Laughlin Steel Corporation / and TV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 11451

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR JEL Steel Corp.	3001 Dickey Rd East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid D.O.S.	0911	NA9189				x	3333					1	201	T	P006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

Page 56

3 PART A

DOCUMENT NO. 7306

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
Hazardous waste, solid, N.O.S. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770	X				1	R1
3.													
4.													

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *James R. Wright* TITLE: *Plant Manager* DATE TO BE SHIPPED: *6/1/81* EXPECTED ARRIVAL DATE: *6/1/81*

Transporter HWT ID No. *122* STATE: *IN* NUMBER: *2199712* TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *J. Marking* DATE RECEIVED: *6/1/81*

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11

3 PART A

DOCUMENT NO. 7306

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
Hazardous waste, solid, N.O.S. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3333	X				1	R1
3.													
4.													

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 1144

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND035462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770	X				1	Rel	T	F006
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTEWATER OPERATOR	DATE TO BE SHIPPED MONTH 6 DAY 1 YEAR 82	EXPECTED ARRIVAL DATE MONTH 6 DAY 1 YEAR 82
TRANSPORTER ID No. 124	STATE IN	NUMBER 21893R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH 6 DAY 1 YEAR 82

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1144

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND035462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3333	X				1	Rel	T	F006
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 58

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312 P.O. Box 59 East Chicago, IN 46312	219-391-2531 219-397-2664	IND005462601 IND044250587
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7358	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WA T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3333	X				1	Roll		FO
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 5 DAY 31 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 31
TRANSPORTER STATE IN	NUMBER 2893A	TRANSPORTER NO. / SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 5 DAY 31

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312 P.O. Box 59 East Chicago, IN 46312	219-391-2531 219-397-2664	IND005462601 IND044250587
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WA T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3776	X				1	Roll		FO
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 11442
Page 59

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND0005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid n.o.s.	ORM-E	NA9189					3770				1	Rel		F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George P. ...</i>	TITLE <i>Water Treatment Operator</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5 27 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 27 82
TRANSPORTER HWT ID No. 126 JIM 2797A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OR RECEIPT OF SHIPMENT <i>J. ...</i>	DATE RECEIVED MONTH DAY YEAR 5 27 82	

HAZARDOUS WASTE MANIFEST

7306 11443

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189					3333				1	Rel		F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

REFERENCE 80

Page 60

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. 6056 Gary, IN 46406	219-944-7358	IND0770059

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189					3170					1 RoL	
2. (Central waste treatment plant sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John K. ...</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 5 DAY 28 YEAR 82	EXPECTED ARRIVAL MONTH 5 DAY 28
TRANSPORTER HWT ID NO. 7029072	STATE NUMBER 7029072	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John K. ...</i>	DATE RECEIVED MONTH 5 DAY 28

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7358	IND0770059

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous waste solid n.o.s.	ORM-E	NA9189					3333					1 RoL	
2. (Central waste treatment plant sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL
-----------------------	-------	--------------------	------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 11430
REFERENCE 80

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00546260
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3044	X				1	R-1	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
George Pinner	Waste Water Operator	5/17/87	5/17/87
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
IND00546260	IN	2901AR	5/17/87

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1143

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND00546260
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2700	X				1	R-1	F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
TRANSPORTER NO. 1	J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND00546260
	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO.	TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2700				1	Ro	
2. (Central waste treatment plant sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George Pinner</i>	TITLE WASTE WATER OPER	DATE TO BE SHIPPED MONTH 5 DAY 27 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 27
Transporter ID No. 122	STATE IN	NUMBER 28197R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. Hartung</i>
		DATE RECEIVED MONTH 5 DAY 27	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 11

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
TRANSPORTER NO. 1	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO.	TYPE	EPA HAZ CODE	WEIGHT
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2700				1	Ro		FO
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

HAZARDOUS WASTE MANIFEST

DOCUMENT NO 7306

1143

3 PART A

REFERENCE 80

Page 63

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Rd East Chicago, IN 46312	PHONE NO 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. BOX 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste solid n.o.s.	ORM-E	NA9189				X	3770					1 Ro		F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Shang P. Wang</i>	TITLE WASTE WATER OPER	DATE TO BE SHIPPED MONTH 5 DAY 27 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 27 YEAR 82
TRANSPORTER HWT ID No. 122	STATE IN	NUMBER 78978	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. Martin</i>

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO 7306

1143

3 PART A

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333					1 Ro		F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>J. Martin</i>	TITLE WASTE WATER OPER	DATE TO BE SHIPPED MONTH 5 DAY 27 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 27 YEAR 82
---	----------------------------------	---	--

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7305

REFERENCE 80

Page 64

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2700	X				1	RoL	T	F00
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O. Leslie	TITLE manutransporter	DATE TO BE SHIPPED MONTH 27 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 YEAR 82
TRANSPORTER HWT ID No. 122	STATE IN	NUMBER 21897R	DATE RECEIVED MONTH 5 YEAR 82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7305

1143

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	RoL	T	F006
2. (Central waste treatment plant sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 11425
REFERENCE 80

3 PART A	
NAME	SITE ADDRESS
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312
TRANSPORTER NO. 2 (IF ANY)	
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406
219-391-2531 Page 65	
219-397-2664 IND044250587	
219-344-7858 IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3276	X				1	Rel	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George Pinner</i>	TITLE <i>Unit Water Operator</i>	DATE TO BE SHIPPED MONTH DAY YEAR 3 26 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 26 82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. Marting</i>	DATE RECEIVED MONTH DAY YEAR 5 26 82		

Jones & Laughlin Steel Corporation / an I.T.V. company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 114

3 PART A	
NAME	SITE ADDRESS
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312
TRANSPORTER NO. 2 (IF ANY)	
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406
219-391-2531	
219-397-2664 IND044250587	
219-344-7858 IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3044	X				1	Rel	F00
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>A</i>	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 66

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189			X		304	X			1	Roll	P	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>George P. ...</i>	Waste Management OPER	5/26/92	5/26/92
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
IND 129	IN	29042	5/26/92

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

114

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189			X		3333	X			1	Roll	P	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

7306 1142
REFERENCE 80
Page 67

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	Rd	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O. Ledo	TITLE WASTE WATER OPER	DATE TO BE SHIPPED MONTH 5 DAY 26 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 26 YEAR 82
TRANSPORTER HWT ID No. 122	STATE IN	NUMBER 28977A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT J. H. H. H.

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

7306 1142
DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	Rd	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY GENERATOR

DATE TO BE SHIPPED
EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
Page 68

3 PART A

DOCUMENT NO. 7306

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601	
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587	
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid N.O.S.	ORM-E	NA9139					2700					1	ROL	T	FO
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE manutemater sp	DATE TO BE SHIPPED MONTH 5 DAY 26 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 26 YEAR
Transporter HWT ID No. 123 IN 28978	STATE NUMBER 28978	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. Marting</i>	DATE RECEIVED MONTH 5 DAY 26 YEAR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 114

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601	
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587	
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid N.O.S.	ORM-E	NA9139					2700					1	ROL	T	FO
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11419
EPA I.D. NO. IND077005916

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Rd East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste solid N.O.S.	ORM-B	NA9189					3333					1	ROL	P006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Sharon Pinner</i>		TITLE <i>Director of Operations</i>		DATE TO BE SHIPPED MONTH DAY YEAR 5 25 87		EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 25 87	
TRANSPORTER HWT ID No. 1267M 7891R		STATE NUMBER		TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Paul Vode</i>		DATE RECEIVED MONTH DAY YEAR 5 25 87	

Jones & Laughlin Steel Corporation / an LTV company
HAZARDOUS WASTE MANIFEST
DOCUMENT NO. 7306 - 11419

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp		3001 Dickey Rd East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste solid N.O.S.	ORM-B	NA9189					3770					1	ROL	P006
2. (Central waste treatment Plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 70

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	TND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EP WA: TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid H.O.S.	ORM-F	NA9189					3044					1	ROL		FO
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Jay Marking</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH DAY YEAR 5 25 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 25 82
Transporter ID No. 122	STATE IN	NUMBER 2897A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OR RECEIPT ON SHIPMENT <i>J. Marking</i>
			DATE RECEIVED MONTH DAY YEAR 5 25 82

Jones & Laughlin Steel Corporation / an ILC company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

114

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	TND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EP WA: TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid H.O.S.	ORM-F	NA9189					2700					1	ROL		FO
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 8041

3 PART A

GENERATOR NAME	3001 DICKER ROAD	PHONE NO.	EPA I.D. NO.
1. J & S STEEL CORP	EAST CHICAGO, IN 46312	219-397-2531	IND0054621
TRANSPORTER NO. 1	P.O. BOX 59		
INDUSTRIAL DISPOSAL CORP	EAST CHICAGO, IN 46312	219-397-2601	IND0041250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. BOX 6056		
CARL LAND DEVELOPMENT	CARL IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE					GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189					X	2700	X						1	ROL T	FOO
2. (CENTRAL WASTE TREATMENT PLANT SLUDGE)	(12)																
3.																	
4.																	

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>John Smith</i>	WASTE WATER OPERATOR	5-25-82	5-25-82
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
IND	IN	29014R	

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an I. T. Company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 2306 1141

3 PART A

GENERATOR NAME	3001 DICKER ROAD	PHONE NO.	EPA I.D. NO.
1. J & S STEEL CORP	EAST CHICAGO, IN 46312	219-397-2531	IND0054621
TRANSPORTER NO. 1	P.O. BOX 59		
INDUSTRIAL DISPOSAL CORP	EAST CHICAGO, IN 46312	219-397-2601	IND0041250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. BOX 6056		
CARL LAND DEVELOPMENT	CARL IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE					GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189					X	2700	X						1	ROL T	FOO
2. (CENTRAL WASTE TREATMENT PLANT SLUDGE)	(12)																
3.																	
4.																	

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>John Smith</i>			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7806 114

GENERATOR NAME J & L STEEL CORP	SITE ADDRESS 3001 DICKER ROAD EAST CHICAGO, IN 46312 P.O. BOX 59	PHONE NO. 219-391-2531	EPA I.D. NO. IND0054626
TRANSPORTER NO. 1 INDUSTRIAL DISPOSAL CORP	EAST CHICAGO, IN 46312	219-397-2664	IND004125058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY GRP LAND DEVELOPMENT	P.O. BOX 6056 GARV IN 46406	219-944-7858	IND0110059

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189				X	3700					1	ROL T	FO
2. CENTRAL WASTE TREATMENT	(12)													
3. PLANT SLUDGE														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert Leslie</i>	TITLE <i>Manager</i>	DATE TO BE SHIPPED MONTH <i>5</i> DAY <i>25</i> YEAR <i>82</i>	EXPECTED ARRIVAL DATE MONTH <i>5</i> DAY <i>25</i> YEAR <i>82</i>
Transporter HMT ID No. <i>124</i>	STATE <i>IN</i>	NUMBER <i>219938</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. ...</i>
			DATE RECEIVED MONTH <i>5</i> DAY <i>25</i> YEAR <i>82</i>

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7806 1140

GENERATOR NAME J & L STEEL CORP	SITE ADDRESS 3001 DICKER ROAD EAST CHICAGO, IN 46312 P.O. BOX 59	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 INDUSTRIAL DISPOSAL CORP	EAST CHICAGO, IN 46312	219-397-2664	IND004125058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY GRP LAND DEVELOPMENT	P.O. BOX 6056 GARV IN 46406	219-944-7858	IND011005910

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189				X	3044					1	ROL T	FO
2. CENTRAL WASTE TREATMENT	(12)													
3. PLANT SLUDGE														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Use TYPE or PRINT clearly, using
all point pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 11405

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JL STEEL CORP	3001 DICKERSON ROAD EAST CHICAGO, IN 46312	219-391-2531	IND000542601
TRANSPORTER NO. 1	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2001	IND0044250587
INDUSTRIAL DISPOSAL CORP			
TRANSPORTER NO. 2 (IF ANY)			

TREATMENT, STORAGE OR DISPOSAL FACILITY	ADDRESS	PHONE NO.	EPA I.D. NO.
MRP LAND DEVELOPMENT	P.O. BOX 6056 GARIN, IN 46406	219-944-7858	IND0010005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLODGE		GALLONS	CUBIC YDS	POUNDS	TONS				
HAZARDOUS WASTE, SOLID, N.O.S. (CENTRAL WASTE TREATMENT PLANT SLUDGE)	ORM-E (12)	NA9189					2700 X					1	ROL T		FOOL6

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	5/24/82	5/24/82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	MONTH	DAY
<i>[Signature]</i>	5	24	82

Jones & Laughlin Steel Corporation / an LTV company
HAZARDOUS WASTE MANIFEST
DOCUMENT NO. 7006-11406

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JL STEEL CORP	3001 DICKERSON ROAD EAST CHICAGO, IN 46312	219-391-2531	IND000542601
TRANSPORTER NO. 1	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2001	IND0044250587
INDUSTRIAL DISPOSAL CORP			
TRANSPORTER NO. 2 (IF ANY)			

TREATMENT, STORAGE OR DISPOSAL FACILITY	ADDRESS	PHONE NO.	EPA I.D. NO.
MRP LAND DEVELOPMENT	P.O. BOX 6056 GARIN, IN 46406	219-944-7858	IND0010005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLODGE		GALLONS	CUBIC YDS	POUNDS	TONS				
HAZARDOUS WASTE, SOLID, N.O.S. (CENTRAL WASTE TREATMENT PLANT SLUDGE)	ORM-E (12)	NA9189					3333 X					1	ROL T		FOOL6

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7306 11409

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J & L STEEL CORP	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2531	IND0005462601
TRANSPORTER NO. 1 INDUSTRIAL DISPOSAL CORP	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2664	IND004250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
SAFETY LAND DEVELOPMENT	P.O. BOX 4056 SAFETY IN 46406		
	219-944-7858 IND0077005914		

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	QUANTITY	GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, A.Q.S.	ORM-E	NA9189				X	2700	X				1	ROLT	FOO00
2. (CENTRAL WASTE TREATMENT	(12)													
3. PLANT SLUDGE)														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: WASTE WATER OPERATOR DATE TO BE SHIPPED: 5-25-82 EXPECTED ARRIVAL DATE: 5-25-82

Transporter STATE: IN NUMBER: 1227412897R TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: 5-25-82

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7306 1141

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J & L STEEL CORP	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2531	IND0005462601
TRANSPORTER NO. 1 INDUSTRIAL DISPOSAL CORP	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2664	IND004250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
SAFETY LAND DEVELOPMENT	P.O. BOX 4056 SAFETY IN 46406		
	219-944-7858 IND0077005914		

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	QUANTITY	GALLONS	CU YDS	POUNDS	TONS			
1. HAZARDOUS WASTE, SOLID, A.Q.S.	ORM-E	NA9189				X	2700	X				1	ROLT	FOO00
2. (CENTRAL WASTE TREATMENT	(12)													
3. PLANT SLUDGE)														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: DATE TO BE SHIPPED: EXPECTED ARRIVAL DATE:

3 PART A

REFERENCE 80

Page 75

TO BE FILLED OUT BY GENERATOR

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR			
TRANSPORTER NO. 1			
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1.															
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No.	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OR SHIPMENT	DATE RECEIVED MONTH DAY YEAR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1141

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR			
TRANSPORTER NO. 1			
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1.															
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
-----------------------	-------	--------------------------------------	---

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7304

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Ind Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-844-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				x	3333					1 RoL		PO
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Wesley Water Operator</i>	TITLE WESLEY WATER OPERATOR	DATE TO BE SHIPPED MONTH 5 DAY 24 YEAR 80	EXPECTED ARRIVAL DATE MONTH 5 DAY 26 YEAR 80
TRANSPORTER HWT. 12071128951R	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Wesley Water Operator</i>	DATE RECEIVED MONTH 5 DAY 26 YEAR 80

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7306

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Ind Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-844-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste, solid, n.o.s.	ORM-E	NA9189				x	2700					1 RoL		PO
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

REFERENCE 80

Page 77

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND035462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9139				X	5770	X				1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>Waste Manager</i>	DATE TO BE SHIPPED MONTH <i>5</i> DAY <i>18</i> YEAR <i>1987</i>	EXPECTED ARRIVAL DATE MONTH <i>5</i> DAY <i>18</i> YEAR <i>1987</i>
TRANSPORTER'S SIGNATURE <i>[Signature]</i>	TITLE <i>John T. [unclear]</i>	DATE TO BE SHIPPED MONTH <i>5</i> DAY <i>18</i> YEAR <i>1987</i>	EXPECTED ARRIVAL DATE MONTH <i>5</i> DAY <i>18</i> YEAR <i>1987</i>

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / and its company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1188

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND035462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9139				X	3333	X				1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>[unclear]</i>	DATE TO BE SHIPPED MONTH <i>5</i> DAY <i>18</i> YEAR <i>1987</i>	EXPECTED ARRIVAL DATE MONTH <i>5</i> DAY <i>18</i> YEAR <i>1987</i>
---	---------------------------	---	--

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 78

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development		P.O. Box 6056 Cary, IN 46406	219-344-7858 IND077005916
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>			
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM SOLID LIQUID GAS SLUDGE
1. Hazardous waste, solid n.o.s.	091-E	NA9189	QUANTITY 3770
2. (Central waste treatment plant sludge)	(12)		
3.			
4.			
Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.			
GENERATOR'S SIGNATURE <i>Thom Monahan</i>		DATE TO BE SHIPPED MONTH 7 DAY 24 YEAR 82	
TRANSPORTER SIGNATURE <i>Carl</i>		DATE RECEIVED MONTH 5 DAY 24 YEAR 82	

3 PART A		DOCUMENT NO. 7306					
NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR J&L Steel Corp.		3001 Dickey Rd East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1 Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development		P.O. Box 6056 Cary, IN 46406		219-344-7858		IND077005916	
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE							
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>							
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM SOLID LIQUID GAS SLUDGE	QUANTITY	UNITS GALLONS CU YDS POUNDS TONS	CONTAINERS NO. TYPE	EPA HAZ CODE EPA WASTE TYPE
1. Hazardous waste, solid n.o.s.	091-E	NA9189		2700		1 Red	FOO
2. (Central waste treatment plant sludge)	(12)						
3.							
4.							
Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)							
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.							

HAZARDOUS WASTE MANIFEST

3 PART A

REFERENCE 80

Page 79

GENERATOR NAME: JSL Steel Corp. SITE ADDRESS: 3001 Dickey Rd, East Chicago, IN 46312

TRANSPORTER NO. 1: Industrial Disposal Corp. P.O. Box 59, East Chicago, IN 46312

TREATMENT, STORAGE OR DISPOSAL FACILITY: P.O. Box 6056, Gary, IN 46406

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid	ORG-E	WA9189					3044					1	Roll		
2 (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: [Signature] TITLE: WASTE WATER OPERATOR

DATE TO BE SHIPPED: 5-24-82

EXPECTED ARRIVAL DATE: 5-24-82

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION: [Signature]

DATE RECEIVED: 5-24-82

HAZARDOUS WASTE MANIFEST

3 PART A

11887

GENERATOR NAME: JSL Steel Corp. SITE ADDRESS: 3001 Dickey Rd, East Chicago, IN 46312

TRANSPORTER NO. 1: Industrial Disposal Corp. P.O. Box 59, East Chicago, IN 46312

TREATMENT, STORAGE OR DISPOSAL FACILITY: P.O. Box 6056, Gary, IN 46406

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste solid	ORG-E	WA9189					2700					1	Roll		
2 (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: [Signature] TITLE: [Title]

DATE TO BE SHIPPED: [Date]

EXPECTED ARRIVAL DATE: [Date]

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION: [Signature]

DATE RECEIVED: [Date]

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

Page 80

3 PART A

DOCUMENT NO.

7306

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00546266
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2700	X				1 ROL	
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Jay Minkler</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 5 DAY 21 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 21
TRANSPORTER HWT ID NO. 0129	STATE IN	NUMBER 2904A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. K. ...</i>
		DATE RECEIVED MONTH 5 DAY 21	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00546266
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2700	X				1 ROL	
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

PLEASE TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11855
EPA I.D. NO. 11855
Page 81

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077605916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	2700	X				1 Rol	T	P006

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Jay Mink</i>	TITLE Waste Water Cop	DATE TO BE SHIPPED MONTH 5 DAY 21 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 21 YEAR 82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT <i>John T...</i>	STATE IN	DATE RECEIVED MONTH 5 DAY 21 YEAR 82	

PLEASE TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11856

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3074	X				1 Rol	T	P006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 82

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	3044	X				1	Rel	FO06
2. Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Jim M... ..</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 5 DAY 21 YEAR 82	EXPECTED ARRIVAL DATE MONTH 5 DAY 21 YEAR 82
Transporter HWT ID No. 107112875 R	STATE IN	NUMBER 2875 R	DATE RECEIVED MONTH 5 DAY 21 YEAR 82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Robert J.</i>			

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1185

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	2700	X				1	Rel	FO06
2. Central Waste Treatment Plant Sludge	(12)													
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
Page 83

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND0054626	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND0770059	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2700	X					1	Roll	T
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL	
<i>Jay M. ...</i>		WASTE WATER OPERATOR		5-21-87		5-21-87	
TRANSPORTER'S SIGNATURE		STATE		NUMBER		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	
<i>Robert J. ...</i>		IN		219-397-2664		<i>Robert J. ...</i>	

HAZARDOUS WASTE MANIFEST

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND0054626	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND0770059	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1 Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3044	X					1	Roll	T
2 (Central Waste Treatment Plant Sludge)	(12)														
3															
4															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7306 08

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE		
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS	
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	333.3	X				1	Ro	T	FOO
2. (Tar Decanter Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *[Signature]* DATE TO BE SHIPPED: MONTH *12* DAY *12* YEAR *1990* EXPECTED ARRIVAL DATE: MONTH *12* DAY *12* YEAR *1990*

Transporter: *[Signature]* STATE: *IN* NUMBER: *12* DATE RECEIVED: MONTH *12* DAY *12* YEAR *1990*

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7306 118

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE		
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS	
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	333.3	X				1	Ro	T	FOO
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 861213

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp TRANSPORTER NO. 1	3001 Dickey Rd East Chicago, IN 46312 P.O. Box 59	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	East Chicago, IN 46312	219-397-2654	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste, solid H.O.S.	ORM-E	NA9139				x	3790	x				1 RoL	T	F006
2. (Central waste treatment Plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John W. Winkler</i>	TITLE Waste Wkld. Officer	DATE TO BE SHIPPED 5/20/82	EXPECTED ARRIVAL DATE 5/20/82
TRANSPORTER HWT ID No. 129	STATE Ind	NUMBER 190116	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Winkler</i>
			DATE RECEIVED 5/20/82

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

121

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp TRANSPORTER NO. 1	3001 Dickey Rd East Chicago, IN 46312 P.O. Box 59	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	East Chicago, IN 46312	219-397-2654	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid H.O.S.	ORM-E	NA9139				x	3790	x				1 RoL	T	F006
2. (Central Waste treatment Plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

Page 86

3	PART A	DOCUMENT NO. 7306	121	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
1	J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
2	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				
37				
38				
39				
40				
41				
42				
43				
44				
45				
46				
47				
48				
49				
50				
51				
52				
53				
54				
55				
56				
57				
58				
59				
60				
61				
62				
63				
64				
65				
66				
67				
68				
69				
70				
71				
72				
73				
74				
75				
76				
77				
78				
79				
80				
81				
82				
83				
84				
85				
86				
87				
88				
89				
90				
91				
92				
93				
94				
95				
96				
97				
98				
99				
100				

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	SOLID	LIQUID	GAS	SLUDGE	QUANTITY	GALLONS	CU YDS	POUNDS	TONS	CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
												NO.	TYPE			
Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	2700	X					1	Ro	3	P006
(Central Waste Treatment Plant Sludge)	EX (12)															
			</													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Water Operator	5/12/82	5/12/82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	DATE RECEIVED
<i>[Signature]</i>	<i>[Signature]</i>	MONTH DAY YEAR	MONTH DAY YEAR

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1213

3	PART A	DOCUMENT NO. 7306	1213	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
1	J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
2	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				
37				
38				
39				
40				
41				
42				
43				
44				
45				
46				
47				
48				
49				
50				
51				
52				
53				
54				
55				
56				
57				
58				
59				
60				
61				
62				
63				
64				
65				
66				
67				
68				
69				
70				
71				
72				
73				
74				
75				
76				
77				
78				
79				
80				
81				
82				
83				
84				
85				
86				
87				
88				
89				
90				
91				
92				
93				
94				
95				
96				
97				
98				
99				
100				

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
hazardous waste, solid L.C.S.	ORM-E	NA9189				X	3770	Y			1	Ro	T	P006
(Central waste treatment plant sludge)	EX (12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Water Operator	5/12/82	5/12/82
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	DATE RECEIVED
<i>[Signature]</i>	<i>[Signature]</i>	MONTH DAY YEAR	MONTH DAY YEAR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12129

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E MX	NA9189				X	3044	X				1	204	T	F006
2. (Central Waste Treatment plant sludge)	822X (12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Lesko</i>	TITLE <i>Waste Water Oper</i>	DATE TO BE SHIPPED MONTH / DAY / YEAR <i>5/18/82</i>	EXPECTED ARRIVAL DATE MONTH / DAY / YEAR <i>5/18/82</i>
TRANSPORTER STATE ID No. <i>129 IN 290 AR</i>	NUMBER <i>129</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Rausch</i>	DATE RECEIVED MONTH / DAY / YEAR <i>5/18/82</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12130

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp	3001 Dickey Rd East Chicago, IN	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	204	T	F006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Lesko</i>	TITLE <i>Waste Water Oper</i>	DATE TO BE SHIPPED MONTH / DAY / YEAR <i>5/18/82</i>	EXPECTED ARRIVAL DATE MONTH / DAY / YEAR <i>5/18/82</i>
---	----------------------------------	--	---

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 88

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Rd.	East Chicago, IN 46312	219-397-2531	IND005462601
Industrial Disposal Corp/	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid	ORM-P	NA9189				X	7700	X				1	Ro		F006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
Robert L. Leslie	Waste Manager	5/12/82	5/12/82
TRANSPORTER	STATE	NUMBER	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
HWT	IN	79018	John R. Smith
ID No. 120			DATE RECEIVED
			5/12/82

Jones & Laughlin Steel Corporation / an TV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12128

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Rd.	East Chicago, IN 46312	219-397-2531	IND005462601
Industrial Disposal Corp	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid	ORM-P	NA 9189				X	3333	X				1	Ro		F006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 1212
Page 89

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7852	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9129					3333					1	Ro	006
2. (Central waste treatment plant sludge)	SLX (12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>R. L. ...</i>	<i>...</i>	5/12/82	5/12/82

TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION	DATE RECEIVED
129	IN	29012	<i>...</i>	5/12/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7396

1212

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7852	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9129					3333					1	Ro	006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE

TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION	DATE RECEIVED

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
Page 90

3 PART A

DOCUMENT NO. 7306

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
1	J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
2	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
3				
4				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406		
Cary Land Development		219-944-7858		

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid	091-E	NA9189					3333					1	Rel	T	P006
2. (Central Waste Treatment Plant Sludge)	091-E (12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
Robert O Leslie	Waste Transfer Agent	MONTH 5 DAY 16 YEAR 82	MONTH 5 DAY 16 YEAR 82
Transporter	STATE	NUMBER	DATE RECEIVED
HWT	IN	1212	MONTH 5 DAY 16 YEAR 82
ID No.	1212		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306

1212

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
1	J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
2	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
3				
4				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406		
Cary Land Development		219-944-7858		

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid	091-E	NA9189					3770					1	Rel	T	P006
2. (Central Waste Treatment Plant Sludge)	091-E (12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12118
REFERENCE 80

3 PART A

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Cary, IN 46406		219-444-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid n.o.s.	034-E (12)	NA9180				X	3330	X				1	Roll	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>[Title]</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>[Date]</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>[Date]</i>
Transporter HWT ID No. <i>124</i>	STATE <i>IN</i>	NUMBER <i>7093</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OR RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH DAY YEAR <i>5 15 87</i>

Jones & Laughlin Steel Corporation / an LTV company

lease TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 12119

3 PART A

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Cary, IN 46406		219-444-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid n.o.s.	034-E (12)	NA 9180				X	3270	X				1	Roll	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

Page 92

3 PART A

DOCUMENT NO. 7306

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3333	X				1	ROL	T	PC
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James P. ...</i>	DATE TO BE SHIPPED MONTH DAY YEAR 8 10 88	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 10 88
TRANSPORTER HWT ID No. 126/40 2491K	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Robert ...</i>	DATE RECEIVED MONTH DAY YEAR 8 11 88

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 114

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3770	X				1	ROL	T	PC
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1149
REFERENCE 80

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR			
IND. Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Industrial Disposal Corp.			
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916
Gary Land Development			IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189					3333	x						T	F006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	YEAR	EXPECTED ARRIVAL DATE
<i>Robert Wode</i>	<i>Waste Water Oper.</i>	<i>6-15-82</i>		
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OR RECEIPT OF SHIPMENT	DATE RECEIVED
<i>IND. Steel Corp.</i>	<i>IN</i>	<i>28918</i>	<i>Robert Wode</i>	<i>6-15-82</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 114

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR			
IND. Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Industrial Disposal Corp.			
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. 6056 Gary, IN 46406	219-944-7858	IND077005916
Gary Land Development			IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste solid n.o.s.	ORM-E	NA9189					3770	x				1	Rel	T	F006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
Page 94

3 PART A

DOCUMENT NO. 7306

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jsr. Steel Corp.	3001 Dickey Rd. East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312 YXG	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	V
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2333	X					1	HAZ	
2. (Central Waste Treatment Plant Sludge)	SLUR (12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE James R. W. Wright	TITLE Water Works Operator	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No. 124	STATE IN	NUMBER 28938	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT Richard Proach
			DATE RECEIVED MONTH DAY YEAR 5 14

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jsr. Steel Corp.	3001 Dickey Rd. East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EF WA TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2770	X					1	HAZ	
2. (Central Waste Treatment Plant Sludge)	SLUR (12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12111

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid H.O.S.	ORM-E	NA9189				X	332					1	Not	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE <i>Manager</i>	DATE TO BE SHIPPED MONTH <i>5</i> DAY <i>11</i> YEAR <i>82</i>	EXPECTED ARRIVAL DATE MONTH <i>5</i> DAY <i>12</i> YEAR <i>82</i>
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OR SHIPMENT <i>Richard R. R...</i>	STATE <i>IN</i>	NUMBER <i>5183</i>	DATE RECEIVED MONTH <i>5</i> DAY <i>12</i> YEAR <i>82</i>

Jones & Laughlin Steel Corporation / an UTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12115

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Rd East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid H.O.S.	ORM-E	NA9189				X							T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE

TITLE

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306
EPA I.D. TND005462
TND044250
TND077005

GENERATOR J&L Steel Corp	SITE ADDRESS 3001 Dickey Rd East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. TND005462
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND044250
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND077005

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, P.O.S.	ORM-E	MA9129				X	2000	X					1	ROL	T
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															
Special Handling Instructions including Container Exemption (i.e. Identification of a Non-Hazardous Material)															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James K. Wright</i>	TITLE <i>Waste Mgr</i>	DATE TO BE SHIPPED MONTH <input type="checkbox"/> DAY <input type="checkbox"/> YEAR <input type="checkbox"/>	EXPECTED ARRIVAL MONTH <input type="checkbox"/> DAY <input type="checkbox"/>
Transporter HWT ID No. <i>114</i>	STATE <i>IN</i>	NUMBER <i>1741</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Michael R. Rouse</i>
DATE RECEIVED MONTH <input type="checkbox"/> DAY <input type="checkbox"/>			

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

DOCUMENT NO. 7306
EPA I.D. N
TND00546261
TND0442505
TND07700591

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Rd East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. N TND00546261
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	TND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	TND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE	
1. Hazardous waste, solid, P.O.S.	ORM-E	MA9129				X	3770	X				1	ROL	T
2. (Central Waste Treatment Plant Sludge)	WM (12)													
3.														
4.														
Special Handling Instructions (if any)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James K. Wright</i>	TITLE <i>Waste Mgr</i>	DATE TO BE SHIPPED MONTH <input type="checkbox"/> DAY <input type="checkbox"/> YEAR <input type="checkbox"/>	EXPECTED ARRIVAL MONTH <input type="checkbox"/> DAY <input type="checkbox"/>
Transporter HWT ID No. <i>114</i>	STATE <i>IN</i>	NUMBER <i>1741</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Michael R. Rouse</i>
DATE RECEIVED MONTH <input type="checkbox"/> DAY <input type="checkbox"/>			

PLEASE TYPE OR PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 11839

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, N.O.S. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3383	X				1 866	T	F006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility, can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James R. Wright</i>	TITLE <i>Waste Management Director</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>5 2 82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>5 2 82</i>
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Industrial Disposal Corp.</i>	DATE RECEIVED MONTH DAY YEAR <i>5 2 82</i>		

PLEASE TYPE OR PRINT clearly, using
a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 11940

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous waste, solid, N.O.S. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770	X				1 866	T	F006
2														
3														
4														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility, can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James R. Wright</i>	TITLE <i>Waste Management Director</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>5 2 82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>5 2 82</i>
---	---	---	--

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7306

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND0770

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3533	X					1	Rel	T
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *Waste Water Oper* DATE TO BE SHIPPED: *5/5/87* EXPECTED ARRIVAL: *5/5/87*

TRANSPORTER HWT ID No. *19* STATE: *IN* NUMBER: *19042* TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: *5/5/87*

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A DOCUMENT NO. 7306 - 1

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X					1	Rel	T
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3906

11933

3 PART A

DOCUMENT NO. 7306 - 11936

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3770	X			1	Ro	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Harvey P. ...</i>	TITLE <i>Waste Mgmt. Operator</i>	DATE TO BE SHIPPED MONTH <i>5</i> DAY <i>11</i> YEAR <i>82</i>	EXPECTED ARRIVAL DATE MONTH <i>5</i> DAY <i>1</i> YEAR <i>82</i>
TRANSPORTER HWT ID No. <i>121</i>	STATE <i>IN</i>	NUMBER <i>2798K</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Michael ...</i>
			DATE RECEIVED MONTH <i>5</i> DAY <i>1</i> YEAR <i>82</i>

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 11936

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3533	X			1	Ro	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

Page 100

3 PART A

DOCUMENT NO. 7306

1134

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. SPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. TRANSPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	3333	X				1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED MONTH DAY YEAR			EXPECTED ARRIVAL DATE MONTH DAY YEAR		
Transporter HWT ID No. 121	STATE IN	NUMBER AP 90 R		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT Richard P. ...			DATE RECEIVED MONTH DAY YEAR 4 27 73		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306

11347

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp. SPORTER NO. 2 (IF ANY)	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	3770	X				1	Rel	T	F005
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

DOCUMENT NO. 7305 - 1193
PHONE NO. EPA I.D. NO.

GENERATOR NAME	SITE ADDRESS		DOCUMENT NO.	EPA I.D. NO.
LJL Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND04250587
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND04250587
Industrial Disposal Corp.				
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916
Gary Land Development				

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	9858	X					1	200	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>K. J. P. P. P.</i>	TITLE <i>Waste Water Operator</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>10 27 82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>11 28 82</i>
Transporter HWT ID No. <i>124</i>	STATE <i>IN</i>	NUMBER <i>22934</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Barbara K. Kouch</i>
DATE RECEIVED MONTH DAY YEAR <i>11 29 82</i>			

base TYPE or PRINT clearly using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
Page 102

3 PART A DOCUMENT NO. 7306 1140

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J & L STEEL CORP	3001 DICKEY RD EAST CHICAGO, IN 46312	219-391-2531	IND000546260
TRANSPORTER NO. 1 NATIONAL DISPOSAL CORP	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. BOX 6056 GARY, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
HAZARDOUS WASTE, SOLID, A.C.S.	ORM-E	NA9189					X 2100 X					1	ROL T	FOOL
2. CENTRAL WASTE TREATMENT PLANT	(12)													
3. SLODGE														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: WASTE WATER OPERATOR DATE TO BE SHIPPED: MONTH 5 DAY 24 YEAR 82 EXPECTED ARRIVAL DATE: MONTH 5 DAY 24 YEAR 82

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: MONTH 5 DAY 24 YEAR 82

base TYPE or PRINT clearly using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

11404

3 PART A DOCUMENT NO. 7306 11404

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J & L STEEL CORP	3001 DICKEY ROAD EAST CHICAGO, IN 46312	219-391-2531	IND000546260
TRANSPORTER NO. 1 NATIONAL DISPOSAL CORP	P.O. BOX 59 EAST CHICAGO, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. BOX 6056 GARY, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
HAZARDOUS WASTE, SOLID, A.C.S.	ORM-E	NA9189					X 3044 X					1	ROL T	FOOL
CENTRAL WASTE TREATMENT PLANT	(12)													
WASTE SLODGE														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen. PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1140
REFERENCE 80
 PHONE NO. EPA I.D. NO.
Page 103

3 PART A

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Rd				
Trl Steel Corp	East Chicago, IN 46312			219-391-2531	IND005462601
TRANSPORTER NO.	P.O. Box 59				
Industrial Disposal Corp	East Chicago, IN 46312			219-397-2566	IND0044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056				
Gary Land Development	Gary, IN 46406			219-954-7058	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	DRUMS	55 GALS	POUNDS	TONS	DRUMS	55 GALS	POUNDS	TONS				
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189							2700						1	ROL		T005
2. (Central waste treatment plant sludge)	(12)																	
3.																		
4.																		

Special Handling Instructions Including Container Exemption (i.e., identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	5-24-88	5-24-88
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION ON RECEIPT
IND 005462601	IN	2895A	<i>[Signature]</i>

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen. PRESS HARD

3 PART A

DOCUMENT NO. 7306 1140

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Rd				
Trl Steel Corp	East Chicago, IN 46312			219-391-2531	IND005462601
TRANSPORTER NO.	P.O. Box 59				
Industrial Disposal Corp	East Chicago, IN 46312			219-397-2566	IND0044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056				
Gary Land Development	Gary, IN 46406			219-954-7058	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	DRUMS	55 GALS	POUNDS	TONS	DRUMS	55 GALS	POUNDS	TONS				
1. HAZARDOUS WASTE, SOLID, N.O.S.	ORM-E	NA9189							3044						1	ROL		T005
2. (CENTRAL WASTE TREATMENT PLANT SLUDGE)	(12)																	
3.																		
4.																		

Special Handling Instructions Including Container Exemption (i.e., identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 104

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	201	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert & Leslie</i>	TITLE waste water oper	DATE TO BE SHIPPED MONTH DAY YEAR 5/22/82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5/22/82
Transporter HWT ID No. 124	STATE IN	NUMBER 2404R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John K...</i>
			DATE RECEIVED MONTH DAY YEAR 5/22/82

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

11860

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3044	X				1	201	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 11
EPA I.D. NO.

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WAS TYF	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid H.O.S.	ORM-E	NA9189				X	3333	X					1	20	T	FOI
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>John R. Smith</i>	Waste Manager	5/22/87	5/22/87
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
129	IN	2904E	5/22/87

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 11
EPA I.D. NO.

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WAS TYF	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid H.O.S.	ORM-E	NA9189				X	3333	X					1	20	T	FOI
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>John R. Smith</i>	Waste Manager	5/22/87	5/22/87
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
129	IN	2904E	5/22/87

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302

1112

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	KO87
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nye</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 3 18 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3 18 82
Transporter HWT ID No. 118 170 218 90 R	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Robert Code</i>	DATE RECEIVED MONTH DAY YEAR 3 18 82

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Robert Code</i>	DATE DELIVERED MONTH DAY YEAR 3 18 82
Transporter No. 2 HWT ID No. 118 170 218 90 R	DATE RECEIVED MONTH DAY YEAR 3 18 82
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1 P-37

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>W. L. H. H. H.</i>	TITLE <i>W. L. H. H. H.</i>	DATE RECEIVED MONTH DAY YEAR 3 18 82
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302

1112

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 11126

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2644	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 RoH	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Page</i>		TITLE <i>Supt. Clerk</i>		DATE TO BE SHIPPED MONTH 3 DAY 17 YEAR 82			EXPECTED ARRIVAL DATE MONTH 3 DAY 17 YEAR 82					
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. Rouch</i>		TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>			DATE RECEIVED MONTH 3 DAY 17 YEAR 82			DATE DELIVERED MONTH 3 DAY 17 YEAR 82				
Transporter HWT ID No. 44	STATE IN	NUMBER 2893R										

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard R. Rouch</i>				DATE DELIVERED MONTH 3 DAY 17 YEAR 82			
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>[Signature]</i>				DATE RECEIVED MONTH 3 DAY 17 YEAR 82			
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>[Signature]</i>				DATE DELIVERED MONTH 3 DAY 17 YEAR 82			
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.							
Handling Method: 1. D81 2. 3. 4.							
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>				TITLE		DATE RECEIVED MONTH 3 DAY 17 YEAR 82	
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637							

DOCUMENT NO. 7302 - 11126

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PENCILS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 1112

1 PART A-

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 3 8 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3 8 82
Transporter HWT ID No. 129 IN 29012	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>	DATE RECEIVED MONTH DAY YEAR 3/8/82	

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR 3/8/82
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 1112

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302 - 08775

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Rb 11	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 3 1 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3 1 82
Transporter HWT ID No. 124	STATE 111	NUMBER 2892R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. R...</i>
			DATE RECEIVED MONTH DAY YEAR 3 1 82

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard R. R...</i>	DATE DELIVERED MONTH DAY YEAR 3 1 82
Transporter No. 2 HWT ID No. 124	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	
DATE DELIVERED MONTH DAY YEAR	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methc

1	D 871
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED
MONTH DAY YEAR
3-1-82

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0877

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302

28

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Meyer</i>	TITLE <i>Plant Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 2 22 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2 22 82
Transporter HWT ID 129	STATE IN	NUMBER 2904R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Touch</i>
			DATE RECEIVED MONTH DAY YEAR 2/22/82

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Touch</i>	DATE DELIVERED MONTH DAY YEAR 2/22/82
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Wm. Boyd</i>	DATE DELIVERED MONTH DAY YEAR 2-22-82
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1 <i>DB</i> 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Wm. Boyd</i>	DATE RECEIVED MONTH DAY YEAR 2-22-82
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637	

DOCUMENT NO. 7302

-1112

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0877

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 ROLL	T	K08
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>Steve Huggs</i>	<i>Asst. Clerk</i>	2 15 82	2 15 82
Transporter HWT ID No. 124	STATE IN	NUMBER 2993 R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. R...</i>
			DATE RECEIVED MONTH DAY YEAR 2 15 82

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
<i>Richard R. R...</i>	2 15 82
Transporter No. 2 HWT ID No. 124	STATE IN
NUMBER 2993 R	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	
DATE RECEIVED MONTH DAY YEAR	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth.

1	081
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION	TITLE	DATE RECEIVED MONTH DAY YEAR
<i>Donna Boyd</i>	2-15-82	Feb

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0877

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 ROLL	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Naps</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 2 8 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2 8 82
Transporter HWT ID No. 129 EW 29045	STATE IN	NUMBER 29045	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Trench</i>
			DATE RECEIVED MONTH DAY YEAR 2/3/82

TEAR AT THIS PERFORATION

1 PART B	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Trench</i>	DATE DELIVERED MONTH DAY YEAR 2/3/82
Transporter No. 2 HWT ID No.	STATE IN	NUMBER 29045
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED MONTH DAY YEAR 2/3/82
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR 2/3/82

TO BE FILLED OUT BY TRANSPORTER

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methc

1	D-2
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED
MONTH DAY YEAR
2 - 8 - 82

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0877

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302 - 08777

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.c.s.	HAZAR. ORM-E	NA9189					X 3000	X				1 Roll	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Napp</i>		TITLE <i>Supt. Clark</i>		DATE TO BE SHIPPED MONTH DAY YEAR 2 4 82		EXPECTED ARRIVAL DATE MONTH DAY YEAR 2 4 82	
Transporter HWT ID No. <i>121</i>	STATE <i>IN</i>	NUMBER <i>9893R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. R...</i>			DATE RECEIVED MONTH DAY YEAR 2 4 82	

YEAR OF FIRST SHIPMENT
YEAR AT THIS PERFORMANCE

1 PART B		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard R. R...</i>		DATE DELIVERED MONTH DAY YEAR 2 4 82	
Transporter No. 2 HWT ID No. <i>121</i>	STATE <i>IN</i>	NUMBER <i>9893R</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R. R...</i>		DATE RECEIVED MONTH DAY YEAR 2 4 82
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard R. R...</i>			DATE DELIVERED MONTH DAY YEAR 2 4 82		

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.			Handling Method 1 <i>D81</i> 2 3 4	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>		TITLE		DATE RECEIVED MONTH DAY YEAR 2 - 7 - 82

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 08777

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08771

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	K08
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagz</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>2-1-82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>2-1-82</i>
Transporter HWT ID No. <i>24 IN 2692R</i>	STATE <i>IN</i>	NUMBER <i>2692R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>
			DATE RECEIVED MONTH DAY YEAR <i>2 1 82</i>

TEAR AT THIS PERFORATION
TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard Roach</i>	DATE DELIVERED MONTH DAY YEAR <i>2 1 82</i>
Transporter No. 2 HWT ID No. <i>24 IN 2692R</i>	DATE RECEIVED MONTH DAY YEAR <i>2 1 82</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Brian Boyd</i>	DATE DELIVERED MONTH DAY YEAR <i>2 1 82</i>

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1 D81

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE	DATE RECEIVED MONTH DAY YEAR <i>2-1-82</i>
--	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0877

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189					X 3000	X				1 ROL	T	KO87
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>1/28/82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>1/28/82</i>
Transporter HWT ID No. <i>129 IN 2697R</i>	STATE <i>IN</i>	NUMBER <i>2697R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>
			DATE RECEIVED MONTH DAY YEAR <i>1/28/82</i>

YEAR AT THIS PERFORATION

1 PART B

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR <i>1/28/82</i>
Transporter No. 2 HWT ID No. <input type="checkbox"/>	STATE <input type="checkbox"/>
NUMBER <input type="checkbox"/>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
DATE RECEIVED MONTH DAY YEAR <input type="checkbox"/>	
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR <input type="checkbox"/>

TO BE FILLED OUT BY TSD FACILITY

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1 <i>D-81</i> 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>1-28-82</i>
DATE RECEIVED MONTH DAY YEAR <i>1/28/82</i>	
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637	

DOCUMENT NO.

7302 - 08769

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	OPA-E	NA9189				X	3,770	X				1 RoL	T	F006
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment as a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Waste Water Operator</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 2 DAY 18 YEAR 82	EXPECTED ARRIVAL DATE MONTH 2 DAY 18 YEAR 82
IMPORTER STATE IN NO. 1377 NUMBER 26014	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James</i>	DATE RECEIVED MONTH 2 DAY 18 YEAR 82	

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	OPA-E	NA9189				X	3,773	X				1 RoL	T	F006
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment as a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

REFERENCE 0895

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	094-E	NA9129				X	3770	X				1 Rd	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
J. R. W. [Signature]	Owner	1/16/82	1/16/82
Transporter HWI ID No. 121	STATE IN	NUMBER 1793K	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT [Signature]
			DATE RECEIVED MONTH DAY YEAR 2/16/82

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 0895

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	094-E	NA9129				X	3770	X				1 Rd	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 118

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JUL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	RoL	T	F000
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

CENTRAL WASTE TREATMENT PLANT

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE JUL Steel Corp.	TITLE JUL Steel Corp.	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
TRANSPORTER HWI ID No. 12411129924	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT Michael R. Roush	DATE RECEIVED MONTH DAY YEAR	3 13 8

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0895

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JUL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3533	X				1	RoL	T	F000
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

CENTRAL WASTE TREATMENT PLANT

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

08903

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND05462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189			X		5770	X				1 RAL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Dennis R. W. [Signature]	TITLE 1741 Waste Water Oper	DATE TO BE SHIPPED 2/11/82	EXPECTED ARRIVAL DATE 2/11/82
TRANSPORTER HWT ID No. 129	STATE IN	NUMBER 2904R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT John [Signature]

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08904

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND05462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189			X		3333	X				1 RAL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 120

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3333	X				1	Ro	T	FOC
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>John R. ...</i>	Waste Water Oper	1/30/82	1/30/82
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
IND No. 124	IN	2697R	1/30/82

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 088

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3770	X				1	Ro	T	FO
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08845

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

Page 121

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-F	NA9189				X	3770					1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John J. ...</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 1 DAY 27 YEAR 82	EXPECTED ARRIVAL DATE MONTH 1 DAY 27 YEAR 82
Transporter's HWT ID No. 0129	STATE IN	NUMBER 249	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John J. ...</i>
		DATE RECEIVED MONTH 1 DAY 27 YEAR 82	

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306 - 08846

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-F	NA9189				X	3333					1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7302 - 08761

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	INDO05462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	INDO44250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	INDO77005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagel</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 1 25 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 1 25 82
Transporter HWT ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Trench</i>
			DATE RECEIVED MONTH DAY YEAR 1/25/82

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Trench</i>	DATE DELIVERED MONTH DAY YEAR 1/25/82
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR 1/25/82
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE DELIVERED MONTH DAY YEAR
TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth.

1	P-2
2	
3	
4	75

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION
Bruce Boyd

TITLE

1-25-82

DATE RECEIVED
MONTH DAY YEAR
1-25-82

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 08761

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 123

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,333	X				1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert B. Leslie</i>	TITLE <i>Transporter</i>	DATE TO BE SHIPPED MONTH <i>10</i> DAY <i>20</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>10</i> DAY <i>20</i> YEAR <i>81</i>
Transporter HWT ID No. <i>1347</i>	STATE <i>IN</i>	NUMBER <i>010031</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
DATE RECEIVED MONTH <i>10</i> DAY <i>20</i> YEAR <i>81</i>			

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

0884

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,333	X				1	Rel	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 088
REFERENCE 80

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044258
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	1770	X						
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Robert D. Lender	Manager	1-23-82	1-23-82
Transporter HWT ID No. 157	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 088

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044258587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	5334	X						
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 125

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7856	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189	X				3770	X				1	ROL	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE Material Manager	DATE TO BE SHIPPED MONTH DAY YEAR 1 18 91	EXPECTED ARRIVAL DATE MONTH DAY YEAR 1 18 91
Transporter HWHT ID No. 134	STATE IN	NUMBER 71838	TRANSPORTER NO. SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James H. Hines</i>
		DATE RECEIVED MONTH DAY YEAR 1 18 91	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7305

0884

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	ROL	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

HAZARDOUS WASTE MANIFEST

7306 - 0880
REFERENCE 80
 DOCUMENT NO. 7306 - 0880
 EPA I.D. NO.

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	CONTAINERS TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *George P. Smith* TITLE: *Waste Coordinator* DATE TO BE SHIPPED: *1/16/82* EXPECTED ARRIVAL DATE: *1/16/82*

Transporter HWT ID No. *129* STATE: *IN* NUMBER: *26472* TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *John K. Smith* DATE RECEIVED: *1/16/82*

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST 7306 - 0880
 DOCUMENT NO. 7306 - 0880

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	CONTAINERS TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X		X						T	F00
2. (Central Waste Treatment Plant Sludge)	(12)														
3.							333					1	ROL		
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: _____ TITLE: _____ DATE TO BE SHIPPED: _____ EXPECTED ARRIVAL DATE: _____

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08804

REFERENCE 80
Page 127

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	3,770	X				1 RoL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 1 DAY 13 YEAR 82	EXPECTED ARRIVAL DATE MONTH 1 DAY 13 YEAR 82
TRANSPORTER ID No. 119	STATE IN	NUMBER 26855	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
		DATE RECEIVED MONTH 1 DAY 13 YEAR 82	

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08805

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189				X	3383	X				1 RoL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

3 PART A

REFERENCE 80100

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2654	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X					1	R-L	T	FOI
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Jones & Laughlin</i>	TITLE <i>Manager</i>	DATE TO BE SHIPPED MONTH <i>11</i> DAY <i>14</i> YEAR <i>82</i>	EXPECTED ARRIVAL DATE MONTH <i>11</i> DAY <i>14</i> YEAR <i>82</i>
TRANSPORTER HWT ID No. <i>25</i>	STATE <i>IN</i>	NUMBER <i>41714</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH <i>11</i> DAY <i>14</i> YEAR <i>82</i>

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

088

3 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2654	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X					1	R-L	T	FOI
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>[Title]</i>	DATE TO BE SHIPPED MONTH <i>11</i> DAY <i>14</i> YEAR <i>82</i>	EXPECTED ARRIVAL DATE MONTH <i>11</i> DAY <i>14</i> YEAR <i>82</i>
---	-------------------------	--	---

TO BE FILLED OUT BY GENERATOR

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 00745

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.			TYPE
Hazardous waste, solid, M.O.S.	ORM-E	NA9189				X	3,770	X				1	ROL	T	P006
(Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *WASTE WATER OPERATOR* DATE TO BE SHIPPED: *7/9/82* EXPECTED ARRIVAL DATE: *7/9/82*

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: *7/9/82*

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08801

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.			TYPE
Hazardous waste, solid, M.O.S.	ORM-E	NA9189				X	3,770	X				1	ROL	T	P006
(Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

REFERENCE 80

Page 130

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3776	X				1 RLT		FO
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George Perryman</i>	TITLE Waste Water Oper	DATE TO BE SHIPPED MONTH DAY YEAR 1/10/82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 1/10/82
TRANSPORTER FWT ID No. 129	STATE IN	NUMBER 26978	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Smith</i>
			DATE RECEIVED MONTH DAY YEAR 1/10/82

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 088

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3736	X				1 RLT		FO
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08767

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	KO87
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling instructions including Container Exemption (i.e. Identification of Additional Wastes included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Page</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 1 7 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 1 7 82
TRANSPORTER HWT ID No. 134 EN 2485 K	STATE IN	NUMBER 2485 K	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Lamar Thomas</i>
DATE RECEIVED MONTH DAY YEAR 1 7 82			

TEAR AT THIS PERFORATION

1 PART B

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Lamar Thomas</i>		DATE DELIVERED MONTH DAY YEAR 1 7 82
Transporter No. 2 HWT ID No.	STATE IN	NUMBER 2485 K
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE RECEIVED MONTH DAY YEAR 1 7 82
		DATE DELIVERED MONTH DAY YEAR

TO BE FILLED OUT BY TSD FACILITY

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.		Handling Metho 1 D81 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>1-7-82</i>	DATE RECEIVED MONTH DAY YEAR 1 7 82
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		DOCUMENT NO. 7302 - 08767

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7305

REFERENCE 80
Page 132

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	E W T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X		X						
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE <i>Manager</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>12 1 77</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>12 1 77</i>
TRANSPORTER HWY ID No. <i>17 77 2 485 A</i>	STATE <i>IN</i>	NUMBER <i>1</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT <i>Robert O. Leslie</i>
DATE RECEIVED MONTH DAY YEAR <i>12 1 77</i>			

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	E W T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,335	X				1	Rel	
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 08741
Page 133

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.											
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005452601											
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587											
TRANSPORTER NO. 2 (IF ANY)																			
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916											
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE																			
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>																			
PROPER US DOT SHIPPING NAME		US DOT HAZARD CLASS		UN NUMBER		FORM		QUANTITY		UNITS		CONTAINERS		EPA HAZ CODE		EPA WASTE TYPE			
1. Hazardous waste, solid, H.O.S.		ORM-E		NA9189		X		3270		X		1		ROL		T F006			
2. (Central Waste Treatment Plant Sludge)		(12)																	
3.																			
4.																			
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)																			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.																			
GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		YEAR		MONTH		DAY		EXPECTED ARRIVAL DATE		YEAR		MONTH		DAY	
H. J. P. P. P.		Waste W. W. W.		1		1982		1		4		8		1		4		8	
TRANSPORTER		STATE		NUMBER		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED		MONTH		DAY		YEAR		MONTH		DAY	
HWT-1		IN		3270		Robert J. J. J.		1		4		8		1		4		8	

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.									
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005452601									
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587									
TRANSPORTER NO. 2 (IF ANY)																	
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916									
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE																	
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>																	
PROPER US DOT SHIPPING NAME		US DOT HAZARD CLASS		UN NUMBER		FORM		QUANTITY		UNITS		CONTAINERS		EPA HAZ CODE		EPA WASTE TYPE	
1. Hazardous waste, solid, H.O.S.		ORM-E		NA9189		X		3333		X		1		ROL		T F006	
2. (Central Waste Treatment Plant Sludge)		(12)															
3.																	
4.																	
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)																	
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.																	

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302 - 08766

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	INDO05462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	INDO44250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	INDO77005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	2000	X				1 RCL	T	KO87
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Napp</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>1-4-82</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>1-4-82</i>
Transporter HWT ID No. <i>134</i>	STATE <i>IM</i>	NUMBER <i>21685R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
			DATE RECEIVED MONTH DAY YEAR <i>1-4-82</i>

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>	DATE DELIVERED MONTH DAY YEAR <i>1-4-82</i>
Transporter No. 2 HWT ID No. <i>134</i>	STATE <i>IM</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>	DATE RECEIVED MONTH DAY YEAR <i>1-4-82</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR <i>1-4-82</i>
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	
Handling Methc 1 <i>D81</i> 2 3 4	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>1-1-82</i>
DATE RECEIVED MONTH DAY YEAR <i>1-4-82</i>	

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 08766

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 08737

REFERENCE 80
Page 135

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	ROL	T	F006
(Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: Robert M. Leal
TITLE: Manager
DATE TO BE SHIPPED: MONTH 7 DAY 1 YEAR 89
DATE RECEIVED: MONTH 1 DAY 1 YEAR 89

Transporter HWT ID No. 27 IN 56958P

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 08738

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	ROL	T	F006
(Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE:

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE NO. 80 00

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE	
1. Hazardous waste, solid, n.o.s.	001-2	NA9189				X	3,770	X				1	Roll	T
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 3 DAY 82 YEAR 1	EXPECTED ARRIVAL MONTH 3 DAY 1 YEAR 3
TRANSPORTER HWT ID NO. 13 IN 37143	STATE IN NUMBER 37143	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 1 DAY 3 YEAR 3

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / J&L company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, N.O.S.	001-2	NA9189				X	3,333	X				1	Roll	T
2. (Central Waste Treatment Plant Sludge)	(0012)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 3 DAY 82 YEAR 1	EXPECTED ARRIVAL MONTH 3 DAY 1 YEAR 3
TRANSPORTER HWT ID NO. 13 IN 37143	STATE IN NUMBER 37143	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 1 DAY 3 YEAR 3

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302 - 08561

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2. (Tar decanter sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Huggs</i>	TITLE <i>Sent Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 31 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 31 81
TRANSPORTER HWT ID No. 124 1VV 269 ER	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>	DATE RECEIVED MONTH DAY YEAR 12 31 81

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard Roach</i>	DATE DELIVERED MONTH DAY YEAR 12 31 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methc

1 D81

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED

MONTH DAY YEAR
12 31 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 08561

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

REFERENCE 80
Page 138

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste, solid, n.o.s.	ORM-E	NA9189				X	3,770	X				1	RoL	T	FOO
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	MONTH 12 DAY 30 YEAR 87	MONTH 12 DAY 30 YEAR 87
TRANSPORTER HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
217	IN	2785	<i>[Signature]</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

08

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	I W. T	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,333	X				1	RoL	T	F
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 08733
REFERENCE 80733
Page 139

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS	NO.			TYPE
1. Hazardous waste, solid, N.O.S.	ORM-E	NA9189			X		3770					1	Roll	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
Robert O. Leslie	Customer Representative	7-29-87	7-29-87
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
Industrial Disposal Corp.	IN	6292R	7-29-87

Jones & Laughlin Steel Corporation / an LTV company

350 TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 08734

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS	NO.			TYPE
1. Hazardous waste, solid, N.O.S.	ORM-E	NA9189			X		3333					1	Roll	T	P006
2. (Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an I TV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08566

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3000	X				1 ROLL	T	K087
2. (Tar decanter sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 28 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 28 81
Transporter HWT ID No. 124	STATE IN	NUMBER 26925	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R...</i>
			DATE RECEIVED MONTH DAY YEAR 12 28 81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard R...</i>	DATE DELIVERED MONTH DAY YEAR 12 28 81
Transporter No. 2 HWT ID No. 124	DATE RECEIVED MONTH DAY YEAR 12 28 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE DELIVERED MONTH DAY YEAR 12 28 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Don B...</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 12 28 81
--	-------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 08566

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 141

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3990	X			1	26	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Water Oper.	DATE TO BE SHIPPED MONTH 12 DAY 22 YEAR 81	EXPECTED ARRIVAL DATE MONTH 12 DAY 22 YEAR 81
TRANSPORTER HWT. ID NO. 117 1A 2795A	STATE IN	NUMBER 2795A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH 12 DAY 22 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0873

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3333	X			1	26	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 - 08729
REFERENCE 80729

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3370	X				1	Roll	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John T. ...</i>	TITLE Waste Water Operator	DATE TO BE SHIPPED MONTH DAY YEAR 12 27 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 27 81
TRANSPORTER HWT ID No. 117 JIM 72 25 81	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. ...</i>	DATE RECEIVED MONTH DAY YEAR 12 27 81	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / and its company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08731

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3332	X				1	Roll	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08126

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. SPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid D.O.S.	ORM-E	NA9189				X	3333	X					1	Roll	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Water Area	DATE TO BE SHIPPED MONTH 12 DAY 25 YEAR 87	EXPECTED ARRIVAL DATE MONTH 12 DAY 25 YEAR 87
Transporter HWT ID No. 117	STATE IN	NUMBER 2183A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH 12 DAY 25 YEAR 87

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 0868

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp. TRANSPORTER NO. 1	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid D.O.S.	ORM-E	NA9189				X	3772	X					1	Roll	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7305 087
EPA I.D. NO.

3 PART A

REFERENCE 80
Page 144

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY				
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3,770	X				1 ROL	T	FC
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	12 25 81	12 25
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
<i>[Signature]</i>	12 35		

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7305 087
EPA I.D. NO.

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY				
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3,333	X				1 ROL	T	FC
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>		12 25 81	12 25

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3000	X				1 R-11	T	K087
2. (Tar decanter sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Vige</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 23 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 28 81
Transporter HWT ID No. 3471196832	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Tom Horn</i>	DATE RECEIVED MONTH DAY YEAR 12 24 81

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Tom Horn</i>	DATE DELIVERED MONTH DAY YEAR 12 24 81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1 D81 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Bruce Boyd</i>	TITLE DATE RECEIVED MONTH DAY YEAR 12 24 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0856

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08680

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM	QUANTITY	UNITS	CONTAINERS	EPA HAZ CODE	EPA WASTE TYPE
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189	SOLID	3333	TONS	1	RoZ	T R006
2. (Central Waste Treatment Plant Sludge)	(12)							
3.								

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: [Signature] TITLE: [Title] DATE TO BE SHIPPED: [Date] EXPECTED ARRIVAL DATE: [Date]

Transporter: [Signature] STATE: [State] NUMBER: [Number] TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: [Signature] DATE RECEIVED: [Date]

REFERENCE 80
Page 146

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08681

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM	QUANTITY	UNITS	CONTAINERS	EPA HAZ CODE	EPA WASTE TYPE
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189	SOLID	3333	TONS	1	RoZ	T R006
2. (Central Waste Treatment Plant Sludge)	(12)							
3.								
4.								

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

REFERENCE 80

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-391-2531	IND044250501
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WA TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189			X			X							FO
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O. Leslie	TITLE Manager	DATE TO BE SHIPPED MONTH DAY YEAR 12 23 81	EXPECTED ARRIVAL DATE MONTH DAY 12 23
TRANSPORTER HWT ID No. 34	STATE IN	NUMBER 7 1813 K	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT DATE RECEIVED MONTH DAY 12 23

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO.

7306

086

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-391-2531	IND044250501
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WA TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189			X		3333	X			1	25L		FI
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302

08564

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	3000	X				one Roll	T	K087
2 (Tar decanter sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>12 - 21 - 81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>12 - 21 - 81</i>
Transporter HWT ID No. <i>1342W 90813</i>	STATE <i>IN</i>	NUMBER <i>90813</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Jan Roma</i>
			DATE RECEIVED MONTH DAY YEAR <i>12 21 81</i>

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Jan Roma</i>			DATE DELIVERED MONTH DAY YEAR <i>12 21 81</i>
Transporter No. 2 HWT ID No. <i>1342W 90813</i>	STATE <i>IN</i>	NUMBER <i>90813</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Jan Roma</i>
			DATE RECEIVED MONTH DAY YEAR <i>12 21 81</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Jan Roma</i>			DATE DELIVERED MONTH DAY YEAR <i>12 21 81</i>
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.			Handling Method <i>D81</i>
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Bruce Boyd</i>			TITLE <i>Bruce Boyd</i>
			DATE RECEIVED MONTH DAY YEAR <i>12 - 21 - 81</i>

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

0856

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

Page 149

3 PART A

DOCUMENT NO. 7306

0867

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.			TYPE
1. Hazardous waste, solid U.S.	ORM-E	NA9189				X	3335	X				1	Ro	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>		TITLE Central Waste Corp.	DATE TO BE SHIPPED MONTH DAY YEAR 12/19/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12/19/81
Transporter HWT ID No. 129	STATE IN	NUMBER 20972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 12/19/81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

0867

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.			TYPE
1. Hazardous waste, solid U.S.	ORM-E	NA9189				X	3770	X				1	Ro	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306
EPA I.D. NO. 0867

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Road			219-391-2531	IND005462601
J&L Steel Corp.	East Chicago, IN 46312				
TRANSPORTER NO. 1	P.O. Box 59			219-397-2664	IND044250587
Industrial Disposal Corp.	East Chicago, IN 46312				
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056			219-944-7858	IND077005916
Gary Land Development	Gary, IN 46406				

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	SALLONS	CU YDS	POUNDS	TONS	SALLONS	CU YDS	POUNDS	TONS			
1 Hazardous waste, solid n.o.s.	ORM-E	NA9189			X		3770	X							1	ROL	T
2 (Central Waste Treatment Plant Sludge)	(12)																
3																	
4																	

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Manager	12/12/21	12/12/21
TRANSPORTER HWT	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
24	IN	21072	<i>[Signature]</i>

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306
EPA I.D. NO. 0867

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Road			219-391-2531	IND005462601
J&L Steel Corp.	East Chicago, IN 46312				
TRANSPORTER NO. 1	P.O. Box 59			219-397-2664	IND044250587
Industrial Disposal Corp.	East Chicago, IN 46312				
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056			219-944-7858	IND077005916
Gary Land Development	Gary, IN 46406				

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	SALLONS	CU YDS	POUNDS	TONS	SALLONS	CU YDS	POUNDS	TONS			
1 Hazardous waste, solid n.o.s.	ORM-E	NA9189			X		5533	X							1	ROL	T
2 (Central Waste Treatment Plant Sludge)	(12)																
3																	
4																	

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

REFERENCE 80
Page 151

3 PART A DOCUMENT NO. 08679

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189			X	37%	X				1	Re	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>[Signature]</i>	<i>[Title]</i>	12 21 81	12 21 81

Transporter HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
154	IN	2133	<i>[Signature]</i>	12 21 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

08679

3 PART A DOCUMENT NO. 08679

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189			X	9333	X				1	Re	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR

Transporter HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306
REFERENCE 80-152
 Page 152

3 PART A			
GENERATOR NAME	SITE ADDRESS		
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		
TRANSPORTER NO. 1	PHONE NO.		
Industrial Disposal Corp.	219-391-2531		
TRANSPORTER NO. 2 (IF ANY)	EPA I.D. NO.		
	IND044250587		
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406		
	219-944-7858		
	IND077005916a		

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous waste, solid, E.O.G.	ORM-E	NA9189				X	3333	X					1	ROL	T	7006
2. (Central Waste Treatment Plant Sludge)	(12)															
3.																
4.																

Special Handling Instructions including Container Exemption (i.e., identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>[Title]</i>	MONTH DAY YEAR	MONTH DAY YEAR
TRANSPORTER HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
126	IN	2948	<i>[Signature]</i>
			DATE RECEIVED
			MONTH DAY YEAR
			12 20 8

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 **086**

3 PART A			
GENERATOR NAME	SITE ADDRESS		
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		
TRANSPORTER NO. 1	PHONE NO.		
Industrial Disposal Corp.	219-391-2531		
TRANSPORTER NO. 2 (IF ANY)	EPA I.D. NO.		
	IND044250587		
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406		
	219-944-7858		
	IND077005916		

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		3333	X				1 PL	T	700
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														

Special Handling Instructions including Container Exemption (i.e., identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302

08421

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916
Gary Land Development			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 ROLL		K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE	DATE TO BE SHIPPED			EXPECTED ARRIVAL DATE		
			MONTH	DAY	YEAR	MONTH	DAY	YEAR
<i>Steve Nagy</i>		<i>Supt. Clerk</i>	12	17	81	12	17	81
Transporter HWT ID No.	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT				DATE RECEIVED		
129	IN 26972	<i>John Kouch</i>				12/17/81		

YEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT						DATE DELIVERED			
						MONTH	DAY	YEAR	
<i>John Kouch</i>						12	17	81	
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT						DATE RECEIVED			
						MONTH	DAY	YEAR	
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT						DATE DELIVERED			
						MONTH	DAY	YEAR	
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.								Handling Method	
								1. D-21	
								2.	
								3.	
								4.	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION						TITLE			
<i>Brian Boyd</i>									
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637						DOCUMENT NO. 7302 - 08421			

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08668

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Generator Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2331	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Treatment, Storage or Disposal Facility Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-R (12)	NA9189				X	3,770					1	Pol T	FC06

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *Waste Water Operator* TITLE: *WASTE WATER OPERATOR* DATE TO BE SHIPPED: 12/16/81 EXPECTED ARRIVAL DATE: 12/16/81

TRANSPORTER'S SIGNATURE: *Robert Uode* TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: DATE RECEIVED: 12/16/81

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08667

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Generator Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN	219-397-2664	IND044250587
Treatment, Storage or Disposal Facility Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s. (Central Waste Treatment Plant Sludge)	ORM-R (12)	NA9189				X	3,334					1	Pol T	FC06
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment or a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen. — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306 - 08669

3 PART A

REFERENCE 80

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00542501
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1 Ro	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Manager	12/16/81	12/16/81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	MONTH	YEAR
<i>[Signature]</i>	12/16/81		

Transporter HWT ID No.	STATE	NUMBER
124	IN	2097K

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen. — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306 - 0867

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462501
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1 Ro	T	006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRES. HARD

Jones & Laughlin Steel Corporation / an LTV company

REFERENCE 80

HAZARDOUS WASTE MANIFEST

7302

Page 156
08325

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR SL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189					3000	X				1 Roll	T	K087
2. Tar Decanter Sludge														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 14 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 14 81
Transporter HWT ID No. 124 IN 2692R	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>	DATE RECEIVED MONTH DAY YEAR 12 14 81

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard Roach</i>	DATE DELIVERED MONTH DAY YEAR 12 14 81
Transporter No. 2 HWT ID No. 124 IN 2692R	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons And Disposition of Rejected Materials.	Handling Method 1 D81 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Bayel</i>	TITLE DATE RECEIVED MONTH DAY YEAR 12 14 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

7302 - 08325
DOCUMENT NO.

TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 157

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid H.O.S.	ORM-E	NA9189				X	3,333	X				1	2-L	T	7606
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>[Signature]</i>	<i>[Title]</i>	12 14 88	12 14 88
TRANSPORTER HWT ID No.	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
219 12 26 92	8	<i>[Signature]</i>	12 14 88

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08661

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid H.O.S.	ORM-E	NA9189				X	3,770	X				1	Ro	I	7606
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Use TYPE or PRINT clearly, using
ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

08586

3 PART A

DOCUMENT NO. 7306
PHONE NO. 219-391-2531
EPA I.D. NO. IND0044250587
Page 158

GENERATOR NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND0044250587
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND0044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s. (Central waste treatment plant sludge)	ORM-E (12)	NA9189				X	3333	X				1	ROL	F006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility, can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>W.W. O'Brien</i>	12/13/72	12/13/72
TRANSPORTER'S SIGNATURE	TITLE	DATE RECEIVED	
<i>[Signature]</i>	<i>[Signature]</i>	12/13/72	

HAZARDOUS WASTE MANIFEST

7306

08587

3 PART A

DOCUMENT NO. 7306

GENERATOR NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND0044250587
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND0044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s. (Central waste treatment plant sludge)	ORM-E (12)	NA9189				X	3770	X				1	ROL	F006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility, can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 159

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, h.o.s.	ORM-E	HA9189				X	3333	X				1	2	T	P006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE V.P. Sales	DATE TO BE SHIPPED MONTH DAY YEAR 11 11 71	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 11 71
Transporter HWT ID No. 7306	STATE IN	NUMBER 976377	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH DAY YEAR 11 11 71

Jones & Laughlin Steel Corporation / an L.P. company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

08583

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid h.o.s.	ORM-E	HA9189				X	3770	X				1	Ro	T	P006
2. (Central waste treatment plant sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7305 - 0858
EPA I.D. NO. 160

3 PART A			
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2331	IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE
This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9109				X	3,333	X				1 Ro	T	F00
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Greg Mitchell</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 12 DAY 12 YEAR 81	EXPECTED ARRIVAL DATE MONTH 12 DAY 12 YEAR 81
TRANSPORTER'S SIGNATURE <i>John Z...</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH 12 DAY 12 YEAR 81	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7305 - 0858

3 PART A			
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2331	IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE
This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	2706	X				1 Ro	T	06
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 161

3 PART A		DOCUMENT NO. 7306		
GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ. CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.c.	ORM-E	NA3189				X	377	X						T	FC06
Central waste treatment plant sludge	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
		MONTH DAY YEAR	MONTH DAY YEAR
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
	MONTH DAY YEAR		

Jones & Laughlin Steel Corporation / an LTV company

TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08579

3 PART A		DOCUMENT NO. 7306		
GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ. CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.c.	ORM-E	NA3189				X		X						T	FC06
Central waste treatment plant sludge	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE

TITLE

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

7306 085
REFERENCE 80

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WAS TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CY YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	377g	X				1	Pol	T	20
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No.	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

7306 085
DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WAS TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CY YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	377g	X				1	Pol	T	20
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
DOCUMENT NO. 7302 08323
Page 163
EPA ID NO.

1 PART A		DOCUMENT NO. 7302 08323	
NAME	SITE ADDRESS	PHONE NO.	EPA ID NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189				X	3000	X				1 Roll	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nuzz</i>	TITLE <i>Sent. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 7 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 7 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R...</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>...</i>	DATE RECEIVED MONTH DAY YEAR 12 7 81	
TRANSPORTER NO. 1 HWT ID No. 1241 N 26928	STATE NUMBER 1241 N 26928		

1 PART B		TEAR AT THIS PERFORATION	
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR 12 7 81	
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE RECEIVED MONTH DAY YEAR 12 7 81	
TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons and Disposition of Rejected Materials.		Handling Method 1 D81 2 3 4	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Jack Br...</i>		DATE RECEIVED MONTH DAY YEAR 12 7 81	
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637			
DOCUMENT NO. 7302 - 08323			

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
PORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,770	X				1 Rgt		F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Aug. M. M... ..</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH DAY YEAR 12 7 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 7 81
Transporter HWT ID No. 600	STATE IN	NUMBER JAN 26 81	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard P.</i>
		DATE RECEIVED MONTH DAY YEAR 12 7 81	

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
PORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X		X					2	F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

08

3 PART A

REFERENCE 80 08
DOCUMENT NO. 7306
EPA I.D. NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	I.W. T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-Z	NA9189				X		X						T	1
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE N.W. OPERATOR	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL MONTH DAY
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION <i>[Signature]</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION <i>[Signature]</i>	DATE RECEIVED MONTH DAY	

TRANSPORTER NO. 1 HWT ID No. 12128 2483	TRANSPORTER NO. 2 HWT ID No. 12128 2483
--	--

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306
EPA I.D. NO. 08

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	I.W. T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,770	X				1	Roll		
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION <i>[Signature]</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION <i>[Signature]</i>	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL MONTH DAY
---	---	--------------------------------------	-------------------------------

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
1. Hazardous waste, solid, U.S.	ORM-E	NA9189				X	3770	X			1	R/T	F006
2. (Central waste treatment plant sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *Waste Manager* DATE TO BE SHIPPED: 12/4/21
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: 12/4/21

Jones & Laughlin Steel Corporation / an I.T.V. company
HAZARDOUS WASTE MANIFEST
DOCUMENT NO. 7306 08571

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
1. Hazardous waste, solid, U.S.	ORM-E	NA9189				X	3,333	X			1	R/T	F006
2. (Central waste treatment plant sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

REFERENCE 80
Page 167

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250501
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development P.O. Box 6056 Gary, IN 46406			
219-944-7858 IND077005916			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WA- TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-X	NA9189				X	3776	X				1	Roll	TD
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leach</i>	TITLE <i>Waste Management</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>12 16 81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>12 16 81</i>
Transporter HWT ID No. <i>126</i>	STATE <i>IN</i>	NUMBER <i>24732</i>	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Robert Wade</i>

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

7306

08

3 PART A

DOCUMENT NO.

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250501
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development P.O. Box 6056 Gary, IN 46406			
219-944-7858 IND077005916			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WA- TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-X	NA9189				X	3333	X				1	Roll	TD
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leach</i>	TITLE <i>Waste Management</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>12 16 81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>12 16 81</i>
Transporter HWT ID No. <i>126</i>	STATE <i>IN</i>	NUMBER <i>24732</i>	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Robert Wade</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08324

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189				X	3000	X				1 R.L.	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (ER)</i>	TITLE <i>Super's Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 3 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 3 81
TRANSPORTER HWT ID No. 129 E R 269 7 R	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John T. ...</i>	DATE RECEIVED MONTH DAY YEAR 12/3/81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John T. ...</i>	DATE DELIVERED MONTH DAY YEAR 12/3/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	DATE DELIVERED MONTH DAY YEAR
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYO</i>	DATE RECEIVED MONTH DAY YEAR 12-3-81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637	

DOCUMENT NO. 7302 - 08324

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 169

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-E	HA9189				X	3770	X				1	601	T	P006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
	WASTE WATER OPER	MONTH DAY YEAR 12 3 87	MONTH DAY YEAR 12 3 87
Transporter's HWI ID No. 117 IN 277156	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	
		MONTH DAY YEAR 12 3 87	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

0855

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, H.O.S.	ORM-E	HA9189				X	3363	X				1	601	T	P006
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

ease TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

08552

3 PART A

REFERENCE NO. 170

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
U.S. Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
INDUSTRIAL DISPOSAL CORP.	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056	Gary, IN 46406	219-844-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid P.O.S. (Central waste treatment plant sludge)	ORM-E (12)	NA9189				X	2700					1 Rpt		P006

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WINTER OPER	12/1/81	12/1/81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	STATE	NUMBER	DATE RECEIVED
<i>[Signature]</i>	IN	277858	12/1/81

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

08569

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
U.S. Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
INDUSTRIAL DISPOSAL CORP.	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056	Gary, IN 46406	219-844-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid P.O.S. (Central waste treatment plant sludge)	ORM-E (12)	NA9189				X	3,333					1 Rpt		P006

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7302 - 03199

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1, 21	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (EP)</i>		TITLE <i>Superior Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 11 30 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 30 81
TRANSPORTER HWT ID No. 129	STATE IN	NUMBER 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Konek</i>	DATE RECEIVED MONTH DAY YEAR 11/30/81

1 PART B

TEAR AT THIS PERFORATION

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Konek</i>			DATE DELIVERED MONTH DAY YEAR 11/30/81
TRANSPORTER No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE RECEIVED MONTH DAY YEAR

TO BE FILLED OUT BY TSD FACILITY

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.			Handling Meth. 1. <i>D.B.</i> 2. 3. 4.
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>KEITH BOYD</i>		TITLE	DATE RECEIVED MONTH DAY YEAR 11-30-81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0319

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				21	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (EP)</i>	TITLE <i>Supt's Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 11 30 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 30 81
TRANSPORTER HWT ID No. 129	STATE IN	NUMBER 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Konec</i>
			DATE RECEIVED MONTH DAY YEAR 11/30/81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Konec</i>	DATE DELIVERED MONTH DAY YEAR 11/30/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR 11/30/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR 11/30/81
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Methc 1 <i>D.B.</i> 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>KEVIN BOYD</i>	TITLE <i>KEVIN BOYD</i>
DATE RECEIVED MONTH DAY YEAR 11-30-81	

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 03199

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				11 ROL	T	F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPER	DATE TO BE SHIPPED MONTH 11 DAY 22 YEAR 81	EXPECTED ARRIVAL DATE MONTH 11 DAY 28 YEAR 81
TRANSPORTER'S SIGNATURE <i>[Signature]</i>	TITLE J. Martinez	DATE RECEIVED MONTH 11 DAY 28 YEAR 81	

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				11 ROL	T	F006
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 085!
Page 174

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	ISI Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-R	NA9189				x	3,333					1	RoL	T	F00
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Water Oper	11/29/81	11/29/81
TRANSPORTER'S SIGNATURE	STATE	NUMBER	DATE RECEIVED
<i>[Signature]</i>	IN	278512	11/29/81

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / acm TV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 085!

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	ISI Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-R	NA9189				x	3,770					1	RoL	T	F00
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 175

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid H.O.S.	ORM-R	NA9189				X	3333	X				1, 100		FOO
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Water Oper.	DATE TO BE SHIPPED MONTH 11 DAY 25 YEAR 87	EXPECTED ARRIVAL DATE MONTH 11 DAY 25 YEAR 87
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 11 DAY 25 YEAR 87		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0854

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous waste, solid H.O.S.	ORM-R	NA9189				X	3550	X				1, 100		FOO
2. (Central waste treatment plant sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Base TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 08543
REFERENCE 8013
Page 176

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid n.o.s. (Central waste treatment plant sludge)	ORM-E (12)	NA9189				X	2533	X				1	Roll	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	OPER	11-24-81	11-24-81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	MONTH	DAY
<i>[Signature]</i>	11-24-81	11	24

HAZARDOUS WASTE MANIFEST

Base TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

7306 08544
DOCUMENT NO.

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s. (Central waste treatment plant sludge)	ORM-E (12)	NA9189				X	3172	X				1	Roll	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>		11-24-81	11-24-81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	MONTH	DAY
<i>[Signature]</i>	11-24-81	11	24

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 177
7302 - 08322

DOCUMENT NO.

7302

08322

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189					X 3000	X			1 ROLL		T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nye</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 11 23 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 23 81
Transporter HWT ID No. 124 IN 2692R	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>	DATE RECEIVED MONTH DAY YEAR 11 23 81

1 PART B

TEAR AT THIS PERFORATION

TO BE FILLED OUT BY TSD FACILITY	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard Roach</i>	DATE DELIVERED MONTH DAY YEAR 11 23 81	
	Transporter No. 2 HWT ID No. 1 IN 2692R	DATE RECEIVED MONTH DAY YEAR 11 23 81	
	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE DELIVERED MONTH DAY YEAR	
	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR	
TO BE FILLED OUT BY TSD FACILITY	Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.		Handling Meth 1 D81 2 3 4
	TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYD</i>		
	TITLE <i>BRIAN BOYD</i>		
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637			DATE RECEIVED MONTH DAY YEAR 11 23 81

DOCUMENT NO. 7302

- 0832

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3333	X				1	Ro/	T	P005
2. (Central waste treatment plant sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>[Signature]</i>	<i>Warehouse Operator</i>	11-23-81	11-23-81

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
<i>[Signature]</i>	11-23-81

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08542

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY y Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3777	X				1	Ro/	T	P006
2. (Central waste treatment plant sludge)	(12)														
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 08539

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CUBIC YDS	POUNDS	TONS	GALLONS	CUBIC YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	5393	X							1	2.2	T	F006
2. (Central waste treatment plant sludge)	(12)																	
3.																		
4.																		

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>[Title]</i>	MONTH DAY YEAR	MONTH DAY YEAR
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
IND ID No. 12117439	IN	12117439	<i>[Signature]</i>
			DATE RECEIVED
			MONTH DAY YEAR
			11 21 21

lease TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 08540

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CUBIC YDS	POUNDS	TONS	GALLONS	CUBIC YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X							1	2.2	T	F006
2. (Central waste treatment plant sludge)	(12)																	

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>[Title]</i>	MONTH DAY YEAR	MONTH DAY YEAR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 180

3 PART A		DOCUMENT NO. 7306	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.
1. Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531
	P.O. Box 59	East Chicago, IN 46312	219-397-2664
TRANSPORTER NO. 2 (IF ANY)	Industrial Disposal Corp.		
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858
EPA I.D. NO.			
IND005462601		IND044250587	
IND077005916			
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>			
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM
1. Hazardous waste, solid	ORM-E	NA9182	SOLID LIQUID GAS SLUDGE
2. (Central waste treatment plant sludge)	(12)		
3.			
4.			
QUANTITY			
GALLONS CU YDS POUNDS TONS			
CONTAINERS NO. TYPE			
EPA HAZ CODE			
EPA WASTE TYPE			
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.			
GENERATOR'S SIGNATURE		TITLE	DATE TO BE SHIPPED
[Signature]		[Title]	MONTH DAY YEAR
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED	
[Signature]		MONTH DAY YEAR	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

0853

2 PART A		DOCUMENT NO. 7306	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.
1. Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531
	P.O. Box 59	East Chicago, IN 46312	219-397-2664
TRANSPORTER NO. 2 (IF ANY)	Industrial Disposal Corp.		
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858
EPA I.D. NO.			
IND005462601		IND044250587	
IND077005916			
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>			
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM
1. Hazardous waste, solid	ORM-E	NA9182	SOLID LIQUID GAS SLUDGE
2. (Central waste treatment plant sludge)	(12)		
3.			
QUANTITY			
GALLONS CU YDS POUNDS TONS			
CONTAINERS NO. TYPE			
EPA HAZ CODE			
EPA WASTE TYPE			
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.			
GENERATOR'S SIGNATURE		TITLE	DATE TO BE SHIPPED
[Signature]		[Title]	MONTH DAY YEAR
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED	
[Signature]		MONTH DAY YEAR	

base TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 08537
EPA I.D. NO. 7306
Page 181

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid H.O.S.	ORM-K	NA9189				X	3333	X				1	20	T	R006
(Central waste treatment plant sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPER.	11/20/81	11/20/81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
<i>[Signature]</i>	11/20/81		

Please TYPE or PRINT clearly, using ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306
08538

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid H.O.S.	ORM-E	NA9189				X	3777	X				1	20	T	R006
(Central waste treatment plant sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>			

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 182

3 PART A		DOCUMENT NO. 7306	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.
EL Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59	219-397-2664
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	219-944-7858
		Gary, IN 46406	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
1. Hazardous Waste, solid, H.O.S.	ORM-E	NA9189			X		3,770				1	ROL	T
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	11/18/81	11/18/81
TRANSPORTER SIGNATURE	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	
<i>[Signature]</i>	<i>[Signature]</i>	11/18/81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0849

3 PART A		DOCUMENT NO. 7306	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59	219-397-2664
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	219-944-7858
		Gary, IN 46406	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
1. Hazardous Waste, solid, H.O.S.	ORM-E	NA9189			X		3,333				1	ROL	T
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED
<i>[Signature]</i>		

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 0849

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,770	X				1	Roll		FO06
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	11 17 81	11 17 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	MONTH	DAY
<i>[Signature]</i>	11 17 81		

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 0849

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3,333	X				1	Roll		FO06
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
		MONTH DAY YEAR	MONTH DAY YEAR

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 03198

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3,000	X				1 TRK	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>S. Nagay</i>	TITLE <i>Deputy Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 11 16 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 16 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Tom Horn</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Tom Horn</i>	DATE RECEIVED MONTH DAY YEAR 11 16 81	DATE RECEIVED MONTH DAY YEAR 11 16 81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Tom Horn</i>	DATE DELIVERED MONTH DAY YEAR 11 16 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Tom Horn</i>	DATE RECEIVED MONTH DAY YEAR 11 16 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1	D 81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED
MONTH DAY YEAR
11 16 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

03198

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 185

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3770	X				1 ROL T		P006
2. (Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE W.W. ORRISON	DATE TO BE SHIPPED MONTH 11 DAY 15 YEAR 81	EXPECTED ARRIVAL DATE MONTH 11 DAY 15 YEAR 81
TRANSPORTER'S SIGNATURE <i>[Signature]</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 11 DAY 15 YEAR 81	

HAZARDOUS WASTE MANIFEST

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3333	X				1 ROL T		P006
(Central Waste Treatment Plant Sludge)	(12)													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306
EPA I.D. NO. 084

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Generator J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054626
Transporter No. 1 (if any) Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425053
Treatment, Storage or Disposal Facility Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		2770	X			1 RCL	T	FOO
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>M. Pater</i>	TITLE Vice President	DATE TO BE SHIPPED 11/13/81	EXPECTED ARRIVAL DATE 11/13/81
Transporter HWT ID No. 24	STATE IN	NUMBER 16972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306
EPA I.D. NO. 084

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Generator J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Transporter No. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Treatment, Storage or Disposal Facility Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189			X		2433	X			1 RCL	T	FOO
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7302

REFERENCE 80

Page 187

DOCUMENT NO. 08325

1 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189					3000	X				1 ROLL	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 14 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 14 81
TRANSPORTER HWI ID No. 124 IN 2692R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard R...</i>	DATE RECEIVED MONTH DAY YEAR 12 14 81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08324

1 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189					3000	X				1 ROLL	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08323
REFERENCE 80
Page 188

NAME		SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE.

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189				X	3000	X				1 ROLL	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>Steve Page</i>	<i>Sent. Clerk</i>	12 7 81	12 7 81

TRANSPORTER	STATE	NUMBER	DATE RECEIVED
1241	IN	26928	12 7 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0832

NAME		SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE.

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189				X	3000	X			1 ROLL	T	K087	
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen -- PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0832

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189				X	3000	X				1 Roll	T	K087
Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nye</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH 11 DAY 12 YEAR 81	EXPECTED ARRIVAL DATE MONTH 11 DAY 12 YEAR 81
Transporter HWT ID No. 129 IN 2697R	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF <i>John Kowalski</i>
			DATE RECEIVED MONTH 11 DAY 12 YEAR 81

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>	DATE DELIVERED MONTH 11 DAY 12 YEAR 81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Meth. 1 D-2 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	DATE RECEIVED MONTH 11 DAY 12 YEAR 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0832

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

7302

REFERENCE 80

Page 190

1 PART A

DOCUMENT NO.

0832

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189					3000	X				1 ROLL	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Muggs</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 14 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 14 81
TRANSPORTER HWT ID No. 124 IN 2692R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF <i>Richard R...</i>	DATE RECEIVED MONTH DAY YEAR 12 14 81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302

0832

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189					3000	X				1 ROLL	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

PLEASE TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

JONES & LAUGHLIN STEEL CORPORATION / an LTV company

HAZARDOUS WASTE MANIFEST

7302 - 083223
REFERENCE 80

1 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid, N.O.S. Tar Decanter Sludge	ORM-E-12	NA9189				X	3000	X				1 ROLL	T	K087

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	YEAR	EXPECTED ARRIVAL DATE
<i>Steve Nays</i>	<i>Supt. Clerk</i>	12 7	81	12 7 81
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED
1241	IN	26928	<i>Richard R. Smith</i>	12-7-81

Jones & Laughlin Steel Corporation / an LTV company

PLEASE TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08322

1 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid, N.O.S. 2 Tar Decanter Sludge	ORM-E-12	NA9189				X	3000	X				1 ROLL	T	K087
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

EXPECTED ARRIVAL DATE

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12754

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. May</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 11 3 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 3 81
Transporter HWT ID No. 22 IN 91690	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>	DATE RECEIVED MONTH DAY YEAR 11 3 81

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>	DATE DELIVERED MONTH DAY YEAR 11 3 81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methc

1	D81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYO</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 11 4 81
--	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 1275

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 193

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid H.O.S.	ORM-E	NA9189				X	3333	X				1	Rel	T	FO06
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>Waste Water Oper.</i>	MONTH DAY YEAR	MONTH DAY YEAR
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
ID No. 117	IN	2785	<i>[Signature]</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

0848

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, H.O.S.	ORM-E	NA9189				X	3333	X				1	Rel	T	FO06
(Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

3 PART A

REFERENCE NO. 80

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA ID
J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054
TRANSPORTER NO. 1		P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS	EPA HAZ COD
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1 Rcl	T
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the treatment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL
<i>[Signature]</i>	Central Waste Oper	11/1/82	11/1/82
Transporter HWI	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OR RECEIPT OF SHIPMENT
ID No. 129	IN	7297R	<i>[Signature]</i>

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA ID
J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054
TRANSPORTER NO. 1		P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS	EPA HAZ COD
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3325	X				1 Rcl	T
2. (Central Waste Treatment Plant Sludge)	(12)												
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the treatment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE
<i>[Signature]</i>	

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12311

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RCL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Vays</i>	TITLE <i>Gen. Mgr.</i>	DATE TO BE SHIPPED MONTH DAY YEAR 11 9 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 9 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR 11 9 81	

TEAR AT THIS PERFORATION
TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>	DATE DELIVERED MONTH DAY YEAR 11 9 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR 11 9 81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D-2
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Woyt</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 11 9 81
--	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 1231

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 196

NAME		SITE ADDRESS		PHONE NO.	EPA I.D. NO.										
GENERATOR J Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-397-2531	IND005462601										
TRANSPORTER NO. 1		P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587										
TRANSPORTER NO. 2 (IF ANY)															
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916										
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE															
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>															
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid H.O.S.	ORM-E	NA9189			X		3333	X				1	Rel	T	FO05
Central Waste Treatment Plant Sludge	(12)														
3.															
4.															
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)															
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.															
GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE									
[Signature]		WASTE WATER OPER.		11/5/87		11/5/87									
TRANSPORTER HWHT		STATE		NUMBER		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED							
117		IN		2778-12		[Signature]		11/5/87							

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

084

NAME		SITE ADDRESS		PHONE NO.	EPA I.D. NO.										
GENERATOR J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-291-2531	IND005462601										
TRANSPORTER NO. 1		P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587										
TRANSPORTER NO. 2 (IF ANY)															
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005916										
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE															
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>															
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EP. WASTE TYI	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid H.O.S.	ORM-E	NA9189			X		3770	X				1	Rel	T	FO
Central Waste Treatment Plant Sludge	(12)														
3.															
4.															
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)															
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.															

HAZARDOUS WASTE MANIFEST

HAZARDOUS WASTE MANIFEST

7306 0847

3 PART A

REFERENCE 80

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044220587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-K	NA9189				X	3333					1	ROL	FOG
(Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 11 DAY 6 YEAR 81	EXPECTED ARRIVAL DATE MONTH 11 DAY 6 YEAR 81
TRANSPORTER FHW ID No. 1217117190	STATE IN NUMBER 7190	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF EQUIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 11 DAY 6 YEAR 81

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 084

3 PART A

DOCUMENT NO.

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044220587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous waste, solid, n.o.s.	ORM-E	NA5189				X	3770					1	ROL	FOG
(Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 11 DAY 6 YEAR 81	EXPECTED ARRIVAL DATE MONTH 11 DAY 6 YEAR 81
TRANSPORTER FHW ID No. 1217117190	STATE IN NUMBER 7190	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF EQUIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 11 DAY 6 YEAR 81

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
Page 198

3 PART A

DOCUMENT NO. 7306

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J.M. Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WAS TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
Hazardous waste, solid, n.e.s.	ORM-E	NA9189				X	3,333							
(Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Transporter HWT ID No. 117	STATE IN	NUMBER 27852	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
		DATE RECEIVED MONTH DAY YEAR	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J.M. Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WAS TY	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
Hazardous waste, solid, n.e.s.	ORM-E	NA9189				X	3,770							
(Central Waste Treatment Plant Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 0848

3 PART A

DOCUMENT NO. 7306 EPA I.D. NO. 0848

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312			219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-F	NA9189				X	3333	X					1	261	P006
(Central Waste Treatment Plant Sludge)	ORM-F (12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested):

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Bob Kent or Leslie</i>	TITLE <i>Waste Vehicle Driver</i>	DATE TO BE SHIPPED MONTH 11 DAY 9 YEAR 1991	EXPECTED ARRIVAL DATE MONTH 11 DAY 9 YEAR 1991
TRANSPORTER HWT ID No. 124	STATE IN	NUMBER 2697E	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION <i>JL</i>

TO BE FILLED OUT BY GENERATOR

HAZARDOUS WASTE MANIFEST

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

DOCUMENT NO. 7306 0848

3 PART A

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312			219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
Hazardous Waste, solid N.O.S. (Central Waste Treatment Plant Sludge)	ORM-E (12)	NA9189				X	3770	X				1	261	1	P006
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested):

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 200

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous Waste, solid, H.O.S.	ORM-E	NA9189				X	3337	X					1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE Waste Management	DATE TO BE SHIPPED MONTH 11 DAY 3 YEAR 81	EXPECTED ARRIVAL DATE MONTH 11 DAY 3 YEAR 81
TRANSPORTER HWT ID No. 177	STATE IN	NUMBER 9698	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION ON RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH 11 DAY 3 YEAR 81

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

08473

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous Waste, solid H.O.S.	ORM-E	NA9189				X	3770	X					1	ROL	T	F006
2. (Central Waste Treatment Plant Sludge	(12)															
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

084

3 PART A

REFERENCE 80

Page 201

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND000546266
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE T
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous waste, solid n.o.s.	ORM-E	NA9189				X	333	X				1	Ro	T	F
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPER	11/4/81	11/4/81
Transporter HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
11/11/81	IN	27852	<i>[Signature]</i>

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / and its company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08

3 PART A

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND000546266
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE	
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770					1	Roll	
Central Waste Treatment Plant Sludge	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 202

3 PART A		DOCUMENT NO. 7306 - 08468	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development		219-944-7858	IND077005916
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/>		Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>	
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM
1. Hazardous waste, solid, H.C.S.	ORM-E NA	NA9189	SOLID LIQUID GAS SLUDGE
2. (Central Waste Treatment Plant Sludge)	(12)		
3.			
4.			
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.			
GENERATOR'S SIGNATURE		TITLE	DATE TO BE SHIPPED
[Signature]		WASTE WATER OPER.	MONTH DAY YEAR
Transporter HWT ID No.		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED
117 IN 278		[Signature]	MONTH DAY YEAR

JONES & LAUGHLIN STEEL CORPORATION / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

08469

3 PART A		DOCUMENT NO. 7306 - 08469	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development		219-944-7858	IND077005916
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/>		Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>	
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM
1. Hazardous waste, solid, H.C.S.	ORM-E	NA9189	SOLID LIQUID GAS SLUDGE
2. (Central Waste Treatment Plant Sludge)	(12)		
3.			
4.			
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08471

3 PART A

REFERENCE 8047
Page 203

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				1	3570					1	RL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Serbie</i>	TITLE <i>Manager</i>	DATE TO BE SHIPPED MONTH 3 DAY 8 YEAR 81	EXPECTED ARRIVAL DATE MONTH 11 DAY 3 YEAR 81
TRANSPORTER FMT ID No. 192	STATE IN	NUMBER 7490	DATE RECEIVED MONTH 11 DAY 3 YEAR 81

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08471

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS	TONS				
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				1	3533					1	RL	T	F006
2. (Central Waste Treatment Plant Sludge)	(12)														
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08487

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

RE MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste, Solid, U.S.S.	ORM-E	NA9189				X	3333	X					1 Ro	T	F006
(Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment if a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE <i>Waste Manager</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>10/31/81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>10/31/81</i>
TRANSPORTER WT No. 29	STATE <i>IN</i>	NUMBER <i>26973</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John K...</i>
			DATE RECEIVED MONTH DAY YEAR <i>10/31/81</i>

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 08486

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

RE MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, Solid, U.S.S.	ORM-E	NA9189				X	2700	X					1 Ro	T	F006
(Central Waste Treatment Plant Sludge)	(12)														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment if a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

GENERATOR NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7853	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3770	X				1	R/T		PO0
(Central Waste Treatment Plant Sludge)	(12)														
3															
4															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE Vice President	DATE TO BE SHIPPED 10/30/81	EXPECTED ARRIVAL DATE 10/30/81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION <i>John R. Smith</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION	DATE RECEIVED 10/30/81	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 084

GENERATOR NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7853	IND087005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3333	X				1	R/T		PO06
Central Waste Treatment Plant Sludge															
3															
4															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE Vice President	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION	DATE RECEIVED	

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12799

REFERENCE 80

Page 206

1 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Stewart E. Nagle</i>		TITLE <i>Asst. Clerk</i>		DATE TO BE SHIPPED MONTH DAY YEAR <i>10 29 81</i>		EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>10 29 81</i>	
TRANSPORTER HWT ID No. <i>129</i>		STATE <i>IN</i>		NUMBER <i>2697R</i>		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>	
						DATE RECEIVED MONTH DAY YEAR <i>10/29/81</i>	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12949

1 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

1 PART A

REFERENCE 80

Page 207

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA ID NO. IND00240691
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Vaz</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>11 3 81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>11 3 81</i>
Transporter HWT ID No. <i>22</i>	STATE <i>IN</i>	NUMBER <i>96910</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Thomas</i>
			DATE RECEIVED MONTH DAY YEAR <i>11 3 81</i>

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08401

REFERENCE 80
Page 208

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-R-12	NA9189				X	3770					1	ROL	T	PD06
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
Robert O. Leslie	Waste Manager	10/29/81	10/29/81
TRANSPORTER	STATE	NUMBER	DATE RECEIVED
HWT ID No. 129	IN	26972	10/29/81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 08401

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-R-12	NA9189				X	3333					1	ROL	T	PD06
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

REFERENCE 80

Page 209

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312			219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3770	X				1	R	T	RD06
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE Waste Management	DATE TO BE SHIPPED MONTH DAY YEAR 10/25/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10/25/81
TRANSPORTER HWT ID No. 129	STATE IN	NUMBER 74972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Smith</i>
			DATE RECEIVED MONTH DAY YEAR 10/25/81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

0839

3 PART A

DOCUMENT NO.

NAME	SITE ADDRESS			PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312			219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	R	T	RD06
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12949

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

The Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	Rel T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>Supt. Clk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 10/26/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10/26/81
Transporter HWT ID No. 129 EN 2491R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 10/26/81	

YEAR AT THIS PERFORMANCE

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>[Signature]</i>	DATE DELIVERED MONTH DAY YEAR 10/26/81
Transporter HWT ID No. <input type="checkbox"/>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1	D-01
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 12949

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 211

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS					
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3333	X					1	Reg	T	F006
2. Central Waste Treatment Plant Sludge																
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>W. J. Jones</i>	TITLE Waste Management Director	DATE TO BE SHIPPED MONTH DAY YEAR 10 27 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 17 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John D. Jones</i>	DATE RECEIVED MONTH DAY YEAR 10 27 81		
Transporter HWT ID No. 124	STATE IN	NUMBER 21972	

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0839

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS					
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3770	X					1	Reg	T	F00
2. Central Waste Treatment Plant Sludge																
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

EXPECTED ARRIVAL DATE

TYPE or PRINT clearly, using
point pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 8896

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
MENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

ORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S. Industrial Waste Treatment Plant Sludge	ORM-E-12	NA9189				X	2533	X				1	86	T	F006

Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

FOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>Waste Transfer Officer</i>	MONTH DAY YEAR 10 26 81	MONTH DAY YEAR 10 26 81
STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED
IND	21972	<i>[Signature]</i>	MONTH DAY YEAR 10 26 81

Jones & Laughlin Steel Corporation / an LTV company

TYPE or PRINT clearly, using
point pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 08395

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
MENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

RE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S. Industrial Waste Treatment Plant Sludge	ORM-E-12	NA9189				X	3770	X				1	86	T	F006

Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12949

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	Rel	T	K087
2.															
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>[Signature]</i>	DATE TO BE SHIPPED MONTH DAY YEAR 10/26/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10/26/81
Transporter HWT ID No. 129 IN 2491R	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 10/26/81

YEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>[Signature]</i>	DATE DELIVERED MONTH DAY YEAR 11/26/81
Transporter HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1	D-01
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

- 12949

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 214

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077003916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	HA9189				X	3333	X				1	1000	T	FO06
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Vice President	DATE TO BE SHIPPED MONTH 10 DAY 25 YEAR 81	EXPECTED ARRIVAL DATE MONTH 10 DAY 25 YEAR 81
TRANSPORTER NO. 1 HWT ID No. 17711111111111111111	STATE NUMBER IN 17711111111111111111	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 10 DAY 25 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0839

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	HA9189				X	3470	X				1	1000	T	FO06
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA ID. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	Roll	T	P006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE	
Robert O. Leschmeister		Transporter		10-23-81		10-23-81	
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED		MONTH		DAY	
J. Marking		10-27-81		10		27	

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 08391

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA ID. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700					1	Roll	T	P006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

On-label Exemption (i.e. Identification of Additional Wastes Included in Shipment)

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08340

REFERENCE 80
Page 216

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
Hazardous Waste Liquid or Solid N.O.S. Central Waste Treatment Plant Sludge	ORM-E-12	NA9189				X	2700	X				1	RT	T P006
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>Robert J. Leibel</i>		<i>Manager</i>	MONTH 10 DAY 22 YEAR 81	MONTH 10 DAY 22 YEAR 81
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED
HWT ID No. 119	IN	229	<i>Mark</i>	MONTH 10 DAY 22 YEAR 81

JONES & LAUGHLIN STEEL CORPORATION / and TV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08339

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
Hazardous Waste Liquid or Solid N.O.S. Central Waste Treatment Plant Sludge	ORM-E-12	NA9189				X	2700	X				1	RT	T P006
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

08338

3 PART A		DOCUMENT NO. 08338													
GENERATOR NAME	SITE ADDRESS		PHONE NO.												
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531												
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664												
Industrial Disposal Corp.			IND044250587												
TRANSPORTER NO. 2 (IF ANY)															
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7858												
Gary Land Development			IND077005916												
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE															
This Form Is No. <input type="checkbox"/>		Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>													
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189			X		00	X							
Central Waste Treatment Plant Sludge															
3.															
4.															
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)															
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.															
GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		YEAR		EXPECTED ARRIVAL DATE		YEAR					
<i>[Signature]</i>		<i>[Signature]</i>		10		24		10		24					
TRANSPORTER		STATE		NUMBER		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED		YEAR					
ID No. 172		IN		9690		<i>[Signature]</i>		10		24					

3 PART A		DOCUMENT NO. 08338													
GENERATOR NAME	SITE ADDRESS		PHONE NO.												
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312		219-391-2531												
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312		219-397-2664												
Industrial Disposal Corp.			IND044250587												
TRANSPORTER NO. 2 (IF ANY)															
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406		219-944-7858												
Gary Land Development			IND077005916												
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE															
This Form Is No. <input type="checkbox"/>		Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>													
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189			X		2200	X							
Central Waste Treatment Plant Sludge															
3.															
4.															
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)															
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.															
DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE													
10		24													

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

08333

REFERENCE 80
Page 218

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	40 L	T	F006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *J. J. Gammillo* TITLE: *W.W. Operator* DATE TO BE SHIPPED: *10/19/81* EXPECTED ARRIVAL DATE: *10/19/81*

Transporter HWHT ID No. *117* STATE: *IN* NUMBER: *117670* TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: *10/19/81*

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08333

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR JSL Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X		X						T	F006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 0833
EPA I.D. NO.

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
J&L Steel Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 1			
Industrial Disposal Corp.			
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916
Gary Land Development			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189					3,770					1	Roll	FO06
Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Manager	DATE TO BE SHIPPED MONTH DAY YEAR 10 21 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10 21 81
TRANSPORTER HWT ID No. 177	STATE IN	NUMBER 916912	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 0833
EPA I.D. NO.

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
J&L Steel Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 1			
Industrial Disposal Corp.			
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916
Gary Land Development			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189					3,770					1	Roll	FO06
Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 22048

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RSLT		K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE				
MONTH	DAY	YEAR	MONTH	DAY	YEAR		
<i>Steve Meyer</i>	<i>Plant Clerk</i>	10	19	81	10	19	81
Transporter HWT ID No. 122IM 2690	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED				
		<i>James Thomas</i>	MONTH DAY YEAR				
			10 19 81				

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED
MONTH DAY YEAR	MONTH DAY YEAR
<i>James Thomas</i>	10 19 81
Transporter No. 2 HWT ID No.	STATE NUMBER
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED
	MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED
	MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Methc
	1 081
	2
	3
	4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION	TITLE
<i>Brian Bond</i>	
DATE RECEIVED	MONTH DAY YEAR
10-19-81	

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 1294

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 221

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J. Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3333	X				1	20L	T	F006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE W.W. Olenstein	DATE TO BE SHIPPED MONTH DAY YEAR 10 18 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10 18 81
Transporter HWT ID No. <i>[Signature]</i>	STATE IN	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 10 18 81

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 0833

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND054250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	20L	T	F006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid N.O.S. Central Waste Treatment Plant Sludge	ORM-E-12	NA9189					37701					1 TR. /	T	F006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Vice President	DATE TO BE SHIPPED MONTH DAY YEAR 10/17/91	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10/17/91
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	STATE IN	NUMBER 212972	DATE RECEIVED MONTH DAY YEAR 10/17/91

Jones & Laughlin Steel Corporation / an LTV company

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid N.O.S. 2 Central Waste Treatment Plant Sludge	ORM-E-12	NA9189					2700					1 TR. /	T	F006
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 223

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189					3333					1	801	T	FC06
Central Waste Treatment Plant Sludge															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John A. Taylor</i>	TITLE <i>Waste Manager</i>	DATE TO BE SHIPPED MONTH <i>10</i> DAY <i>15</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>10</i> DAY <i>15</i> YEAR <i>81</i>
TRANSPORTER STATE <i>IN</i> NUMBER <i>2</i> <i>4972</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION <i>John A. Taylor</i>	DATE RECEIVED MONTH <i>10</i> DAY <i>15</i> YEAR <i>81</i>	

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08327

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189					2700					1	REL	T	FC06
Central Waste Treatment Plant Sludge															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 - 08266
REFERENCE 80
Page 224

3	PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	Rel	T	R006
Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPER	10/14/87	10/15/87
TRANSPORTER'S SIGNATURE	STATE	NUMBER	DATE RECEIVED
<i>[Signature]</i>	IN	2700	10/14/87

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 - 08265

3	PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-R-12	NA9189				X	2700	X				1	Rel	T	R006
Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>			

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12947

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>		TITLE <i>Supt. Oper</i>		DATE TO BE SHIPPED MONTH DAY YEAR 10 15 81			EXPECTED ARRIVAL DATE MONTH DAY YEAR 10 15 81		
Transporter HWT ID No.	STATE IN	NUMBER 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Tancib</i>			DATE RECEIVED MONTH DAY YEAR 10/15/81			

YEAR AT THIS PERFORATION

1 PART B

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Tancib</i>				DATE DELIVERED MONTH DAY YEAR 10/15/81			
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT			DATE RECEIVED MONTH DAY YEAR	
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT				DATE DELIVERED MONTH DAY YEAR			

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.

Handling Method

1	D-81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYD</i>	TITLE <i>10-15-81</i>	DATE RECEIVED MONTH DAY YEAR 10-15-81
--	--------------------------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 12947

TO BE FILLED OUT BY TSD FACILITY

Please TYPE or PRINT clearly, using
a ballpoint pen. - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 226
7302 - 12941

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste 1. Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X			1 Roll		T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
Steve E. Nagy	Supt. Clark	10 12 81	10 12 81
Transporter HWT ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT John Kovech
			DATE RECEIVED MONTH DAY YEAR 10/12/81

YEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
John Kovech	10/12/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Methc 1 D-2 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION Brian Boyd	DATE RECEIVED MONTH DAY YEAR 11 78 10

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 1294

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7366 08264

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Generator Y&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Transporter No. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Transporter No. 2 (if any)			
Treatment, Storage or Disposal Facility Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	HA9189				X	333.5	X			1	Ref	T	F006
2 Central Waste Treatment Plant Sludge														
3														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *Vice President* DATE TO BE SHIPPED: 10/12/01
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *[Signature]* DATE RECEIVED: 10/12/01

REFERENCE 80
Page 227

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 08263

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Generator Y&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Transporter No. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Transporter No. 2 (if any)			
Treatment, Storage or Disposal Facility Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	HA9189				X	2700	X			1	Ref	T	F006
2 Central Waste Treatment Plant Sludge														
3														
4														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. **08261**
EPA I.D. NO. **IND005462601**
Page 228

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1 RoL	T	F006
2 Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Feltie</i>		TITLE Central Waste Corp.	DATE TO BE SHIPPED MONTH DAY YEAR 10/12/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10/12/81
Transporter HWT ID No. 129	STATE IN	NUMBER 24972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John R. ...</i>	DATE RECEIVED MONTH DAY YEAR 10/12/81

Jones & Laughlin Steel Corporation / an ILC company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. **7306** **08261**

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1 RoL	T	F
2 Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 229

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
REPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/>		Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>	
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM SOLID LIQUID GAS SLUDGE
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189	QUANTITY 2700
2. Central Waste Treatment Plant Sludge			UNITS GALLONS CU YDS POUNDS TONS
3.			CONTAINERS NO. TYPE
			EPA HAZ CODE
			EPA WASTE TYPE
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.			
GENERATOR'S SIGNATURE Robert O. Leslie	TITLE Vice President	DATE TO BE SHIPPED MONTH 10 DAY 12 YEAR 81	EXPECTED ARRIVAL DATE MONTH 10 DAY 12 YEAR 81
Transporter HWT ID No. 117	STATE IN	NUMBER 27958	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT J. H. H. H.
			DATE RECEIVED MONTH 10 DAY 12 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

08259

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
REPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Cary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE			
This Form Is No. <input type="checkbox"/>		Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>	
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM SOLID LIQUID GAS SLUDGE
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189	QUANTITY 2700
2. Central Waste Treatment Plant Sludge			UNITS GALLONS CU YDS POUNDS TONS
3.			CONTAINERS NO. TYPE
			EPA HAZ CODE
			EPA WASTE TYPE
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)			
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.			

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 88
REFERENCE 88
EPA I.D. NO.

3 PART A

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X		X					T	F006
2 Central Waste Treatment Plant Sludge														
3														
4														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	W. N. Operator	10/11/81	10/11/81
TRANSPORTER HWI	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
11771M	IN	2785A	<i>[Signature]</i>

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306 0825
DOCUMENT NO.

3 PART A

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3333	X				1 Rd	T	F006
2 Central Waste Treatment Plant Sludge														
3														
4														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189			X		3333	X				1	Ro	T	F006
2. Central Waste Treatment Plant Sludge															
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>John Kowalski</i>	Waste Vehicle Operator	10/11/81	10/11/81
TRANSPORTER ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>
			DATE RECEIVED MONTH DAY YEAR 8 11 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 0825

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189			X		2700	X				1	Ro	T	F006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

REFERENCE 80

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7853	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189			X		1700	X				1 Ro	T	FOO
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE NW Operator	DATE TO BE SHIPPED MONTH 10 DAY 18 YEAR 81	EXPECTED ARRIVAL DATE MONTH 10 DAY 11 YEAR 81
TRANSPORTER HWT ID No. 111	STATE IN	NUMBER 27851A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH 10 DAY 11 YEAR 81

TO BE FILLED OUT BY GENERATOR

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7853	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189			X		3333	X				1 Ro	T	FOO
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

TYPE OF PRINT JOB: USING
Joint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 233

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2,700	X				1	Ro	T F006
2. Central Waste Treatment Plant Sludge														
3.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>John H. H. H.</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 10 DAY 9 YEAR 81	EXPECTED ARRIVAL DATE MONTH 10 DAY 9 YEAR 81
TRANSPORTER HWT ID No. 172	STATE IN	NUMBER 26490	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John H. H. H.</i>
			DATE RECEIVED MONTH 10 DAY 9 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

0825

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	Ro	T F006
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80-3
Page 234

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-391-2531		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	333	X				1	81	FG06
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE	
<i>[Signature]</i>		NAME: ROSTER-OPER		MONTH: 10 DAY: 9 YEAR: 81		MONTH: 10 DAY: 9 YEAR: 81	
TRANSPORTER STATE		NUMBER		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED	
ID No. 117 AM 27285A				<i>[Signature]</i>		MONTH: 10 DAY: 9 YEAR: 81	

TO BE FILLED OUT BY GENERATOR

HAZARDOUS WASTE MANIFEST

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-391-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	81	FG06
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12945

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Hays</i>	TITLE <i>Sent. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 10 8 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10 8 81
Transporter HWT ID No. 122E 02690	STATE IN NUMBER 02690	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Jan Hays</i>	DATE RECEIVED MONTH DAY YEAR 10 8 81

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Jan Hays</i>			DATE DELIVERED MONTH DAY YEAR 10 8 81
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Jan Hays</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.

Handling Metho

1	D81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>Q&A security</i>	DATE RECEIVED MONTH DAY YEAR 10 - 8 - 81
---	---	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 12945

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

REFERENCE 80
Page 236

3 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3601 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3333	X				1	246	T	FOO6
2 Central Waste Treatment Plant Sludge															
3															
4															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>J. J. J. J.</i>	TITLE <i>W. W. O. O. O. O.</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>10 7 81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>10 7 81</i>
Transporter HWT ID No. <i>117 IN 2786R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. J. J. J.</i>	DATE RECEIVED MONTH DAY YEAR <i>10 7 81</i>	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

082

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3601 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	246	T	FOO6
2 Central Waste Treatment Plant Sludge															
3															
4															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

0820

3 PART A

Page 237

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)		East Chicago, IN 46312		
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	219-944-7858	IND077005916
	Gary, IN 46406			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
Hazardous Waste															
Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	Pa	T	P006
Central Waste Treatment															
Plant Sludge															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPER.	10/6/87	10/6/87
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
<i>[Signature]</i>	10/6/87		

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

0820

3 PART A

Document No.

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)		East Chicago, IN 46312		
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	219-944-7858	IND077005916
	Gary, IN 46406			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.

Out Of A Total Of

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
Hazardous Waste															
Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	8333	X				1	Pa	T	P006
Central Waste Treatment															
Plant Sludge															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 - 0820

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X					1	R01	T	F006
2. Central Waste Treatment Plant Sludge																
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

REFERENCE 80
Page 238

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: Robert O. Leslie TITLE: Wastewater OPER DATE TO BE SHIPPED: MONTH 10 DAY 5 YEAR 81 EXPECTED ARRIVAL DATE: MONTH 10 DAY 5 YEAR 81

Transporter STATE NUMBER NUMBER TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OR SHIPMENT DATE RECEIVED: MONTH 10 DAY 5 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 - 0820

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X					1	R01	T	F006
2. Central Waste Treatment Plant Sludge																
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

3 PART A

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077003916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	33.33				1	ROL	T	P006
Central Waste Treatment Plant Sludge														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *George Penney* TITLE: *Waste Water Operator* DATE TO BE SHIPPED: *10/3/84* MONTH: *10* DAY: *3* YEAR: *84*

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *Rich Mayo* DATE RECEIVED: *10/3/84* MONTH: *10* DAY: *3* YEAR: *84*

Jones & Laughlin Steel Corporation / an **ITV** company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. **7306** **08201**

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	1707				1	ROL	T	P006
Central Waste Treatment Plant Sludge														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *Rich Mayo* TITLE: *Waste Water Operator* DATE TO BE SHIPPED: *10/3/84* MONTH: *10* DAY: *3* YEAR: *84*

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT: *Rich Mayo* DATE RECEIVED: *10/3/84* MONTH: *10* DAY: *3* YEAR: *84*

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 1275

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROLL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Yagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 10 1 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10 1 81
Transporter HWT ID No. 12911N2692R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>	DATE RECEIVED MONTH DAY YEAR 10 1 81	

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard Roach</i>	DATE DELIVERED MONTH DAY YEAR 10 1 81
Transporter No. 2 HWT ID No. 12911N2692R	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR 10 1 81
	DATE DELIVERED MONTH DAY YEAR 10 1 81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methc

1 D81

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Jack Buchanan</i>	TITLE <i>Watchman</i>	DATE RECEIVED MONTH DAY YEAR 10 1 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE		

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TSD FACILITY

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

Page 241

3 PART A

DOCUMENT NO. 7306

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 60560 Gary, IN 46406	219-244-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X			1	66	T	F006
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>[Signature]</i>	WASTE WATER OPER	9 20 81	9 30 81
TRANSPORTER HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
417	IN	27852	<i>[Signature]</i>

Jones & Laughlin Steel Corporation / and its company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12999

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-244-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3333	X			1	26	T	F006
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

12

REFERENCE 80

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 8001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	W. T.
			SOLID	LIQUID	GAS	SLUDGE	QUANTITY	GALLONS	CU YDS	POUNDS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700				1	20	T	
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. identification of Additional Wastes included in shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>W. M. O'Brien</i>	DATE TO BE SHIPPED MONTH <i>8</i> DAY <i>27</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>9</i> DAY <i>29</i> YEAR <i>81</i>
TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH <i>9</i> DAY <i>29</i> YEAR <i>81</i>		

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 8001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND0770

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	W. T.
			SOLID	LIQUID	GAS	SLUDGE	QUANTITY	GALLONS	CU YDS	POUNDS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	3333				1	20	T	
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. identification of Additional Wastes included in shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 243

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	HA9189				X	2700	X				1	Rel	T	FO00
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>[Title]</i>	MONTH DAY YEAR	MONTH DAY YEAR
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
ID No. 124	IN	26192K	<i>[Signature]</i>
			DATE RECEIVED
			MONTH DAY YEAR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 129

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EP. WASTE TYI
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	HA9189				X	3300	X				1	Rel	T	FO
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	W	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
Hazardous Waste 1 Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X					1	ROL	T	
Central Waste Treatment 2 Plant Sludge																
3																
4																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George P. ...</i>	TITLE <i>Waste Management</i>	DATE TO BE SHIPPED MONTH: 8 DAY: 27 YEAR: 81	EXPECTED ARRIVAL DATE MONTH: 8 DAY: 27
TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>...</i>	DATE RECEIVED MONTH: 8 DAY: 27		

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / and company

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 12

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND00546260
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07701

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X					1	ROL	T
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED	DATE RECEIVED	EXPECTED ARRIVAL DATE
--------------------	---------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 245

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 60560 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid N.O.S.O.	ORM-E-12	NA9189			X	2700	X				1	ROL	T	FOO
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>[Signature]</i>	DATE TO BE SHIPPED MONTH DAY YEAR 9 26 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 9 26 81
TRANSPORTER HWY ID NO. 122	STATE IN	NUMBER 122	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH DAY YEAR 9 26 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

129

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid N.O.S.O.	ORM-E-12	NA9189			X	2933	X				1	ROL	T	FOO
2. Central Waste Treatment Plant Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 12
REFERENCE 80
D. NO.

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2654	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700					1 RCL	T
2. Central Waste Treatment Plant Sludge													
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>[Signature]</i>	DATE TO BE SHIPPED MONTH DAY YEAR 9 25 81	EXPECTED ARRIVAL MONTH DAY YEAR 9 25 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 9/25/81		

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND0054626
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2654	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND07700591

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS		
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700					1 RCL	T
2. Central Waste Treatment Plant Sludge													
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 247

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	ROL	T	F006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George P. ...</i>	TITLE Waste ...	DATE TO BE SHIPPED MONTH 9 DAY 24 YEAR 81	EXPECTED ARRIVAL DATE MONTH 9 DAY 24 YEAR 81
TRANSPORTER HWT ID No. 177	STATE IN	NUMBER 70401	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
		DATE RECEIVED MONTH 9 DAY 24 YEAR 81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1298

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid N.O.S.	ORM-E-12	NA9189				X	2700	X				1	ROL	T	F006
2. Central Waste Treatment Plant Sludge															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 12963
REFERENCE 80

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462801
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CU YDS	POUNDS	TONS	GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2900	X							1	RO	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	9/22/81	9/22/81
TRANSPORTER	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
HWI	124	101	<i>[Signature]</i>
ID No.	278112		DATE RECEIVED
			9/22/81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 12964

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462801
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CU YDS	POUNDS	TONS	GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X							1	RO	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

SIGNATURE TITLE DATE TO BE SHIPPED EXPECTED ARRIVAL DATE

Jones & Laughlin Steel Corporation / an TV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12759

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nugs</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH 9 DAY 24 YEAR 81	EXPECTED ARRIVAL DATE MONTH 9 DAY 24 YEAR 81
Transporter HWT ID No. 192 I IV 9690	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>	DATE RECEIVED MONTH 9 DAY 24 YEAR 81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>			DATE DELIVERED MONTH 9 DAY 24 YEAR 81
Transporter No. 2 HWT ID No.	STATE NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
for And Disposition of Rejected Materials.

Handling Method

1 D81

2

3 680 SEP

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 12759

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 250

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos.	12-ORM-R	NA9189			X		2700	X				1	REL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>W.W. Operator</i>	MONTH 9 DAY 21 YEAR 81	MONTH 9 DAY 21 YEAR 81
Transporter HWT ID No. 192	STATE IN	NUMBER 79000000000000000000	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
			DATE RECEIVED MONTH 9 DAY 21 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1296

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos.	12-ORM-R	NA9189			X		2700	X				1	REL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12960
REFERENCE 80
Page 251

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (If ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid Res	12-ORM-E	NA9189				X	2760	X				1	REL	T	F006
2															
3															
4															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>Henry P. ...</i>	<i>Waste Management</i>	4/20/87	7/10/87
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
<i>J. ...</i>	9/20/87		

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12959

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.	
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (If ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CUBIC YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid Res	12-ORM-E	NA9189				X	2760	X				1	REL	T	F006
2															
3															
4															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 252

3 PART A		DOCUMENT NO. 7306	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531
TRANSPORTER NO. 1	NAME	SITE ADDRESS	PHONE NO.
Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312	219-397-2664
TRANSPORTER NO. 2 (IF ANY)	NAME	SITE ADDRESS	PHONE NO.
TREATMENT, STORAGE OR DISPOSAL FACILITY	NAME	SITE ADDRESS	PHONE NO.
Gary Land Development	P.O. Box 6056	Gary, IN 46406	219-944-7858
EPA I.D. NO.		EPA I.D. NO.	
IND005462601		IND044250587	
EPA I.D. NO.		EPA I.D. NO.	
IND077005916		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	HA8189				X	2700	X				1	ROL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	N.W. O'Leary	7 19 81	7 19 81
TRANSPORTER'S SIGNATURE	DATE RECEIVED		
<i>[Signature]</i>	7 19 81		

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1295

3 PART A		DOCUMENT NO. 7306	
GENERATOR	NAME	SITE ADDRESS	PHONE NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531
TRANSPORTER NO. 1	NAME	SITE ADDRESS	PHONE NO.
Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312	219-397-2664
TRANSPORTER NO. 2 (IF ANY)	NAME	SITE ADDRESS	PHONE NO.
TREATMENT, STORAGE OR DISPOSAL FACILITY	NAME	SITE ADDRESS	PHONE NO.
Gary Land Development	P.O. Box 6056	Gary, IN 46406	219-944-7858
EPA I.D. NO.		EPA I.D. NO.	
IND005462601		IND044250587	
EPA I.D. NO.		EPA I.D. NO.	
IND077005916		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	HA9189				X	2700	X				1	ROL	T	F006
2.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

HAZARDOUS WASTE MANIFEST

3 PART A

GENERATOR NAME: **JLT Steel Corp.** SITE ADDRESS: **3001 Dickey Road, East Chicago, IN 46312** PHONE NO.: **219-391-2531** EPA ID NO.: **IND005462601**

TRANSPORTER NO. 1 (IF ANY): **Industrial Disposal Corp.** ADDRESS: **P.O. Box 59, East Chicago, IN 46312** PHONE NO.: **219-397-2664** EPA ID NO.: **IND044250587**

TREATMENT, STORAGE OR DISPOSAL FACILITY: **Gary Land Development** ADDRESS: **P.O. Box 6056, Gary, IN 46406** PHONE NO.: **219-944-7858** EPA ID NO.: **IND077005916**

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2740	X				1	100	T	FO06
2															
3															
4															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested):

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: *[Signature]* TITLE: *Manager* DATE: *7/15/88*

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION: *[Signature]* DATE: *7/15/88*

TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION: *[Signature]* DATE: *7/15/88*

HAZARDOUS WASTE MANIFEST

3 PART A

GENERATOR NAME: **Jones & Laughlin Steel Corporation** SITE ADDRESS: **3001 Dickey Road, East Chicago, IN 46312** PHONE NO.: **219-391-2531** EPA ID NO.: **IND005462601**

TRANSPORTER NO. 1 (IF ANY): **Industrial Disposal Corp.** ADDRESS: **P.O. Box 59, East Chicago, IN 46312** PHONE NO.: **219-397-2664** EPA ID NO.: **IND044250587**

TREATMENT, STORAGE OR DISPOSAL FACILITY: **Gary Land Development** ADDRESS: **P.O. Box 6056, Gary, IN 46406** PHONE NO.: **219-944-7858** EPA ID NO.: **IND077005916**

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE:

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	100	T	FO06
2															
3															
4															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested):

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
1295

Page 254

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>[Signature]</i>	Waste Mgr. OPER	9/17/91	9/17/91
Transporter HWT ID No. 129	STATE IN	NUMBER 22972	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
			DATE RECEIVED MONTH DAY YEAR 9/17/91

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

12953

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700						1	R/T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>Waste Mgmt. Officer</i>	DATE TO BE SHIPPED MONTH <i>9</i> DAY <i>16</i> YEAR <i>1991</i>	EXPECTED ARRIVAL DATE MONTH <i>9</i> DAY <i>16</i> YEAR <i>1991</i>
TRANSPORTER ID No. <i>29</i>	STATE <i>IN</i>	NUMBER <i>264712</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF <i>[Signature]</i>
			DATE RECEIVED MONTH <i>9</i> DAY <i>16</i> YEAR <i>1991</i>

Jones & Laughlin Steel Corporation / and TV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO.

7306

12951

GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333					1	R/T	F006	
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>Waste Mgmt. Officer</i>	DATE TO BE SHIPPED MONTH <i>9</i> DAY <i>16</i> YEAR <i>1991</i>	EXPECTED ARRIVAL DATE MONTH <i>9</i> DAY <i>16</i> YEAR <i>1991</i>
TRANSPORTER ID No. <i>29</i>	STATE <i>IN</i>	NUMBER <i>264712</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF <i>[Signature]</i>
			DATE RECEIVED MONTH <i>9</i> DAY <i>16</i> YEAR <i>1991</i>

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 256

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1 R61	T	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leslie</i>	TITLE Waste Management	DATE TO BE SHIPPED MONTH DAY YEAR 9 15 87	EXPECTED ARRIVAL DATE MONTH DAY YEAR 9 15 87
TRANSPORTER HWT ID No. 1171W 2178FR	STATE IN	NUMBER 1	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Y. Marking</i>
		DATE RECEIVED MONTH DAY YEAR 9 15 87	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

129

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1 R61	T	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND00546260
TRANSPORTER NO. 1	Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-391-2531		IND044250587
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	R	T	FOO
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: Robert O. Lerdice
TITLE: Waste Management
DATE TO BE SHIPPED: 10/28/87
EXPECTED ARRIVAL DATE: 11/2/87

TRANSPORTER'S SIGNATURE: J. Mark
TITLE: Manager
DATE RECEIVED: 10/28/87

STATE: IN NUMBER: 2785R

Jones & Laughlin Steel Corporation / and Company

HAZARDOUS WASTE MANIFEST

3 PART A

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND00546260
TRANSPORTER NO. 1	Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-391-2664		IND044250587
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2,700					1	ROL	T	FOO
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE: Robert O. Lerdice
TITLE: Waste Management
DATE TO BE SHIPPED: 10/28/87
EXPECTED ARRIVAL DATE: 11/2/87

TRANSPORTER'S SIGNATURE: J. Mark
TITLE: Manager
DATE RECEIVED: 10/28/87

STATE: IN NUMBER: 2785R

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12758

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1 RCL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Vugz</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 9 17 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 9 17 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>	DATE RECEIVED MONTH DAY YEAR 9/17/81		

YEAR AT THIS PERFORATION

1 PART B

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR 9/17/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons for And Disposition of Rejected Materials.

Handling Methc

1	D-21
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>J.F. Security</i>	DATE RECEIVED MONTH DAY YEAR 9-17-81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302 - 1275

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 259
12757

DOCUMENT NO. 7302

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2														
3														
4														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (ER)</i>	TITLE <i>Dept.'s Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>9/14/81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>9/14/81</i>
Transporter HWT ID No. <i>129</i>	STATE <i>IN</i>	NUMBER <i>2697R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>
			DATE RECEIVED MONTH DAY YEAR <i>9/14/81</i>

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR <i>9/14/81</i>
Transporter NO. HWT ID No. <i>129</i>	STATE <i>IN</i>
NUMBER <i>2697R</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	
DATE DELIVERED MONTH DAY YEAR	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Metho

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>J. H. Security</i>	DATE RECEIVED MONTH DAY YEAR <i>9-14-81</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302

- 12757

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 260

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	R/C	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE W.W. Oberster	DATE TO BE SHIPPED MONTH 11 DAY 11 YEAR 81	EXPECTED ARRIVAL DATE MONTH 9 DAY 11 YEAR 81
TRANSPORTER HWT ID No. 1171112121212121	STATE NUMBER IN 1171112121212121	TRANSPORTER NO. 1 SIGNATURE <i>[Signature]</i>	DATE RECEIVED MONTH 9 DAY 11 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1291

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	R/L	T	F006
2.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 8091
7306 12912

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE <i>W.W. O'Brien</i>	DATE TO BE SHIPPED MONTH <i>9</i> DAY <i>12</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>9</i> DAY <i>12</i> YEAR <i>81</i>
TRANSPORTER HWT ID No. <i>5292R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH <i>9</i> DAY <i>12</i> YEAR <i>81</i>	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12912

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 262

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X					1	ROL	T	F006
2.																
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Sharon Penney</i>	TITLE Waste Site Operator	DATE TO BE SHIPPED MONTH 9 DAY 10 YEAR 81	EXPECTED ARRIVAL DATE MONTH 9 DAY 10 YEAR 81
TRANSPORTER HWY ID No. 117 7A 27 15	STATE NUMBER IN 27 15	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Y. Martin</i>	DATE RECEIVED MONTH 9 DAY 10 YEAR 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1290

3 PART A		DOCUMENT NO. 7306	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X					1	ROL	T	F006
2.																
3.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

FILL OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80907

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	CONTAINERS TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	2.4	T	8006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE W. W. Pearson	DATE TO BE SHIPPED MONTH 9 DAY 8 YEAR 81	EXPECTED ARRIVAL DATE MONTH 9 DAY 8 YEAR 81
TRANSPORTER HWT 179	STATE IN	NUMBER 278362	TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
DATE RECEIVED MONTH 9 DAY 8 YEAR 81			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 129

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	CONTAINERS TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	2.4	T	8006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12756

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>S. Hays</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 9 9 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 9 81
Transporter HWT ID No. 182	STATE IN	NUMBER 249012	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
			DATE RECEIVED MONTH DAY YEAR 9 9 81

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>	DATE DELIVERED MONTH DAY YEAR 9 9 81
Transporter No. 2 HWT ID No.	STATE NUMBER
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons

For And Disposition of Rejected Materials.

Handling Meth.

1 081

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED

MONTH DAY YEAR

9 - 9 - 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 1275

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

7306

REFERENCE 80
Page 265

3 PART A

DOCUMENT NO.

1290

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	1700	X				1	Rel	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Leslie</i>	TITLE <i>Waste Manager</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>9 7 81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>9 7 81</i>
Transporter HWT ID No. <i>1290</i>	STATE <i>IN</i>	NUMBER <i>1</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
DATE RECEIVED MONTH DAY YEAR <i>7 7 81</i>			

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

1290

3 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	7333	X				1	Rel	T	F006
2.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	161 Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Barry Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	Rel	T	F006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Ladd</i>	TITLE <i>Material Manager</i>	DATE TO BE SHIPPED MONTH <i>9</i> DAY <i>9</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>9</i> DAY <i>9</i> YEAR <i>81</i>
TRANSPORTER STATE <i>IN</i> NUMBER <i>1202-2</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>	DATE RECEIVED MONTH <i>9</i> DAY <i>9</i> YEAR <i>81</i>	

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12901

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	161 Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Barry Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	Rel	T	F006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE DATE TO BE SHIPPED EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using a ballpoint pen. — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 267

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X	2700	X				1	ROL T	F006	
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>James P. ...</i>	TITLE Waste Mgmt. ...	DATE TO BE SHIPPED MONTH DAY YEAR 4 28 87	EXPECTED ARRIVAL DATE MONTH DAY YEAR 4 4 87
Transporter HWT ID No. 117 IN 2785 R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. ...</i>	DATE RECEIVED MONTH DAY YEAR 4 4 87	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen. — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1290

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X	2700	X				1	ROL T	F006	
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

12899

3 PART A

REFERENCE 80

Page 268

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN. NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	34	T	F006
2.															
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility; can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Lincic</i>	TITLE Vice President	DATE TO BE SHIPPED MONTH DAY YEAR 9/1/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 9/1/81
TRANSPORTER J&L Steel Corp.	STATE IN	NUMBER 12497C	TRANSPORTER'S SIGNATURE AND CERTIFICATION <i>John Smith</i>

Jones & Laughlin Steel Corporation / Inland Steel Company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

1289

3 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN. NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	34	T	F006
2.															
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named: The Treatment, Storage or Disposal Facility; can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

SIGNATURE TITLE DATE TO BE SHIPPED MONTH DAY YEAR EXPECTED ARRIVAL DATE MONTH DAY YEAR

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 1275!

1 PART A		DOCUMENT NO. 7302 - 1275!	
NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Rb11	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nye</i>	TITLE <i>Supt. office</i>	DATE TO BE SHIPPED MONTH DAY YEAR 9 3 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 9 3 81
Transporter HWT ID No. 129 EW 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Tarned</i>	DATE RECEIVED MONTH DAY YEAR 9/3/81	

YEAR AT THIS PERFORATION
YEAR AT THIS PERFORATION

1 PART B		DATE DELIVERED MONTH DAY YEAR 9/3/81	
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Tarned</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR	
Transporter No. 2 HWT ID No.	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.

Handling Method

1	D-21
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>9-3-81</i>	DATE RECEIVED MONTH DAY YEAR 9 3 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302 - 1275

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12751

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll		K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 8 31 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 31 81
Transporter HWT ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>
			DATE RECEIVED MONTH DAY YEAR 8/31/81

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR 8/31/81
Transporter HWT ID No. 2697R	DATE RECEIVED MONTH DAY YEAR 8/31/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Meth. 1 <i>D-2</i> 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>10 16 81</i>

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 1275

TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 271

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND00546260
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	X	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment as a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George Pannoy</i>	TITLE <i>Waste Water Operator</i>	DATE TO BE SHIPPED MONTH 8 DAY 28 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 28 YEAR 81
TRANSPORTER NWT D No. 12	STATE IN	NUMBER 916967	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Homa</i>
		DATE RECEIVED MONTH 8 DAY 28 YEAR 81	

Please TYPE or PRINT clearly, using ballpoint pen - PRESS HARD

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	ROL	X	F006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment as a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE
-----------------------	-------

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	REL		F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE	
<i>George Penney</i>		<i>W. J. Water Corp. T.</i>		MONTH DAY YEAR		MONTH DAY YEAR	
TRANSPORTER'S SIGNATURE		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED			
<i>James H. Hines</i>				MONTH DAY YEAR			

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND044250587	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	REL		F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE	
<i>George Penney</i>		<i>W. J. Water Corp. T.</i>		MONTH DAY YEAR		MONTH DAY YEAR	
TRANSPORTER'S SIGNATURE		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED			
<i>James H. Hines</i>				MONTH DAY YEAR			

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

JONES & LAUGHLIN STEEL CORPORATION / an L.P. company

HAZARDOUS WASTE MANIFEST

PART A

DOCUMENT NO. 7306

REFERENCE 80
Page 273

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3801 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7058	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	201	T	P006
1.															
1.															
1.															

if Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment
non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Leal</i>	TITLE <i>Manager</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>3 1 81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>3 21 81</i>
TRANSPORTER IWT	STATE IN	NUMBER 1171W27850	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. Martinez</i>
D No.	DATE RECEIVED MONTH DAY YEAR <i>3 31 81</i>		

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80
Page 274

PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	51 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056	Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>Robert A. Leslie</i>	<i>Manager</i>	MONTH DAY YEAR 8 25 81	MONTH DAY YEAR 8 25 81
TRANSPORTER'S SIGNATURE	RECEIPT OF SHIPMENT	DATE RECEIVED	
<i>J. Martinez</i>		MONTH DAY YEAR 8 25 81	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

1269

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	51 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056	Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

HAZARDOUS WASTE MANIFEST

7306

1286

3 PART A

REFERENCE 80
Page 275

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	HA9189				X	2700	X				1	ROL	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Lasko</i>	TITLE <i>General Manager</i>	DATE TO BE SHIPPED MONTH <i>8</i> DAY <i>26</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>8</i> DAY <i>26</i> YEAR <i>81</i>
TRANSPORTER HWT ID No. <i>117 IM 778 ER</i>	STATE <i>IN</i>	NUMBER <i>778 ER</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION ON RECEIPT OF SHIPMENT <i>J. Mantz</i>
			DATE RECEIVED MONTH <i>8</i> DAY <i>26</i> YEAR <i>81</i>

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1286

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	HA9189				X	2700	X				1	ROL	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Lasko</i>	TITLE <i>General Manager</i>	DATE TO BE SHIPPED MONTH <i>8</i> DAY <i>26</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>8</i> DAY <i>26</i> YEAR <i>81</i>
TRANSPORTER HWT ID No. <i>117 IM 778 ER</i>	STATE <i>IN</i>	NUMBER <i>778 ER</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION ON RECEIPT OF SHIPMENT <i>J. Mantz</i>
			DATE RECEIVED MONTH <i>8</i> DAY <i>26</i> YEAR <i>81</i>

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 12695 REFERENCE 80

Page 276

TYPE or PRINT clearly, using
point pen - PRESS HARD
PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
L. Steel Corp.	3001 Hickory Road East Chicago, IN 46312	219-397-1331	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
RY Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos.	12-ORM-E	NA9189				X	2700	X				1	20L	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment)
Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	W.W. Operation	8 24 81	8 24 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
<i>[Signature]</i>	8 24 81		

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 12695

TYPE or PRINT clearly, using
point pen - PRESS HARD
PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
L. Steel Corp.	3001 Hickory Road East Chicago, IN 46312	219-397-1331	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos.	12-ORM-E	NA9189				X	2700	X				1	20L	T	P006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment)
Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED EXPECTED ARRIVAL DATE

PLEASE TYPE OR PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

REFERENCE 80261

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664		IND044250587
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858		IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	QUANTITY	GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	R.C	T F00
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

SIGNATURE

TITLE

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

TELEPHONE NUMBER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT

DATE RECEIVED

TO BE FILLED OUT BY GENERATOR

Jones & Laughlin Steel Corporation / an I.T.V. company

PLEASE TYPE OR PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306 - 1261

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312			219-397-2664		IND044250587
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406			219-944-7858		IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	QUANTITY	GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	333	X				1	R.C	T F00
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE

TITLE

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 278

NAME GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X			1	Ro	T	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Water Oper	DATE TO BE SHIPPED MONTH DAY YEAR 2/22/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2/22/81
TRANSPORTER'S SIGNATURE <i>[Signature]</i>	TITLE John R. R... RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR 2/22/81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

126

NAME GENERATOR J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3,333	X			1	Ro	T	F
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 126
REFERENCE 8026

3 PART A

GENERATOR NAME	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1 Rol	T	FOH
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Water Operator	8/23/87	8/23/87
TRANSPORTER'S SIGNATURE	DATE RECEIVED		
<i>[Signature]</i>	8/23/87		

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 126

3 PART A

GENERATOR NAME	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2200	X				1 Rol	T	FOH
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>			

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 280

3 PART A	NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	1200-ORM-E	NA9189				X	2700	X				1 ROL	T	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George R. ...</i>	TITLE Waste Mgmt. ...	DATE TO BE SHIPPED MONTH 8 DAY 21 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 21 YEAR 81
TRANSPORTER HWT ID No. 100	STATE IN	NUMBER 278152	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. ...</i>
		DATE RECEIVED MONTH 8 DAY 21 YEAR 81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12689

3 PART A	NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1 ROL	T	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

12688

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700 X					1	Ro	T	R006
2.															
3.															
4.															

5. Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	Waste Mgmt. Officer	8/21/81	8/21/81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED		
<i>[Signature]</i>	8/21/81		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

12687

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700 X					1	Ro	T	R006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

TITLE

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12750

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Vargo</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 8 20 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 20 81
TRANSPORTER HWT ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kovach</i>
			DATE RECEIVED MONTH DAY YEAR 8/20/81

YEAR AT THIS PERFORMANCE

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kovach</i>		DATE DELIVERED MONTH DAY YEAR 8/20/81
TRANSPORTER No. 2 HWT ID No.	STATE NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.		Handling Method 1 D-2 2 3 4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>William R. Gorman</i>	TITLE <i>Watch MEN</i>	DATE RECEIVED MONTH DAY YEAR 8 20 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302 - 12750

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 283

3 PART A		DOCUMENT NO. 7306					
GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.			
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601			
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587			
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077009916			
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE							
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>							
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM SOLID LIQUID GAS SLUDGE	QUANTITY GALLONS CU YDS POUNDS TONS	CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189	X	2700	X	1 Ro	T P006
2.							
3.							
4.							
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment) Non-Hazardous Nature Which Do Not Have to be Manifested.)							
Central Waste Treatment Plant Sludge							
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.							
GENERATOR'S SIGNATURE		DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR				
W.W. O'Connell		8 19 81		8 19 81			
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED MONTH DAY YEAR					
John R. ...		8 19 81					

Jones & Laughlin Steel Corporation / an LTV Company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 12683

3 PART A		DOCUMENT NO. 7306 - 12683					
GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.			
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601			
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587			
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916			
IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE							
This Form Is No. <input type="checkbox"/> Out Of A Total Of <input type="checkbox"/> The First Manifest Document No. Is <input type="checkbox"/>							
PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM SOLID LIQUID GAS SLUDGE	QUANTITY GALLONS CU YDS POUNDS TONS	CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189	X	2700	X	1 Ro	T P006
2.							
3.							
4.							
Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment) of a Non-Hazardous Nature Which Do Not Have to be Manifested.)							
Central Waste Treatment Plant Sludge							
GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.							

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80268

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 51 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	ROL	T	FO00
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE W.W. O'Peaton	DATE TO BE SHIPPED MONTH 8 DAY 20 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 20 YEAR 81
TRANSPORTER'S SIGNATURE <i>[Signature]</i>	TITLE John [Name]	DATE RECEIVED MONTH 8 DAY 20 YEAR 81	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / and its company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1268

3 PART A

GENERATOR NAME J&L Steel Corp.	SITE ADDRESS 3001 Dickey Road East Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425058
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	FO06
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE [Name]	DATE TO BE SHIPPED MONTH 8 DAY 20 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 20 YEAR 81
TRANSPORTER'S SIGNATURE <i>[Signature]</i>	TITLE [Name]	DATE RECEIVED MONTH 8 DAY 20 YEAR 81	

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12309

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RSL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Hagg</i>	TITLE <i>Supt. Chem</i>	DATE TO BE SHIPPED MONTH 8 DAY 17 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 17 YEAR 81
Transporter HWT ID No. <i>129</i>	STATE <i>IN</i>	NUMBER <i>2697R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>
			DATE RECEIVED MONTH 8 DAY 17 YEAR 81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>	DATE DELIVERED MONTH 8 DAY 17 YEAR 81
Transporter No. 2 HWT ID No. <i>129</i>	STATE <i>IN</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>	DATE RECEIVED MONTH 8 DAY 17 YEAR 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH 8 DAY 17 YEAR 81
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	
Handling Meth 1 D-2 2 3 4	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Watchman</i>	DATE RECEIVED MONTH 8 DAY 17 YEAR 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637	

DOCUMENT NO. 7302 - 1230

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

REFERENCE 80

Page 286

3 PART A

DOCUMENT NO.

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312 2	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6036 Gary, IN 46400	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	ROL	T	FOO
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	W. W. O'PRA... A T O N	8 16 81	8 16 81
TRANSPORTER HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
117	IN	27958	<i>[Signature]</i>
			DATE RECEIVED
			8 16 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

126

3 PART A

GENERATOR	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road	East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6036 Gary, IN 46400	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	FOO
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

3 PART A

REFERENCE 8058

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04425056
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	DALLONS	CUYDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X			1	ROL	T	FOO
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O. Lesch	TITLE Vice President	DATE TO BE SHIPPED MONTH DAY YEAR 8 28 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 28 81
TRANSPORTER HWT ID No. 1177M 278JA	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT J. Martz	DATE RECEIVED MONTH DAY YEAR 8 28 81	

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1268

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	DALLONS	CUYDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X			1	ROL	T	FOO
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE

REFERENCE 80

Page 288

3 PART A

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312 2	219-391-2531	IND044250587		
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	Gary, IN 46406	219-944-7858	IND077005916		

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X		3333	X			1	ROL	T	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	W. W. Olenick	8 14 81	8 14 81
Transporter	STATE	NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
117	IN	272	<i>[Signature]</i>

Jones & Laughlin Steel Corporation / and its company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO.

7306 - 1247

GENERATOR NAME	J&L Steel Corp.	SITE ADDRESS	3001 Dickey Road East Chicago, IN 46312	PHONE NO.	219-391-2531	EPA I.D. NO.	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59	East Chicago, IN 46312	219-397-2664	IND044250587		
TRANSPORTER NO. 2 (IF ANY)							
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056	Gary, IN 46406	219-944-7858	IND077005916		

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X		2,700	X			1	ROL	T	F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306
REFERENCE 80121

3 PART A		NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.	
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND0442501	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WA TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. HAZARDOUS WASTE Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	FC
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE	
<i>[Signature]</i>		W.W. Operation		8/15/81		8/15	
TRANSPORTER SIGNATURE		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED		MONTH DAY YEAR	
<i>[Signature]</i>		<i>[Signature]</i>		8/15			

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 12

NAME		SITE ADDRESS		PHONE NO.		EPA I.D. NO.			
GENERATOR		J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531		IND005462601	
TRANSPORTER NO. 1		Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-2664		IND04425058	
TRANSPORTER NO. 2 (IF ANY)									
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development		P.O. Box 6056 Gary, IN 46406		219-944-7858		IND077005916	

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WA TY
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	FC
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE		TITLE		DATE TO BE SHIPPED		EXPECTED ARRIVAL DATE	
<i>[Signature]</i>				8/15/81		8/15	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12301

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nuzzo</i>	TITLE <i>Supt. Ck</i>	DATE TO BE SHIPPED MONTH 8 DAY 13 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 13 YEAR 81
Transporter HWT ID No. 22 F/V 9/6/91	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>	DATE RECEIVED MONTH 8 DAY 13 YEAR 81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>	DATE DELIVERED MONTH 8 DAY 13 YEAR 81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methc

1	D81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Jack B. B...</i>	TITLE <i>Watchman</i>	DATE RECEIVED MONTH DAY YEAR <i>81</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302 - 12301

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1246

REFERENCE 80
Page 291

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2,700	X				1	ROL	P006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	WASTE WATER OPERATOR	8/13/81	8/13/81
TRANSPORTER SIGNATURE	DATE RECEIVED		
<i>[Signature]</i>	8/13/81		

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 1246

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	P006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

3 PART A

REFERENCE 80

Page 292

GENERATOR J&L Steel Corp.	SITE ADDRESS Dickey Road Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND0442505
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	261	T	W00
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>J.J. Gaillo</i>	TITLE <i>W.W. Operator</i>	DATE TO BE SHIPPED MONTH <i>8</i> DAY <i>13</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>8</i> DAY <i>13</i> YEAR <i>81</i>
TRANSPORTER FMT ID No. <i>117-1141279121</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. Watkins</i>	DATE RECEIVED MONTH <i>8</i> DAY <i>13</i> YEAR <i>81</i>	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 124

3 PART A

GENERATOR J&L Steel Corp.	SITE ADDRESS Dickey Road Chicago, IN 46312	PHONE NO. 219-391-2531	EPA I.D. NO. IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X					1	Rel	T	FC
2.																
3.																
4.																

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included In Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>J.J. Gaillo</i>	TITLE <i>W.W. Operator</i>	DATE TO BE SHIPPED MONTH <i>8</i> DAY <i>13</i> YEAR <i>81</i>	EXPECTED ARRIVAL DATE MONTH <i>8</i> DAY <i>13</i> YEAR <i>81</i>
---	-------------------------------	---	--

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

This Form Is No. _____	Out Of A Total Of _____	The First Manifest Document No. Is _____
------------------------	-------------------------	--

MOORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

3 PART A
a ballpoint pen - PRESS HARD
HAZARDOUS WASTE MANIFEST
DOCUMENT NO. 7306
1245

Jones & Laughlin Steel Corporation / an LTV company

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

ease TYPE or PRINT clearly, using ballpoint pen — PRESS HARD

3 PART A

DOCUMENT NO. 7306 - 12451

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7838	IND077005916

MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

[illegible]

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Robert O. Lutz</i>		TITLE <i>Master water oper</i>		DATE TO BE SHIPPED MONTH <i>3</i> DAY <i>13</i> YEAR <i>51</i>		EXPECTED ARRIVAL DATE MONTH <i>9</i> DAY <i>17</i> YEAR <i>51</i>	
TRANSPORTER WT <i>129</i>		STATE <i>IN</i>		TRANSPORTER NO. 1 SIGNATURE AND LOCATION OF RECEIPT OF SHIPMENT <i>John F. ...</i>		DATE RECEIVED MONTH <i>3</i> DAY <i>17</i> YEAR <i>51</i>	
3 No <i>129</i>		NUMB <i>21</i>					

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

12441

REFERENCE 80
Page 295

3 PART A

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&I Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Res	1200RM-E	NA9189				X	2700	X				1	R6	T F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	W.W. Orkston	8 5 81	8 5 81

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED
<i>[Signature]</i>	8 5 81

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

12441

GENERATOR NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&I Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Res	12-0RM-E	NA9189				X	2,700	X				1	R6	T F006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>		8 5 81	8 5 81

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED
<i>[Signature]</i>	8 5 81

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1244

REFERENCE 80
Page 296

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	Roll	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O. Leslie	TITLE Manager	DATE TO BE SHIPPED MONTH DAY YEAR 6 21 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 6 81
Transporter ID No. 122	STATE IN	NUMBER 71690	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT James H. Homan
		DATE RECEIVED MONTH DAY YEAR 8 6 81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1244

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	Roll	T	F006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE J. O. Leslie	TITLE Manager	DATE TO BE SHIPPED MONTH DAY YEAR 6 21 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 6 81
---------------------------------------	------------------	---	---

base TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7306

12443

REFERENCE 80
Page 297

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
Hazardous Waste Liquid or Solid Nos.	12-ORM-E	NA9189				X	2700	X			1 ROL	T	F006
2.													
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>[Signature]</i>	Waste Manager	8/3/81	8/3/81
TRANSPORTER'S SIGNATURE	DATE RECEIVED MONTH DAY YEAR		
<i>[Signature]</i>	8/3/81		

Jones & Laughlin Steel Corporation / and its company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 1244

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS			
Hazardous Waste Liquid or Solid Nos.	12-ORM-E	NA9189				X	2700	X			1 ROL	T	F006
2.													
3.													
4.													

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
8/3/81	8/3/81

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

1244

REFERENCE 80
Page 298

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044230587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	ROL	T	P006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

73

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
Robert O. Leslie	Manager	MONTH 3 DAY 11 YEAR 81	MONTH 8 DAY 3 YEAR 81
TRANSPORTER SIGNATURE	STATE	NUMBER	DATE RECEIVED
J. Murphy	IN	10 2785R	MONTH 8 DAY 3 YEAR 81

Jones & Laughlin Steel Corporation / and its company

Please TYPE or PRINT clearly, using a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

1244

3 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND0770051

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	P006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12308

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR			
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1			
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Hugo</i>		TITLE <i>Supt. Cke</i>	DATE TO BE SHIPPED MONTH DAY YEAR 8 13 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 13 81
Transporter HWT ID No. 22	STATE IN	NUMBER 9690	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Hume</i>	DATE RECEIVED MONTH DAY YEAR 8 13 81

1 PART B

YEAR AT THIS PERFORATION

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Hume</i>			DATE DELIVERED MONTH DAY YEAR 8 13 81
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE RECEIVED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.			Handling Methc 1 D81
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Jack Bushman</i>			TITLE <i>Watchman</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637			DATE RECEIVED MONTH DAY YEAR 8 13 81

DOCUMENT NO.

7302 - 12308

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80

Page 300

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	R006
2.															
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George Penner</i>	TITLE <i>Waste Water Operator</i>	DATE TO BE SHIPPED MONTH DAY YEAR 8 12 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 12 81
TRANSPORTER HWT ID NO. 117	STATE IN	NUMBER 27	DATE RECEIVED MONTH DAY YEAR 8 12 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1241

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	FO
2.															
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Pl. Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED

EXPECTED ARRIVAL DATE

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 12464

3	PART A			
NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59			
Industrial Disposal Corp.	East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056		219-944-7856	IND077005916
Gary Land Development	Gary, IN 46406			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CU YDS	POUNDS	TONS	GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333				X				1 RCL	T	7006
2																	
3																	
4																	

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
<i>[Signature]</i>	<i>W.W. Roston</i>	7/11/81	8/12/81
TRANSPORTER'S SIGNATURE	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	
<i>[Signature]</i>	<i>[Signature]</i>	8/12/81	

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

3 PART A

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306 - 12464

NAME	SITE ADDRESS		PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.		219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59			
Industrial Disposal Corp.	East Chicago, IN 46312		219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056		219-944-7856	IND077005916
Gary Land Development	Gary, IN 46406			

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY				UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE	GALLONS	CU YDS	POUNDS	TONS	GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700				X				1 RCL	T	70
2																	
3																	
4																	

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80
Page 302

3 PART A

DOCUMENT NO. 7306

1245

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	P006
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WATER OPERATOR	DATE TO BE SHIPPED MONTH 8 DAY 10 YEAR 81	EXPECTED ARRIVAL DATE MONTH 9 DAY 10 YEAR 81
TRANSPORTER HWT ID No. 11977M 33458	STATE IN	NUMBER 33458	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
		DATE RECEIVED MONTH 8 DAY 10 YEAR 81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

1245

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T	P006
2.															
3.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 80

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	4334	X				1	Box	T	FO06
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Robert O. Leibel	TITLE Masteroperator	DATE TO BE SHIPPED MONTH 8 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 16 YEAR 81
TRANSPORTER HWT ID No. 17007	STATE IN	NUMBER 7060	TRANSPORTER'S SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT James M. Thomas

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

3 PART A

DOCUMENT NO. 7306

1246

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2760	X				1	Box	T	FO06
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e., Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

REFERENCE 80

Page 304

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste														
Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X				1	ROL	T
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
George Pannoy	Unit Unit Operator	3 10 81	3 10 81
TRANSPORTER SIGNATURE	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED	
Ball		3 10 81	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7306

124

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste														
Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X				1	ROL	T
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE
-----------------------	-------	--------------------	-----------------------

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

REFERENCE 1845
Page 305

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X			1	ROL	T	F006
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>George P. Riney</i>		TITLE <i>Waste Water Operator</i>	DATE TO BE SHIPPED MONTH 8 DAY 9 YEAR 87	EXPECTED ARRIVAL DATE MONTH 8 DAY 9 YEAR 87
Transporter HWT ID No. 12471M12175K	STATE IN	NUMBER 12175K	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>J. Marking</i>	

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST DOCUMENT NO. 7306 1245

3 PART A		NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR		J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1		Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)					
TREATMENT, STORAGE OR DISPOSAL FACILITY		Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		BALLONS	CU YDS	POUNDS				TONS
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3335	X			1	ROL	T	F006
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA, and the State. The wastes described above were consigned to the Transporter named, The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

DATE TO BE SHIPPED: MONTH 8 DAY 9 YEAR 87
EXPECTED ARRIVAL DATE: MONTH 8 DAY 9 YEAR 87

TO BE FILLED OUT BY GENERATOR

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12307

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR			
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1			
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-391-2531	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY			
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RoL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>		TITLE <i>Gen'l Mgr</i>		DATE TO BE SHIPPED MONTH DAY YEAR 8 10 81		EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 10 81	
Transporter HWT ID No. 122	STATE IA	NUMBER 2490		TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Lance Horn</i>		DATE RECEIVED MONTH DAY YEAR 8 10 81	

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Lance Horn</i>		DATE DELIVERED MONTH DAY YEAR 8 10 81	
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1	DRI
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION
BRIAN BOYD

TITLE
CA

DATE RECEIVED
MONTH DAY YEAR
8 10 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 12307

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen --PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302

12306

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Huggs</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH 8 DAY 3 YEAR 81	EXPECTED ARRIVAL DATE MONTH 8 DAY 3 YEAR 81
Transporter HWT ID No. 179 IN 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>	DATE RECEIVED MONTH 8 DAY 3 YEAR 81	

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH 8 DAY 3 YEAR 81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth.

1	D-21
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>J.P. Security 8-7-81</i>	DATE RECEIVED MONTH 8 DAY 7 YEAR 81
--	--------------------------------------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

1230

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

Use TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7306

REFERENCE 80
Page 308

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	2700	X			1	REL	T	7006
2.														
3.														
4.														

5. Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Management	DATE TO BE SHIPPED MONTH DAY YEAR 8 1 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 1 81
TRANSPORTER I.D. No. 112 721 722 52	STATE NUMBER IN 01	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH DAY YEAR 8 1 81

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

DOCUMENT NO. 7306 1244

3 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS		EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	NO.	TYPE		
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3333	X			1	REL	T	7006
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE Waste Management	DATE TO BE SHIPPED MONTH DAY YEAR 8 1 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 8 1 81
---	---------------------------	--	---

GENERATOR		SITE ADDRESS		PHONE NO.	EPA ID NO.
J&L Steel Corp.		3001 Dickey Road East Chicago, IN 46312		219-391-2531	IND005662601
Industrial Disposal Corp.		P.O. Box 59 East Chicago, IN 46312		219-397-1664	IND044250587
TREATMENT, STORAGE OR DISPOSAL FACILITY		P.O. Box 6056 Gary, IN 46406		219-944-7858	IND077005966

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS			CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS				
Hazardous Waste Liquid or Solid Res	12-ORM-F	NA9189					3,333				1	ROL	T	T006

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested)

Central Waste Treatment Plant Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>[Signature]</i>	TITLE WASTE WAREHOUSE OPERATOR	DATE TO BE SHIPPED MONTH 8 DAY 1 YEAR 87	CHECKED ARRIVAL DATE MONTH 8 DAY 1 YEAR 87
TRANSPORTER HMT ID No. 111711272852	STATE IN	NUMBER 111711272852	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>
		DATE RECEIVED MONTH 8 DAY 1 YEAR 87	

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302

Page 03070

Please TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RCL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Hugg</i>	TITLE <i>Sgt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 7 31 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7 31 81
Transporter HWT ID No.	STATE IN	NUMBER 2692R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>
		DATE RECEIVED MONTH DAY YEAR 7 31 81	

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR 7 31 81
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE RECEIVED MONTH DAY YEAR 7 31 81
			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1	D81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Baron D. Boyd</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 7 31 81
---	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0307

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 03069

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROLL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH 7 DAY 24 YEAR 81	EXPECTED ARRIVAL DATE MONTH 7 DAY 24 YEAR 81
Transporter HWT ID No. 129	STATE IN	NUMBER 22972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>
			DATE RECEIVED MONTH 7 DAY 24 YEAR 81

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH 7 DAY 24 YEAR 81
Transporter No. 2 HWT ID No. 129	STATE IN
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH 7 DAY 24 YEAR 81
TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1 D-2 2 3 4
---	---

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE <i>JK</i>	DATE RECEIVED MONTH 7 DAY 24 YEAR 81
--	--------------------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0306

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12301

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Noy</i>	TITLE <i>Sgt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 7 20 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7 20 81
TRANSPORTER HWT ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kavech</i>
			DATE RECEIVED MONTH DAY YEAR 7/20/81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kavech</i>	DATE DELIVERED MONTH DAY YEAR 7/20/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Mett

1 D-2

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>33 R LAY BOYD</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 7-20-81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302

- 12301

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos.	12-ORM-E	NA9189					300					1 RSL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Perry</i>	TITLE <i>Sgt. Chief</i>	DATE TO BE SHIPPED MONTH 7 DAY 14 YEAR 81	EXPECTED ARRIVAL DATE MONTH 7 DAY 14 YEAR 81
Transporter HWT ID No. 118	STATE IN	NUMBER 92692A	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
			DATE RECEIVED MONTH 7 DAY 14 YEAR 81

TEAR AT THIS PERFORATION

1 PART B

TO BE FILLED OUT BY TRANSPORTER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>	DATE DELIVERED MONTH 7 DAY 14 YEAR 81
	Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE DELIVERED MONTH DAY YEAR
	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TO BE FILLED OUT BY TSD FACILITY	Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	
	Handling Method 1. D81	
	2.	
	3.	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyo</i>		DATE RECEIVED MONTH 7 DAY 14 YEAR 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO.

7302 - 1230

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 12303

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Ray</i>	TITLE <i>Supt. Chem</i>	DATE TO BE SHIPPED MONTH DAY YEAR 7 10 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7 10 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Trench</i>	DATE RECEIVED MONTH DAY YEAR 7/10/81		

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Trench</i>	DATE DELIVERED MONTH DAY YEAR 7/10/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Trench</i>	DATE DELIVERED MONTH DAY YEAR 7/10/81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
for And Disposition of Rejected Materials.

Handling Method

1	D.E.
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 7-10-81
--	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 12303

GD-675 7-84



To Carl Broman
Superintendent, Environmental Control Dept.
LTV Steel Company Indiana Harbor Works

Date November 19, 1987	Subject HAZARDOUS WASTE MANIFEST - DOCUMENT NO. <u>7302</u> - 03200
---------------------------	--

Message: COPY 1 PART A was lost in system. Attached is a photo copy of COPY 2 PART A,
and COPY 1 PART B.

To Avoid Errors Write it!

Madeline T. Zart
Signed Madeline T. Zart, Secretary

LTV Steel Co. Indiana Harbor Works
District-Division

Please TYPE or PRINT clearly, using
a ballpoint pen or PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0320016

2 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-391-2531	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7358	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>John R. Clark</i>	<i>Dept. Clerk</i>	7 6 81	7 6 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR	
<i>John R. Clark</i>	<i>John R. Clark</i>	7/6/81	

TEAR AT THIS PERFORATION

1 PART B	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
<i>John R. Clark</i>		7/6/81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
<i>John R. Clark</i>	<i>John R. Clark</i>	7/6/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR
<i>John R. Clark</i>		7/6/81
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method	
	1 D-31	
	2	
	3	
	4	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION	TITLE	DATE RECEIVED MONTH DAY YEAR
<i>John R. Clark</i>		7 6 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-2802 AND THE STATE . PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 782-9378; IND. (317) 633-0683; ILL. (217) 782-3637		7302 - 03200

DOCUMENT NO.

GD-675 7-84

LTV Steel

To _____

Date November 19, 1987 Subject HAZARDOUS WASTE MANIFEST - DOCUMENT NO. 7302 - 12301

Message: COPY 1 PART A was lost in system. Attached is a photo copy of COPY 2 PART A,
and COPY 1 PART B.

Madeline T. Zart
Signed Madeline T. Zart, Secretary

LTV Steel Co. Indiana Harbor Works
District-Division

To Avoid Errors Write it!

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302

12301

Please TYPE or PRINT clearly, using
a ballpoint pen or PRESS HARD

PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR V&V Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7853	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	26	T	K087
2.															
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Jim Edwards</i>	TITLE Gen Foreman	DATE TO BE SHIPPED MONTH DAY YEAR 7/3/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7/3/81
Transporter HWT ID No. 129	STATE IN	NUMBER 24972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kovach</i>
			DATE RECEIVED MONTH DAY YEAR 7/3/81

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kovach</i>			DATE DELIVERED MONTH DAY YEAR 7/3/81
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
			DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.

Handling Method

1	D-31
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Brian Boyd</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 7-3-81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		7302 - 12301
B & M. DOCUMENT NO.		

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 02078

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-GRM-E	NA9189				X	3.000	X				1	ROL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Steve Nagy (ER)	TITLE Super's Clerk	DATE TO BE SHIPPED MONTH DAY YEAR 7-1-81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 7-1-81
Transporter HWT ID No. 19214	STATE IN	NUMBER 249012	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT James Hanna
			DATE RECEIVED MONTH DAY YEAR 7-1-81

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT James Hanna	DATE DELIVERED MONTH DAY YEAR 7-1-81
Transporter No. 2 HWT ID No. 19214	STATE IN
NUMBER 249012	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT James Hanna
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR 7-1-81
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1 D81 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION BREA N Boyd	TITLE R. M. 7-1-81
DATE RECEIVED MONTH DAY YEAR 7-1-81	DOCUMENT NO. 7302 - 0207

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302

03197

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 6 26 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 6 26 81
Transporter ID No. 129 EN 2697R	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Rameck</i>

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Rameck</i>	DATE DELIVERED MONTH DAY YEAR 6/26/81
Transporter ID No. 129 EN 2697R	STATE IN
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR 6/26/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1 D-21

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED

MONTH DAY YEAR

6-26-81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302

03197

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid Nos	12-GRM-E	HA9189				X	3000	X					1	Rel T	K087
2															
3															
4															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (ER)</i>		TITLE <i>Superintendent</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>6/22/81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>6/22/81</i>
TRANSPORTER HWT ID No. <i>129</i>	STATE <i>IN</i>	NUMBER <i>2697R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowak</i>	DATE RECEIVED MONTH DAY YEAR <i>6/22/81</i>

TEAR AT THIS PERFORATION

1 PART B			DATE DELIVERED MONTH DAY YEAR <i>6/22/81</i>
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowak</i>			DATE RECEIVED MONTH DAY YEAR <i>6/22/81</i>
TRANSPORTER No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D-E
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYD</i>	TITLE	DATE RECEIVED MONTH DAY YEAR <i>6-22-81</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302

-0207

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302

02076

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3,000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (ER)</i>	TITLE <i>Supr's Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 6 9 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 6 9 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>	DATE RECEIVED MONTH DAY YEAR 6/9/81		

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>	DATE DELIVERED MONTH DAY YEAR 6/9/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D-2
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYD</i>	TITLE <i>6-9-81</i>	DATE RECEIVED MONTH DAY YEAR 6 9 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO.

7302

-0207

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0306

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1 ROL-T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 6-4-81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 6-4-81
Transporter HWT ID No. 192	STATE IN	NUMBER 268912	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
		DATE RECEIVED MONTH DAY YEAR 6-7-81	

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>		DATE DELIVERED MONTH DAY YEAR 6-4-81
Transporter No. 2 HWT ID No.	STATE IN	NUMBER 268912
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>		DATE RECEIVED MONTH DAY YEAR 6-7-81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR 6-7-81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	08
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRTAN 0300</i>	TITLE <i>St. Security 6-4-81</i>	DATE RECEIVED MONTH DAY YEAR 6-4-81
--	-------------------------------------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0306

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 324
7302 - 0182

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. BOX 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>6-1-81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>6-1-81</i>
Transporter HWT ID No. <i>134 IWX 21697R</i>	STATE <i>IN</i>	NUMBER <i>21697R</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
			DATE RECEIVED MONTH DAY YEAR <i>6-1-81</i>

1 PART B

TEAR AT THIS PERFORATION

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>	DATE DELIVERED MONTH DAY YEAR <i>6-1-81</i>
Transporter No. 2 HWT ID No. <i>134 IWX 21697R</i>	STATE <i>IN</i>
NUMBER <i>21697R</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	
DATE DELIVERED MONTH DAY YEAR <i>6-1-81</i>	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth.

1	<i>DS</i>
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BORTAN BOYD</i>	TITLE <i>J. H. density</i>	DATE RECEIVED MONTH DAY YEAR <i>6-1-81</i>
--	--------------------------------------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0182

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7302 - 03196

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 (IF ANY) INDUSTRIAL DISPOSAL CORP. Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form is No. ☐Out Of A Total Of ☐The First Manifest Document No. is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 6 18 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 6 18 81
Transporter HWT ID No. 122 STATE IN NUMBER 9689	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Roma</i>	DATE RECEIVED MONTH DAY YEAR 6 18 81	

TO BE FILLED OUT BY TRANSPORTER

TEAR AT THIS PERFORATION

1 PART B	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Roma</i>	DATE DELIVERED MONTH DAY YEAR 6 18 81
Transporter No. 2 HWT ID No. STATE NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR

TO BE FILLED OUT BY TSD FACILITY

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1 D81 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYD</i>	TITLE <i>TEA</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE - PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637	DATE RECEIVED MONTH DAY YEAR 6 18 81

DOCUMENT NO.

7302 - 03196

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-991-2531	IND065462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1 RoL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5/29/81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5/29/81
Transporter HWT ID No. 129	STATE IN	NUMBER 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowach</i>
			DATE RECEIVED MONTH DAY YEAR 5/29/81

YEAR AT THIS PERFORMANCE

1 PART B			
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowach</i>			DATE DELIVERED MONTH DAY YEAR 5/29/81
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
			DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.			Handling Meth. 1 D-3 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>W. L. Boyd</i>		TITLE	DATE RECEIVED MONTH DAY YEAR 5-28-81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637			

DOCUMENT NO. 7302

- 0182

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0208

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	4000	X				1 RoL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)**#2 Tar Decanter Sludge**

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Vago</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH 5 DAY 26 YEAR 81	EXPECTED ARRIVAL DATE MONTH 5 DAY 26 YEAR 81
Transporter HWT ID No. 129	STATE IN	NUMBER EL97R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowach</i>
			DATE RECEIVED MONTH 5 DAY 26 YEAR 81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowach</i>	DATE DELIVERED MONTH 5 DAY 26 YEAR 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH 5 DAY 26 YEAR 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE DELIVERED MONTH 5 DAY 26 YEAR 81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

D-2

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>M. Lopez</i>	TITLE <i>Clerk</i>	DATE RECEIVED MONTH 5 DAY 26 YEAR 81
--	-----------------------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0208

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

7302

- 02071

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312-	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	REL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)**Tar Decanter Sludge**

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Napp</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>5/26/81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>5/26/81</i>
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Tward</i>	DATE RECEIVED MONTH DAY YEAR <i>5/26/81</i>		

TEAR AT THIS PERFORATION
TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Tward</i>	DATE DELIVERED MONTH DAY YEAR <i>5/26/81</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method <i>D.81</i>
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BORIS IV 120112</i>	DATE RECEIVED MONTH DAY YEAR <i>5-26-81</i>

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

- 02071

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	20L	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagel</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5 22 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 22 81
Transporter HWT ID No. 1302M E 49204	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Brown</i>	DATE RECEIVED MONTH DAY YEAR 5 22 81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Brown</i>	DATE DELIVERED MONTH DAY YEAR 5 22 81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR 5 22 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Meth 1 08 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BURTON BOYD</i>	TITLE DATE RECEIVED MONTH DAY YEAR 5 22 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637	

DOCUMENT NO.

7302 - 0182

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

Page 330
7302 02075

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	ROL	T	K087
2.															
3.															
4.															

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Hagg</i>		TITLE <i>Gen. Mgr.</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5 22 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 22 81
Transporter HWT ID No. 122	STATE IN	NUMBER 2694	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Bob Delephant</i>	
			DATE RECEIVED MONTH DAY YEAR 5 22 81	

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Bob Delephant</i>			DATE DELIVERED MONTH DAY YEAR 5 22 81
Transporter No. 2 HWT ID No. 110	STATE IN	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE RECEIVED MONTH DAY YEAR 5 22 81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D-81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BOB DELEPHANT</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 5 22 81
---	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0207

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - ~~NEVER~~ HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 02074

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				I	3000	I				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Napp</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5 18 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 18 81
Transporter HWT ID No. 1321N 7099K	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Brown</i>	DATE RECEIVED MONTH DAY YEAR 5 18 81

1 PART B

YEAR AT THIS PERFORMANCE

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Brown</i>	DATE DELIVERED MONTH DAY YEAR 5 18 81
Transporter No. 2 HWT ID No.	STATE NUMBER
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	081
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>ROZAN ROYAL</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 5 18 81
---	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0207

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 332
0182

DOCUMENT NO. 7302

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	4000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE Supt. Clerk	DATE TO BE SHIPPED MONTH DAY YEAR 5 18 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 18 81
Transporter HWT ID No. 129 IN 26972	STATE IN	NUMBER 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>
			DATE RECEIVED MONTH DAY YEAR 5/18/81

YEAR AT THIS PERFORATION

1 PART B

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR 5/18/81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE DELIVERED MONTH DAY YEAR
TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth.

1	D-81
2	
3	
4	6761

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED
MONTH DAY YEAR
5 18 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0182

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

Page 333
7302 0207

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Asst. Chl</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5-18-81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5-18-81
Transporter HWT ID No. 130 IN 269814	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Rom</i>	DATE RECEIVED MONTH DAY YEAR 5-18-81	

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Rom</i>	DATE DELIVERED MONTH DAY YEAR 5-18-81
Transporter No. 2 HWT ID No.	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	DY
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BOYD</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 5-18-81
--	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

RC - 0207

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X		3000	X				1 RSL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5 15 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 15 81
Transporter HWT ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Trench</i>
			DATE RECEIVED MONTH DAY YEAR 5/15/81

TEAR AT THIS PERFORATION

1 PART B	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Trench</i>	DATE DELIVERED MONTH DAY YEAR 5/15/81
Transporter No. 2 HWT ID No.	STATE IN	NUMBER 2697R
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED MONTH DAY YEAR 5/15/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR 5/15/81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methd

1	D-81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>M. E. Lopez</i>	TITLE <i>Clerk</i>	DATE RECEIVED MONTH DAY YEAR 5/15/81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		
DOCUMENT NO.		7302 - 0182

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 335
7302 01811

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. Out Of A Total Of The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RGL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steel Mogy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5 14 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 14 81
Transporter HWT ID No. 129 IN 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kovach</i>	DATE RECEIVED MONTH DAY YEAR 5/14/81	

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kovach</i>	DATE DELIVERED MONTH DAY YEAR 5/14/81
Transporter No. 2 HWT ID No.	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D-2
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BREAN BLYD</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 5-14-81
--	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0181

Please TYPE or PRINT clearly, using
a ballpoint pen— PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 336
7302 - 0181

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	4000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 5 14 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5 14 81
Transporter HWT ID No. 129	STATE IN	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Turchi</i>
			DATE RECEIVED MONTH DAY YEAR 5/14/81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Turchi</i>	DATE DELIVERED MONTH DAY YEAR 5/14/81
Transporter HWT ID No. 129	STATE IN
NUMBER 2697R	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	
DATE RECEIVED MONTH DAY YEAR 5/14/81	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D.81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BERTAN BOVO</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 5-17-81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 337
0181

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X		3000	X				1 RoL-	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED	EXPECTED ARRIVAL DATE				
MONTH	DAY	YEAR	MONTH	DAY	YEAR		
<i>Steve E. Nays</i>	<i>Supt. Clerk</i>	5	11	81	5	11	81
Transporter HWT ID No. 129	STATE IN	NUMBER 269	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John T. Trench</i>	DATE RECEIVED MONTH 5	DAY 11	YEAR 81	

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED					
MONTH	DAY	YEAR				
<i>John T. Trench</i>	5	11	81			
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH	DAY	YEAR
				5	11	81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT				DATE DELIVERED MONTH	DAY	YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
for And Disposition of Rejected Materials.

Handling Meth.

1 D 81

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION	TITLE	DATE RECEIVED		
MONTH	DAY	YEAR		
<i>John T. Trench</i>		5	11	81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0181

Please TYPE or PRINT clearly, using
a ballpoint pen - NO PENCIL

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. **7Bage 02872**

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development =	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1 Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	ROL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE Steve Nagy (ER)	TITLE Supt's Clerk	DATE TO BE SHIPPED MONTH DAY YEAR 5-4-81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 5-4-81
TRANSPORTER HWT ID No. 130 IN 2692K	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT James Thomas	DATE RECEIVED MONTH DAY YEAR 5-4-81	

1 PART B

TEAR AT THIS PERFORATION

Tear Delivered

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT James Thomas	DATE DELIVERED MONTH DAY YEAR 5-4-81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT FK	DATE RECEIVED MONTH DAY YEAR 5-4-81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT FK	DATE DELIVERED MONTH DAY YEAR 5-4-81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1 D81

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED
MONTH DAY YEAR
5-7-81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0207

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302

02071

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	202	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)**Tar Decanter Sludge**

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (ER)</i>	TITLE <i>Supr's Clerk</i>	DATE TO BE SHIPPED MONTH 4 DAY 27 YEAR 81	EXPECTED ARRIVAL DATE MONTH 4 DAY 27 YEAR 81
Transporter HWT ID No. 129	STATE IL	NUMBER 2697R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Louch</i>
			DATE RECEIVED MONTH 4 DAY 27 YEAR 81

TEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Louch</i>	DATE DELIVERED MONTH 4 DAY 27 YEAR 81
Transporter No. 2 HWT ID No. 129	DATE RECEIVED MONTH 4 DAY 27 YEAR 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH 4 DAY 27 YEAR 81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Metho

1	D-81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>J Nagy SR</i>	TITLE	DATE RECEIVED MONTH 4 DAY 27 YEAR 81
---	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302

0207

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0181!

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous 1. HAZARDOUS Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RoL.	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Pugs</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 4 20 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 4 20 81
Transporter HWT ID No. 130	STATE IN	NUMBER 269810	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
DATE RECEIVED MONTH DAY YEAR 4 20 81			

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>			DATE DELIVERED MONTH DAY YEAR 4 20 81
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Bob Lott</i>	TITLE <i>Clerk</i>	DATE RECEIVED MONTH DAY YEAR 4 - 20 - 81
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		
DOCUMENT NO. 7302 - 0181		

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 01811

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				ROLT	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Napp</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 4 13 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 4 13 81
Transporter HWT ID No. 189	STATE PA	NUMBER 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Farnish</i>
			DATE RECEIVED MONTH DAY YEAR 4/13/81

1 PART B

YEAR AT THIS PERFORATION

1 2 3 4 5 6 7 8 9 10 11 12

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Farnish</i>	DATE DELIVERED MONTH DAY YEAR 4/13/81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR 4/13/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR 4-13-81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>John Farnish</i>	TITLE <i>owner</i>	DATE RECEIVED MONTH DAY YEAR 4-13-81
--	-----------------------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 01811

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000 X	X					1 RoL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 4 2 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 4 2 81
Transporter HWT ID No. 429	STATE IN	NUMBER 28972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>
			DATE RECEIVED MONTH DAY YEAR 4/2/81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>	DATE DELIVERED MONTH DAY YEAR 4/2/81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	D 31
2	
3	
4	11 10 11

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Bob Foster</i>	TITLE <i>Clerk</i>	DATE RECEIVED MONTH DAY YEAR 4 2 81
--	-----------------------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0181

Please TYPE or PRINT clearly, using a ballpoint pen.— PRESS HARD.

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

7302-01800

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA 9189				X	3000	X					1 RCL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (I.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Yeggs</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 3 25 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3 25 81
Transporter HWT ID No. 129	STATE IN	NUMBER 26472	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John K...k</i>
			DATE RECEIVED MONTH DAY YEAR 3/25/81

TEAR AT THIS PERFORATION
TEAR AT THIS PERFORATION

1 PART B

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John K...k</i>	DATE DELIVERED MONTH DAY YEAR 3/25/81
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.

Handling Methc

1	2-21
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Bob Foster</i>	TITLE <i>Clerk</i>	DATE RECEIVED MONTH DAY YEAR 3 25 81
--	-----------------------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302-0180

Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND04450587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 R.L.	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Dedanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nye</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 3 13 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3 13 81
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Karch</i>	DATE RECEIVED MONTH DAY YEAR 3 13 81		

TEAR AT THIS PERFORATION

1 PART B	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Karch</i>	DATE DELIVERED MONTH DAY YEAR 3 13 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR	
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR	

TO BE FILLED OUT BY TSD FACILITY	Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Meth. 1 D-2 2 3 4 11/14/81
	TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Robert Foster</i>	TITLE <i>Clerk</i>
	DATE RECEIVED MONTH DAY YEAR 3 13 81	
	IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637	

Joseph L. Nye B0609 3-13-81
7302 - 0181
DOCUMENT NO.

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A	NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR	Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1	Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)				
TREATMENT, STORAGE OR DISPOSAL FACILITY	Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-94447858	IND077005946 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 RCL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE	TITLE	DATE TO BE SHIPPED MONTH DAY YEAR	EXPECTED ARRIVAL DATE MONTH DAY YEAR
<i>Steve Nagz</i>	<i>Supt Clerk</i>	2-23-81	2-23-81
TRANSPORTER NO. 2 HWT ID No.	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
29	IN 26332	<i>John Kowal</i>	2/23/81

TEAR AT THIS PERFORATION
TEAR AT THIS PERFORATION

1 PART B	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
	<i>John Kowal</i>	2/23/81
TRANSPORTER NO. 2 HWT ID No.	STATE NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
29	IN 26332	
	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE RECEIVED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methc

	1	D-81
	2	
	3	
	4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION	TITLE	DATE RECEIVED MONTH DAY YEAR
<i>D. P. Craig</i>		FKK 2-23-81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE: PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302

-01812

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 346
7302 - 0181

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 2 10 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2 10 81
Transporter HWT ID No. 129 IN 2633R	STATE IN	NUMBER 2633R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Korsch</i>
			DATE RECEIVED MONTH DAY YEAR 2/10/81

TEAR AT THIS PERFORATION

TO BE FILLED OUT BY TRANSPORTER

1 PART B		
TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Korsch</i>		DATE DELIVERED MONTH DAY YEAR 2/11/81
Transporter HWT ID No. 129 IN 2633R	STATE IN	NUMBER 2633R
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE RECEIVED MONTH DAY YEAR 2/11/81

TO BE FILLED OUT BY TSD FACILITY

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.			Handling Meth 1 D-81 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>P. C. Nagy</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 2 10 81	
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637			

DOCUMENT NO.

7302 - 0181

Please TYPE or PRINT clearly, using
a ballpoint pen — PRESS HARD

HAZARDOUS WASTE MANIFEST

7302 - 01808

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Sup't. oper.</i>	DATE TO BE SHIPPED MONTH DAY YEAR 2 - 5 - 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 2/5/81
Transporter HWT ID No. 29	STATE IN	NUMBER 26332	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>
			DATE RECEIVED MONTH DAY YEAR 2/5/81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR 2/5/81
Transporter No. 2 HWT ID No. 29	DATE RECEIVED MONTH DAY YEAR 2/5/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methd

D.B.I

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED
MONTH DAY YEAR
2-5-81 FK

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

- 01808

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 348
7302 01820

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X		3000	X				1 RoL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 1 26 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 1 26 81
Transporter HWT ID No. 129	STATE IN	NUMBER 2633R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John T. Kunk</i>
			DATE RECEIVED MONTH DAY YEAR 1/26/81

1 PART B

YEAR AT THIS PERFORMANCE

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John T. Kunk</i>	DATE DELIVERED MONTH DAY YEAR 1/26/81
Transporter No. 2 HWT ID No. 129	STATE IN
NUMBER 2633R	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	
DATE DELIVERED MONTH DAY YEAR	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

D-81

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>P. Gary</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 1-26-81
---	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8902 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 01820

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

Page 349

0181

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM0E	NA9189			X		3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 1-19-81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 1-19-81
Transporter HWT ID No. 129 IN 2633R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowak</i>	DATE RECEIVED MONTH DAY YEAR 1/19/81	

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowak</i>	DATE DELIVERED MONTH DAY YEAR 1/19/81
Transporter No. 2 HWT ID No. 129 IN 2633R	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth.

<i>L. Kowak</i>	1	D-81
	2	
	3	
	4	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>L. Kowak</i>	TITLE <i>AK</i>	DATE RECEIVED MONTH DAY YEAR 1-19-81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO.

7302 - 0181

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 0180

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189			X		3000	X				1	ROL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 1 - 8 - 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 1 - 8 - 81
Transporter HWT ID No. 29	STATE IN	NUMBER 2153E	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>
			DATE RECEIVED MONTH DAY YEAR 1/8/81

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>	DATE DELIVERED MONTH DAY YEAR 1/8/81
Transporter HWT ID No. 29	STATE IN
NUMBER 2153E	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
DATE RECEIVED MONTH DAY YEAR	
TRANSPORTER NO. 3 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Methd

1	D. 81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>P. C. Craig</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 1 8 81
---	-------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

25N-1-8-81
DOCUMENT NO. 7302 - 0180

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

DOCUMENT NO.

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos.	12-ORM-E	NA9189				X	3000	X				1	Ro1	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagel</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12-29-80	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12-29-80
TRANSPORTER NO. 1 SIGNATURE <i>John Kouch</i>	STATE IN	NUMBER 2622R	DATE RECEIVED MONTH DAY YEAR 12/29/80

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR 12/21/80
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE RECEIVED MONTH DAY YEAR 12/29/80

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1	
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>F. C. Rung</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 12-29-80
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		DOCUMENT NO. 7302 - 01806

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 01804

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1 Re	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12 22 80	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12 22 80
Transporter HWT ID N 129 IN 26352	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kessel</i>	DATE RECEIVED MONTH DAY YEAR 12/22/80	

1 PART B

TEAR AT THIS LINE ORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kessel</i>	DATE DELIVERED MONTH DAY YEAR 12/22/80
Transporter HWT ID N 129 IN 26352	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kessel</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1 D-8

2

3

4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>D. P. Craig</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 12 22 80
---	-------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302

01804

Please TYPE or PRINT clearly, using
a ballpoint pen.— PRESS HARD

Jones & Laughlin Steel Corporation / an LTV company

HAZARDOUS WASTE MANIFEST

1 PART A

DOCUMENT NO. 7302 - 01805

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1 ROL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and
labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the
State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the ship-
ment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Naps</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12-15-80	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12-15-80
Transporter HWT ID No. 129	STATE IN	NUMBER 26332	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>
			DATE RECEIVED MONTH DAY YEAR 12/15/80

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>			DATE DELIVERED MONTH DAY YEAR 12/15/80
Transporter No. 2 HWT ID No. 129	STATE IN	NUMBER 26332	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE RECEIVED MONTH DAY YEAR 12/15/80
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.			
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>P. C. Gray</i>			TITLE
			DATE RECEIVED MONTH DAY YEAR 12 15 80

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 01805

Please TYPE or PRINT clearly, using
a ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

7302 - 0180

1 PART A

DOCUMENT NO.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1 RLT	K087
2.														
3.														
4.														

Special Handling Instructions including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12-8-80	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12-8-80
TRANSPORTER HWT ID NO. 129 IN 26332	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowal</i>	DATE RECEIVED MONTH DAY YEAR 12/8/80	

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowal</i>	DATE DELIVERED MONTH DAY YEAR 12/8/80
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowal</i>	DATE RECEIVED MONTH DAY YEAR 12/8/80
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth.

1	D-8
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>P. Craig</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 12 8 - 80
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302 - 0180

Please TYPE or PRINT clearly, using
ballpoint pen - PRESS HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 01807

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044260587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X					1	RoL	T K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Hagg</i>	TITLE <i>Supt. Clerk.</i>	DATE TO BE SHIPPED MONTH DAY YEAR 12-1-80	EXPECTED ARRIVAL DATE MONTH DAY YEAR 12-1-80
Transporter HWT ID No. 129	STATE IN	NUMBER 2633R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Korsch</i>
			DATE RECEIVED MONTH DAY YEAR 12/1/80

1 PART B

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Korsch</i>	DATE DELIVERED MONTH DAY YEAR 12/1/80
Transporter HWT ID No. 129	STATE IN
NUMBER 2633R	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	
DATE RECEIVED MONTH DAY YEAR 12/1/80	

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Method

1	D81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>P. Craig</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 12 1 80
--	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE
CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;
OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 01807
F/K 12-1-80

Please TYPE or PRINT clearly, using
a ballpoint pen. — PRESS-HARD

HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302

0180

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 Rd	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nugge</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>11-24-80</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>11-24-80</i>
Transporter HWT ID No. <i>124 IN 26332</i>	STATE <i>IN</i>	NUMBER <i>26332</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowach</i>
			DATE RECEIVED MONTH DAY YEAR <i>11/24/80</i>

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowach</i>	DATE DELIVERED MONTH DAY YEAR <i>11/24/80</i>
Transporter No. 2 HWT ID No. <i>124 IN 26332</i>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
STATE <i>IN</i>	NUMBER <i>26332</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons
For And Disposition of Rejected Materials.

Handling Meth

1	<i>D-8</i>
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>P. Craig</i>	TITLE	DATE RECEIVED MONTH DAY YEAR <i>11 24-80</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8807 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO. 7302

- 0180